

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21004064/T1TF3E2

Date: 15/07/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00026052100
Claimant Vehicle No : SMT7613B **Insured Vehicle No :** SMU520B
Date of Loss: 27/03/2021 Nature of Claim: TP Claim No: SNM21D201786C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMT7613B**
Make & Model: KIA STONIC, 998cc (A) Engine No: G3LCLP056877
Reg. Date: 16/07/2020 (Man. Year: 2020) Chassis No: KNAD6811VL6449427
Colour: Red Odometer: 5704 km
Engine Capacity: 998 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R17 Rear Tyre Size: 205/55 R17
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,814.00	4,410.00	3,404.00	43.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,530.00	8,010.00	7,520.00	48.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	23,344.00	12,420.00	10,924.00	46.80
+ GST 7.00/7.00% (\$\$)	1,634.08	869.40	764.68	46.80
Nett Amount (\$\$)	24,978.08	13,289.40	11,688.68	46.80

INSPECTION

Date of Assignment: 30/03/2021
Date Inspected: 31/03/2021 Inspected At: Cycle & Carriage Fulco Motor Dealer Pte Ltd (HQ)
330 Ubi Road 3
Singapore 408650
Estimated Period of Repair: 11.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$2,682.00 NETT)

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 15 Jul 2021)	
Parts:	N/A	KIA STONIC 998cc (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMT7613B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*C&C LOGO	Necessary	50.00 FS	*50.00 FS
2	1		*ORNAMENT - KIA NO. 1	Necessary	32.00 FS	*32.00 FS
3	1		*GRILLE-RADIATOR	* Check	324.00 FS	*- FS
4	1		*UPR COVER-FR BUMPER	Deformed	476.00 FS	*476.00 FS
5	1		*LWR COVER-FR BUMPER	* Check	367.00 FS	*- FS
6	1		*SKID PLATE-FR BUMPER	* Check	55.00 FS	*- FS
7	1		*MLDG-FR BUMPER A/INT	* Check	61.00 FS	*- FS
8	1		*LWR GRILLE-FR BUMPER	* Check	96.00 FS	*- FS
9	1		*ABSORBER-FRONT BUMPE	* Check	98.00 FS	*- FS
10	1		*BEAM COMPLETE-FR BUM	* Check	544.00 FS	*- FS
11	10		*FR CLIP-BUMPER	Necessary	20.00 FS	*20.00 FS
12	1		*LH BRACKET-FR BUMPER	Not Necessary	13.00 FS	*- FS
13	1		*RH BRACKET-FR BUMPER	Not Necessary	13.00 FS	*- FS
14	1		*PANEL ASSY-TAIL GATE	Bent	1,010.00 FS	*1,010.00 FS
15	1		*GLASS ASSY-TAIL GATE	Necessary	395.00 FS	*395.00 FS
16	12		*PAD-W/SHLD GLASS	Necessary	24.00 FS	*24.00 FS
17	2		*STOPPER-RR WINDOW GL	Necessary	8.00 FS	*8.00 FS
18	2		*PAD-WINDSHIELD	Necessary	34.00 FS	*34.00 FS
19	1		*LOGO ASSY-KIA SUB	Necessary	51.00 FS	*51.00 FS
20	1		*EMBLEM-STONIC	Necessary	26.00 FS	*26.00 FS
21	1		*EMBLEM-TURBO G.D.I	Necessary	38.00 FS	*38.00 FS
22	2		*LAMP ASSY-LICENSE PL	Not Necessary	238.00 FS	*- FS
23	1		*LH SIDE MOULDING ASS	Cracked	152.00 FS	*152.00 FS
24	1		*RH SIDE MOULDING ASS	Not Necessary	152.00 FS	*- FS
25	1		*LWR COVER-RR BUMPER	Deformed	366.00 FS	*366.00 FS
26	1		*LH BRACKET ASSY-RR B	Necessary	27.00 FS	*27.00 FS
27	1		*RH BRACKET ASSY-RR B	Not Necessary	27.00 FS	*- FS
28	1		*SKID PLATE-RR BUMPER	Torn	122.00 FS	*122.00 FS
29	1		*OTR ULTRASONIC SENSO (2PCS)	Not Working (1Pc only)	378.00 FS	*189.00 FS
30	2		*INR ULTRASONIC SENSO	Not Working	378.00 FS	*378.00 FS
31	1		*UNDER SIDE COVER - RR	Deformed	62.00 FS	*62.00 FS
32	1		*LH LAMP ASSY-REAR FO	Cracked	111.00 FS	*111.00 FS
33	1		*RH LAMP ASSY-REAR FO	Not Necessary	111.00 FS	*- FS
34	1		*WIRING HARNESS-BWS E	* Check	245.00 FS	*- FS
35	1		*BEAM-RR BUMPER	Bent	419.00 FS	*419.00 FS
36	1		*LH BRACKET-RR BEAM L	* Check	7.00 FS	*- FS
37	1		*RH BRACKET-RR BEAM L	* Check	5.00 FS	*- FS
38	2		*BRACKET-RR BUMPER UP	* Check	14.00 FS	*- FS
39	1		*ANTENNA ASSY-SMARTKE	* Check	32.00 FS	*- FS
40	1		*LH STAY-RR BUMPER	Cracked	55.00 FS	*55.00 FS
41	1		*RH STAY-RR BUMPER	Not Necessary	55.00 FS	*- FS
42	10		*RR CLIP-BUMPER	Necessary	20.00 FS	*20.00 FS
43	1		*OTR LAMP ASSY-REAR C	* Check	654.00 FS	*- FS
44	1		*PANEL ASSY-BACK	Bent	345.00 FS	*345.00 FS
45	4		*COOLANT	Not Necessary	104.00 FS	*- FS

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DIAGNOSTIC / SCANNING	New	250.00	250.00
2	TO CHECK ALL LIGHTING / WIRING SYSTEM ON FRONT & REAR ACCIDENT AFFECTED AREAS	New	100.00	80.00
3	TO REMOVE & RE-INSTALL RADIATOR & AC CONDENSER TO FACILITATE REPLACEMENT OF FRONT SUPPORT PANEL. TO TOP UP AIRCON GAS & COOLANT (* Check)	New	180.00	0.00
4	TO REPLACE RADIATOR GRILLE, FRONT BUMPER UPR & LWR, BRACKETS, CLIPS, FRONT REINFORCEMENT, FRONT SUPPORT PANEL, ETC - TO REPAIR FRONT BONNET STRAIGHTEN, REFORM, ALIGN ON FRONT ACCIDENT AFFECTED AREAS	New	3,840.00	640.00
5	SPRAY PAINTING ON FRONT ACCIDENT AFFECTED AREAS (FRONT BONNET, FRONT BUMPER)	New	1,650.00	550.00
6	TO TRANSFER TAILGATE COMPONENTS & MECHANISM PARTS	New	640.00	320.00
7	TO REPLACE TAILGATE GLASS	New	300.00	300.00
8	TO INSTALL RIKECOOL SOLAR FILM ON TAILGATE GLASS	New	220.00	220.00
9	TO APPLY SEALANT KIT ON NEW TAILGATE GLASS	New	100.00	100.00
10	TO REMOVE & RE-INSTALL ALL CARPETS / TRIMMING TO FACILITATE REPAIR ON REAR ACCIDENT AFFECTED AREAS	New	640.00	320.00
11	TO REPLACE TAILGATE, REAR BUMPER, EXTN BUMPER, BRACKETS, CLIPS SENSOR, REFLECTOR, REINFORCEMENT, STAY, ETC - TO CUT & WELD REAR END PANEL - TO REPAIR LHR FENDER STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS	New	4,480.00	3,200.00
12	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS (TAILGATE, EXTN BUMPER, LHR FENDER, REAR END PANEL)	New	2,750.00	1,650.00
13	OPC APPLIATION TO BREAK & RESEAL FRONT & REAR LICENSE PLATE	New	280.00	280.00
14	FRONT & REAR LICENSE PLATE WITH CASING	New	100.00	100.00
Gross Labour Cost (\$\$)			15,530.00	8,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >