

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21004067/AQF3N2**Date:** 20/10/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00005792000
Claimant Vehicle No :	SJN9426D	Insured Vehicle No :	SLS8948X
Date of Loss:	27/03/2021	Nature of Claim:	TP
		Claim No:	SNM21D201787/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJN9426D	Engine No:	L15A71801870
Make & Model:	HONDA CITY, 1.5 VTEC (A)	Chassis No:	MRHGM26709P020220
Reg. Date:	04/03/2009 (Man. Year: 2008)	Odometer:	73821 km
Colour:	Silver		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R16	Rear Tyre Size:	185/55 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,274.44	6,749.36	1,525.08	18.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,530.00	4,120.00	1,410.00	25.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	13,804.44	10,869.36	2,935.08	21.26
Approved Total (Overridden) (\$\$)		7,800.00		
(\$\$)	13,804.44	7,800.00	6,004.44	43.50
+ GST 7.00/7.00% (\$\$)	966.31	546.00	420.31	43.50
Nett Amount (\$\$)	14,770.75	8,346.00	6,424.75	43.50

INSPECTION

Date of Assignment:	30/03/2021	
Date Inspected:	30/03/2021 Inspected At:	Twincar Automotive Pte Ltd (Kaki Bukit) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB Singapore 417921
Estimated Period of Repair:	12.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Oct 2021)
Parts:	143	HONDA CITY 1.5 VTEC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJN9426D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*AIRCON CONDENSER	Bent	445.50 FL	*445.50 FL
2	1	*AIRCON CONDENSER DISCHARGE HOSE	Bent	103.20 FL	*103.20 FL
3	1	*AIRCON CONDENSER LIQUID PIPE	Bent	107.95 FL	*107.95 FL
4	1	*AIRCON FAN BLADE	Not Necessary	44.40 FL	*- FL
5	1	*AIRCON FAN COWLING	Cracked	83.50 FL	*83.50 FL
6	1	*AIRCON FAN MOTOR	Damaged	195.00 FL	*195.00 FL
7	1	*AIRCON SUCTION HOSE	Not Necessary	103.85 FL	*- FL
8	1	*ALTERNATOR ASSY	Cracked	677.80 FL	*677.80 FL
9	1	*FRONT BONNET	Distorted	455.62 FL	*455.62 FL
10	2	*FRONT BONNET HINGES L/R	Bent	92.40 FL	*92.40 FL
11	1	*FRONT BONNET LOCK	Damaged	142.40 FL	*142.40 FL
12	1	*FRONT BUMPER	Distorted	505.80 FL	*505.80 FL
13	1	*FRONT BUMPER AIR GUIDE GARNISH	Not Necessary	15.20 FL	*- FL
14	1	*FRONT BUMPER REINFORCEMENT	Distorted	179.50 FL	*179.50 FL
15	1	*FRONT FENDER L/R	O/s Buckled	595.20 FL	*297.60 FL
16	1	*FRONT GRILLE	Cracked	98.10 FL	*98.10 FL
17	1	*FRONT GRILLE H LOGO	Necessary	25.80 FL	*25.80 FL
18	1	*FRONT GRILLE OUTER GARNISH	Cracked	166.85 FL	*166.85 FL
19	2	*FRONT HEADLAMP L/R	N/s Cracked/O/s Smashed	713.00 FL	*713.00 FL
20	1	*FRONT HEADLAMP LOWER BRACKET L/R	O/s Cracked	60.40 FL	*30.20 FL
21	1	*FRONT RH FENDER QUARTER GARNISH	Not Necessary	40.50 FL	*- FL
22	1	*FRONT SUPPORT PANEL	Buckled	371.80 FL	*371.80 FL
23	2	*FRONT WIPER GARNISH COVER L/R	Not Necessary	32.00 FL	*- FL
24	1	*RADIATOR ASSY (A)	Cracked	1,272.60 FL	*1,272.60 FL
25	1	*RADIATOR FAN BLADE	Not Necessary	56.90 FL	*- FL
26	1	*RADIATOR FAN COWLING	Cracked	98.23 FL	*98.23 FL
27	1	*RADIATOR FAN MOTOR	Damaged	321.20 FL	*321.20 FL
28	1	*RADIATOR SPARE TANK	Not Necessary	46.50 FL	*- FL
29	1	*REAR BOOTLID	Repair	407.75 FL	*- FL
30	1	*REAR BOOTLID CITY EMBLEM	Necessary	17.85 FL	*17.85 FL
31	1	*REAR BOOTLID H LOGO	Necessary	19.50 FL	*19.50 FL
32	1	*REAR BOOTLID I-VTEC EMBLEM	Necessary	24.45 FL	*24.45 FL
33	2	*REAR BOOTLID GUIDE RUBBER PROTECTOR L/R	Not Necessary	17.00 FL	*- FL
34	1	*REAR BOOTLID INNER TRIM COVER	Not Necessary	79.80 FL	*- FL
35	1	*REAR BOOTLID MECHANISM LOCK	Not Necessary	62.50 FL	*- FL
36	1	*REAR BOOTLID RUBBER SEAL	Not Necessary	81.85 FL	*- FL
37	1	*REAR BUMPER	Deformed	510.05 FL	*510.05 FL
38	4	*REAR BUMPER SIDE CLIPS L/R	Necessary	32.80 FL	*32.80 FL
39	2	*REAR BUMPER SIDE RETAINER L/R	Necessary	31.60 FL	*31.60 FL
40	1	*REAR END PANEL	Dented	366.90 FL	*366.90 FL
41	1	*REAR END PANEL INNER TOP GARNISH	Deformed	73.30 FL	*73.30 FL
42	1	*REAR SPARE TYRE INNER TOP BOARD COVER	Not Necessary	77.80 FL	*- FL
43	2	*REAR TAILLAMP GASKET SEAL L/R	Necessary	23.80 FL	*23.80 FL
44	2	*REAR TAILLAMP L/R	Cracked	452.40 FL	*452.40 FL
45	1	*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
46	1	*SET FRONT GRILLE CLIPS	Necessary	50.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRONT NUMBER PLATE	Dented	50.00 FS	*30.00 FS
48	1		*FRONT NUMBER PLATE HOLDER	Deformed	50.00 FS	*30.00 FS
49	1		*SET FRONT RH FENDER QUARTER GARNISH CLIPS	Not Necessary	20.00 FS	*- FS
50	1		*FRONT WEEKEND SEAL BRACKET	Necessary	80.00 FS	*20.00 FS
51	1		*SET REAR BOOTLID INNER TRIM COVER CLIPS	Not Necessary	50.00 FS	*- FS
52	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
53	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
54	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	20.00 FS	*10.00 FS
55	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
56	1		*REAR NUMBER PLATE HOLDER	Not Necessary	50.00 FS	*- FS
57	2		*SET REAR TAILLAMP CLIPS L/R	Necessary	40.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,140.55	8,336.70
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,866.11	1,587.34
Total Parts (\$\$)	8,274.44	6,749.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHANGE AIR CON PARTS,VACUUMS,REFILL AIR CON GAS	New	150.00	120.00
2	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING,RESETTING HEADLAMP FOCUSING AND REWIRE FOR PARKING SENSOR	New	80.00	80.00
3	TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY,CUSHION SEAT,TRIM GARNISH,TRIM LINER CARPET (TO FR)	New	100.00	60.00
4	TO RE-SPRAY PAINTING ON THE REAR BOOTLID,REAR END PANEL,REAR FENDER (L/R),SPARE TYRE PANEL AND REAR BUMPER	New	1,300.00	800.00
5	TO RE-SPRAY PAINTING ON THE FRONT BONNET,FRONT SUPPORT PANEL,FRONT FENDER (L/R),FRONT BUMPER AND FRONT DOORS (L/R)	New	1,500.00	1,100.00
6	TO REMOVE AND REINSTALL EXHAUST PIPE	New	80.00	0.00
7	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	2,200.00	1,900.00
8	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	60.00
Gross Labour Cost (\$\$)			5,530.00	4,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >