

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21004100/T1RS3Q2
Date: 05/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800118026	
Claimant Vehicle No :	SHA3917K	Insured Vehicle No :	SGL1208R	
Date of Loss:	29/03/2021	Nature of Claim:	TP	Claim No: 2904368722SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA3917K		
Make & Model:	HYUNDAI AE IONIQ, 1.6 (A)	Engine No:	G4LEKU399667
Reg. Date:	30/10/2019 (Man. Year: 2019)	Chassis No:	KMHC851CVLU187245
Colour:	Blue	Odometer:	127232 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,684.20	1,174.72	509.48	30.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	820.00	630.00	190.00	23.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,504.20	1,804.72	699.48	27.93
+ GST 7.00/7.00% (S\$)	175.29	126.33	48.96	27.93

Nett Amount (S\$)	2,679.49	1,931.05	748.44	27.93
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$129.47/day) (S\$)		388.41		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,471.46		

INSPECTION

Date of Assignment: 30/03/2021

Date Inspected: 30/03/2021

Estimated Period of Repair: 2.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	459.40 FL	*459.40 FL
2	1		*REAR BUMPER CTR MOULDING	Deformed	451.25 FL	*451.25 FL
3	1		*REAR BUMPER REFLECTOR RH	Not Necessary	41.45 FL	*- FL
4	1		*REAR BUMPER BEAM	Not Necessary	394.80 FL	*- FL
5	1		*REAR BUMPER STAY RH	Not Necessary	138.10 FL	*- FL
6	1		*REAR BUMPER FOGLAMP	Cracked	201.50 FL	*201.50 FL
7	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
8	1		*REAR BUMPER MAT	Not Necessary	50.00 FS	*- FS
9	1		*REVERSE SENSOR	Not Working	180.00 FS	*180.00 FS
10	1		*REAR NO.PLATE W/TRIM CVR	Cracked	55.00 FS	*55.00 FS
11	1		*SMARTKEY ANTENNA	Cracked	40.50 FL	*40.50 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,034.00	1,409.65
- List Item Discount on L Items 20.00/20.00% (\$)	349.80	234.93
Total Parts (\$)	1,684.20	1,174.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	350.00
2	SPRAYPAINT CHARGE	New	300.00	250.00
3	R/I REVERSE SENSOR	New	120.00	30.00
Gross Labour Cost (\$\$)			820.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >