24 Penshurst Place, Singapore 556440 Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783 Reg No: 201000228E

INVOICE

Invoice No.:

CL/210250

Roset Limousine Services Pte Ltd

C/o: Teamwork Garage Pte Ltd

Ref No.:

TWG/04/2103/TP

53 Ubi Avenue 1

#01-24 Paya Ubi Industrial Park, Singapore 408934

Date:

3 May 2021

DESCRIPTION

AMOUNT

OUR SERVICE FEE CHARGES:

SURVEY INSPECTION FOR VEHICLE NO.

SLF 2970 M

- RESURVEY INSPECTION
- DIGITAL PHOTOGRAPHS SERVICES
 (INCLUSIVE OF STORAGE AND SUBMISSION OF DIGITAL PHOTOGRAPHS)
- TRANSPORTATION

GRAND TOTAL

S\$ 552.00

E & O. E

All cheque payment should be "Crossed" and made payable to "CLAPPRAISER PTE LTD"

We shall be grateful if you could forward our payment at your early convenience.



24 Penshurst Place, Singapore 556440 Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783 Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Roset Limousine Services Pte Ltd

Date

: 3 May 2021

C/o: Teamwork Garage Pte Ltd

Our ref

: TWG/04/2103/TP

53 Ubi Avenue 1

#01-24 Paya Ubi Industrial Park, Singapore 408934

Accident Date

: 27 March 2021

Type of Survey: Third Party

Inspection Date

: 26 April 2021

Repairer Name

: Teamwork Garage Pte Ltd

53 Ubi Avenue 1

#01-24 Paya Ubi Industrial Park, Singapore 408934

PARTICULARS OF VEHICLE

Registration No

: SLF 2970 M

Year / Capacity:

2016 / 1798 cc

Make / Model

: Toyota Wish

Colour

Blue

Chassis No

: JTDGG20WX0J004884

Mileage

297430

Engine No

: 2ZR1821578

CONDITION OF TYRES

		Make	Size	Thread Balance	Rim
Front Nearside	:	Giti	195/65 R15	5 mm	Sport
Front Offside	:	Giti	195/65 R15	5 mm	Sport
Rear Nearside	:	Giti	195/65 R15	5 mm	Sport
Rear Offside	:	Giti	195/65 R15	5 mm	Sport

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the rear portion. (Details refer to the photographs attached)

Enclosed number of photographs:

52

copies

REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not given authorization and instruction to the repairer to proceed with the repair.

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a Lump Sum of \$5,600.00 on a contractual basis.

Under normal circumstances, the repair period would be about 6 (Six) working days.

Page 1



Vehicle Registration No.: SLF 2970 M

Our Ref No.:

TWG/04/2103/TP

Qty	Description	Conditions	Repairer's Estimate		Revised Amount
	SPARE PARTS - LIST ITEMS				70
1	Rear windscreen glass moulding X SVC	Necessary	\$ 297.54	\$	297.54
1	Rear tailgate X Repair	Damage	\$ 1,466.25	\$	1,466.25
2	Rear tailgate dampers SVC	Intact	\$ 444.20		
1	Rear tailgate inner trim board X SVC	Damage	\$ 485.51	\$	485.51
1	Rear tailgate inner lock X SVC	Damage	\$ 497.37	\$	497.37
1	Rear tailgate weatherstrip 🗸	Necessary	\$ 370.50	\$	370.50 320
1	Rear tailgate "VALVE MATIC" emblem /	Necessary	\$ 89.80	\$	89.80 65
2	Rear taillamps SVC	Intact	\$ 881.00		
1	Rear end panel	Damage	\$ 900.20	\$	900.20 540.8
1	Rear end panel inner garnish 🗸	Damage	\$ 296.50	\$	296.50 285
1	Rear keyless sensor 🗸	Damage	\$ 477.30	\$	477.30 138.5
1	Rear bumper	Damage	\$ 841.65	\$	841.65 492
2	Rear bumper reflectors X SVC	Damage	\$ 179.60	\$	179.60
2	Rear bumper side retainers X SVC	Necessary	\$ 128.86	\$	128.86
2	Rear bumper PDC sensors 🗸	Damage	\$ 467.60	\$	467.60 200(SN
	•		\$ 7,823.88	\$	6,498.68 1841.3
		Less 25%	\$ 1,955.97	\$	1,624.67
	Total Cost - List Items		\$ 5,867.91	\$	4,874.011380.9
	SPECIAL NETT ITEMS				
1	Rear windscreen sealant X SVC	Necessary	\$ 80.00	\$	50.00
1	Rear "PRIVATE HIRE" sticker X SVC	Necessary	\$ 45.00	\$	45.00
1	Rear bumper clip (1 set) \checkmark	Necessary	\$ 60.00	\$	60.00 30
	Total Cost - Special Nett items		\$ 185.00	\$	155.00

Total cost of parts

\$ 6,052.91	\$ 5,029.01



Vehicle Registration No.: SLF 2970 M

Our Ref No.:

TWG/04/2103/TP

S/No	Description	Repairer's Estimate		Revised Amount
	Total cost of parts c/f	\$ 6,052.91	\$	5,029.01
	<u>LABOUR</u>			
1	To remove, refit, replaced damaged lamps and check up rear electrical wiring	\$ 80.00	S	50.00 30
2	To remove and refit inner garnishes, inner trim to assist repair.	\$ 150.00	\$	120.00 60
3	To remove and refit rear reverse sensor.	\$ 120.00	\$	80.00 40
4	To transfer rear tailgate mechanism and wiring assembly to assist repair.	\$ 80.00	\$	80.00 X N
5	To remove and refit rear windscreen glass.	\$ 180.00	\$	120.00X N
6	To apply undercoating on repaired and replaced panel.	\$ 150.00	\$	90.00 60
7	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld; re-align body structure and damaged consistent to the accident.	\$ 1,080.00	\$	750.00 600
8	To respray painting include polishing and waxing on the changed body parts, repaired portions where	\$ 1,000.00	\$	660.00 600
	consistent to the accident.			1390
	GRAND TOTAL	\$ 8,892.91	\$	6,979.01

2800.98

-20%: 2200

5 Days



Vehicle Registration No.: SLF 2970 M

Our Ref No .:

TWG/04/2103/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of: \$ 5,600.00

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notifed the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD

Cheong KVH

Automotive Appraiser

















































































