

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21004123/AQCE2

**Date:** 03/08/2021

### REFERENCE

Insured/Claimant:	NG RUI ZHI	Policy No:	1900114746		
Date of Loss:	17/03/2021	Nature of Claim:	OD	Claim No:	4989700741SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM4965S		
Make & Model:	AUDI A4, 2.0 TFSI S-TRONIC (A)	Engine No:	CVK079993
Reg. Date:	28/06/2019 (Man. Year: 2019)	Chassis No:	WAUZZZF41KN011524
Colour:	White	Odometer:	10379 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$130,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

### CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre tread depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,362.00	7,958.80	6,403.20	44.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,852.00	1,852.00	1,000.00	35.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>17,214.00</b>	<b>9,810.80</b>	<b>7,403.20</b>	<b>43.01</b>
<b>- Excess (S\$)</b>	<b>1,600.00</b>	<b>1,600.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>15,614.00</b>	<b>8,210.80</b>	<b>7,403.20</b>	<b>47.41</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,092.98</b>	<b>574.76</b>	<b>518.22</b>	<b>47.41</b>
<b>Nett Amount (S\$)</b>	<b>16,706.98</b>	<b>8,785.56</b>	<b>7,921.42</b>	<b>47.41</b>

### INSPECTION

Date of Assignment:	31/03/2021		
Date Inspected:	30/03/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

**Adjuster:** ADRIAN LING

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,787.00 FS	*1,429.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	587.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	71.00 FS	*- FS
4	1		*FRONT BUMPER LOWER GRILLE - CENTER	Not Necessary	196.00 FS	*- FS
5	1		*FRONT BUMPER LOWER CLOSING ELEMENT - CENTER	Cracked	210.00 FS	*167.60 FS
6	1		*FRONT BUMPER AIR GUIDE - LH	Not Necessary	63.00 FS	*- FS
7	1		*FRONT RADIATOR GRILLE	Not Necessary	1,332.00 FS	*- FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Cut	135.00 FS	*108.00 FS
9	1		*FRONT BUMPER CARRIER	Not Necessary	845.00 FS	*- FS
10	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	124.00 FS	*99.20 FS
11	1		*FRONT BUMPER REINFORCEMENT COVER	Not Necessary	127.00 FS	*- FS
12	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	36.00 FS	*- FS
13	1		*CAUTION STICKER	Not Necessary	14.00 FS	*- FS
14	1		*AIR CONDITIONER STICKER	Not Necessary	8.00 FS	*- FS
15	2		*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	58.00 FS	*- FS
16	1		*FRONT PARKING AID SENSOR	Not Necessary	244.00 FS	*- FS
17	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
18	1		*FRONT HIGH TONE HORN - LH	Not Necessary	126.00 FS	*- FS
19	1		*FRONT HIGH TONE HORN SPRING SHACKLE - LH	Not Necessary	29.00 FS	*- FS
20	1		*HEADLIGHT - LH	Cut	7,693.00 FS	*6,154.40 FS
21	1		*HEADLIGHT LIFT CYLINDER - LH	Not Necessary	210.00 FS	*- FS
22	1		*FRONT RADIATOR OUTER AIR DUCT - LH	Not Necessary	28.00 FS	*- FS
23	1		*FRONT RADIATOR INNER AIR DUCT - LH	Not Necessary	12.00 FS	*- FS
24	1		*FRONT RADIATOR UPPER AIR DUCT - LH	Not Necessary	16.00 FS	*- FS
25	1		*FRONT NUMBER PLATE	Not Necessary	60.00 FS	*- FS
26	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS
27	1		*FRONT BUMPER LOCK CARRIER BRACKET	Not Necessary	137.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 14,362.00 7,958.80

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	360.00	360.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTSS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
4	TO RESPRAY FRONT BUMPER	New	900.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,852.00</b>	<b>1,852.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >