



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|--|-----------------|----------------------------|--|
| TAN KOK QUAN PARTNERSHIP 1 WALLICH STREET #07-02 GUOCO TOWERSINGAPORE 078881 | | | Ref: CS/LAW21004129/Dqf3e2 | |
| | | | Date: 21/04/2021 | |
| | | | Code: L021 | |
| 1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION) | | | | |
| Insured Veh. | SGM 6288X | Veh. Inspected | SJR 3576X | |
| Policy No. | MC/MC 344/2020 | Coverage (\$) | 0.00 | |
| Claim No. | CF.MKC.so.0089.20-aig | Excess (\$) | 0.00 | |
| Assign From | CASSANDRA KANG (LAWRENCE CHUA PRACTICE LLC) | Assign Date | 24/03/2021 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | HONDA STREAM | c.c | 1799 | |
| Engine No. | HIDDEN | Year of Reg. | 2009 | |
| Chassis No. | RN61083250 | Colour | BLACK | |
| Odometer | 308759 KM | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | SPORTS RIM | |
| General | GOOD | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 215/55 R17 | GOODRICH | 5 mm | |
| L/H Front Tyre | 215/55 R17 | GOODRICH | 5 mm | |
| R/H Rear Tyre | 215/55 R17 | GOODRICH | 5 mm | |
| L/H Rear Tyre | 215/55 R17 | GOODRICH | 5 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 14/07/2018 | Inspection Date | 08/04/2021 | |
| Survey held at | EM SOLUTION PTE LTD 160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | | 6 Working Days | |