

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21004130/UPS3Q2
Date: 15/09/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100493936
Claimant Vehicle No :	EQ26C	Insured Vehicle No :	SJJ1314S
Date of Loss:	30/03/2021	Nature of Claim:	TP
		Claim No:	0272484157SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	EQ26C		
Make & Model:	HONDA VEZEL, 1.5 HYBRID X (A)	Engine No:	LEB5066155
Reg. Date:	22/02/2016 (Man. Year: 2015)	Chassis No:	RU31116137
Colour:	Black	Odometer:	84715 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,992.90	347.44	3,645.46	91.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,260.00	1,610.00	650.00	28.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,252.90	1,957.44	4,295.46	68.70
Approved Total (Overridden) (S\$)		1,550.00		

(S\$)	6,252.90	1,550.00	4,702.90	75.21
+ GST 7.00/7.00% (S\$)	437.70	108.50	329.20	75.21
Nett Amount (S\$)	6,690.60	1,658.50	5,032.10	75.21
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,840.50		
Global Sum Settlement (S\$)		1,800.00		

INSPECTION

Date of Assignment: 31/03/2021

Date Inspected: 31/03/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Fastech Auto Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
 Singapore 417883

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	788.20 F	*- FL
2	1		*REAR BUMPER SIDE RH	Deformed	295.00 F	*185.20 FL
3	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
4	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	62.50 F	*- FL
5	1		*REAR FENDER RH	Repair	981.00 F	*- FL
6	1		*REAR FENDER OUTER PROTECTOR RH	Torn	366.20 F	*199.10 FL
7	1		*REAR SPORT RIM RH	Repair	1,000.00 F	*- FL
8	1		*REAR WHEEL HUB BEARING RH	Not Necessary	450.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	3,992.90	434.30
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	86.86
Total Parts (S\$)	3,992.90	347.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REFIX REAR REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
4	TO CONDUCT WHEEL ALIGNMENT	New	100.00	60.00
5	TO DISMANTLE & REFIX REAR UNDER CARRIAGE	New	150.00	0.00
6	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	680.00	600.00
7	TO PUTTY & SPRAY PAINTING	New	1,080.00	800.00
Gross Labour Cost (S\$)			2,260.00	1,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >