

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21004134/T1QF3Q2
Date: 16/07/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0100555339
Claimant Vehicle No :	SMR2836T	Insured Vehicle No :	SCY21Y
Date of Loss:	27/03/2021	Nature of Claim:	TP
		Claim No:	5416304163SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR2836T		
Make & Model:	HONDA FIT, 1.3 (A)	Engine No:	L13B3940070
Reg. Date:	27/12/2019 (Man. Year: 2019)	Chassis No:	GK33425580
Colour:	Grey	Odometer:	61552 km
Engine Capacity:	1317 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

7/16/2021

Adjuster Report

Date of Assignment: 29/03/2021

Date Inspected: 31/03/2021 Inspected At:

Benefit Auto Care Pte Ltd (HQ)
11 KAKI BUKIT ROAD 1 #01-02 EUNOS TECHNOLINK
Singapore 415939

Estimated Period of Repair: 9.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

7/16/2021

Adjuster Report

MARKET VALUE:\$68,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Cut	0.00 F	*- F
2	1		*REAR NUMBER PLATE BASE	Cracked	0.00 F	*- F
3	1		*REAR BUMPER	Deformed	0.00 F	*- F
4	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
5	2		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
6	2		*REAR BUMPER LIGHT	Cracked	0.00 F	*- F
7	1		*REAR BUMPER LOWER SPOILER	Deformed	0.00 F	*- F
8	1		*REVERSE SENSOR	Not Working	0.00 F	*- F
9	1		*REAR END PANEL	Bent	0.00 F	*- F
10	1		*REAR END PANEL TOP GARNISH	Deformed	0.00 F	*- F
11	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
12	1		*REAR LH TAILLAMP PANEL	Bent	0.00 F	*- F
13	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
14	1		*REAR RH TAILLAMP PANEL	Bent	0.00 F	*- F
15	1		*TAILGATE	Bent	0.00 F	*- F
16	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
17	1		*TAILGATE OUTER HANDLE	Necessary	0.00 F	*- F
18	1		*TAILGATE INNER HANDLE	Deformed	0.00 F	*- F
19	1		*TAILGATE GARNISH	Deformed	0.00 F	*- F
20	2		*TAILGATE REFLECTOR	Cracked	0.00 F	*- F
21	1		*TAILGATE WIPER MOTOR	*Check	0.00 F	*- F
22	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
23	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
24	1		*TAILGATE LOCK	Bent	0.00 F	*- F
25	1		*TAILGATE RUBBER	Cut	0.00 F	*- F
26	1		*TAILGATE HINGE	Repair	0.00 F	*- F
27	1		*TAILGATE DAMPER	*Check	0.00 F	*- F
28	1		*TAILGATE INNER BOARD	Deformed	0.00 F	*- F
29	1		*SPARE TYRE BOARD	Deformed	0.00 F	*- F
30	1		*SPARE TYRE PANEL	Buckled	0.00 F	*- F
31	1		*SPARE TYRE TOOL SPONGE COMPARTMENT	Deformed	0.00 F	*- F
32	1		*REAR EXHAUST PIPE	Bent	0.00 F	*- F
33	1		*REAR EXHAUST MOUNTING	Deformed	0.00 F	*- F
34	1		*REAR EXHAUST HEAT SHIELD	Bent	0.00 F	*- F
35	1		*REAR LH FENDER	Repair	0.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR LH FENDER INNER TRIM	Deformed	0.00 F	* - F
37	1		*REAR RH FENDER	Repair	0.00 F	* - F
38	1		*REAR RH FENDER INNER TRIM	Deformed	0.00 F	* - F
F=Franchise part.						
					Total Parts (S\$)	0.00
						0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >