



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGP 1949P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	A/C GAS (SN)	NOT NECESSARY	60.00	-
1	COVER FOR FRT BUMPER (SN)	CRUSHED	1,371.14	1,371.14
1	SUPPORT PA BUMPER INNER BRACKET LH (SN)	NOT NECESSARY	43.78	-
1	SUPPORT PA BUMPER INNER BRACKET RH (SN)	NOT NECESSARY	43.78	-
1	GUIDE PIEC BUMPER SIDE BRACKET RH (SN)	BENT	34.59	34.59
1	END PLATE BUMPER LOWER CLOSING ELEMENT (SN)	NOT NECESSARY	137.13	-
1	SENSOR BRACKET (SN)	NECESSARY	12.93	12.93
1	SENSOR BRACKET (SN)	NECESSARY	12.93	12.93
1	SENSOR BRACKET (SN)	NECESSARY	12.93	12.93
1	SENSOR BRACKET (SN)	NECESSARY	12.93	12.93
1	BONDING AGENT FOR PLASTIC (SN)	NECESSARY	62.81	62.81
1	2K-PLASTIC ADHESIVE (SN)	NECESSARY	78.91	78.91
1	COVER NOZZLE COVER RH (SN)	NOT NECESSARY	18.88	-
1	PRESSURE C NOZZLE CYLINDER RH (SN)	BROKEN	82.77	82.77
1	UNBEKANNT RADIATOR GRILLE (SN)	NOT NECESSARY	232.85	-
1	COVER STRI RADIATOR GRILLE CHROM (SN)	NOT NECESSARY	248.94	-
1	STICKER 'AC' REFRIGERAN (SN)	NOT NECESSARY	16.84	-
1	KENNSCHILD "BEI OLUBERFUL" (SN)	NOT NECESSARY	14.54	-
1	STICKER 'OIL COMPLY WITH (SN)	NOT NECESSARY	23.84	-
1	COOLING AI CTR LOWER GRILLE (SN)	CUT	92.93	92.93
1	COVER FOR FOG LAMP GRILLE RH (SN)	CUT	48.36	48.36
1	UNBEKANNT RHS LED LAMP (SN)	CUT	2,189.08	2,189.08
1	HALOGEN FO RHS FOG LAMP (SN)	BROKEN	263.62	263.62
1	BUFFER BUMPER FOAM (SN)	BROKEN	49.49	49.49
1	FRONT PANE LOCK CARRIER (SN)	NOT NECESSARY	679.92	-
2	COOLANT (SN)	NOT NECESSARY	41.76	-
1	OIL FOR REFRIGERANT COMPR A/C OIL (SN)	NOT NECESSARY	36.70	-
1	RHS FENDER (SN)	TO REPAIR SEE LABOUR	616.26	-
2	RIVETTED CAP NUT (SN)	NECESSARY	4.46	4.46

Report Ref No. CS/UOI21004142/Evf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FENDER - B FENDER BRACKET RH (SN)	NOT NECESSARY	98.92	-
			6,644.02	4,329.88
	LABOUR			
	CHECK SHORT CIRCUIT / HARNESS REPAIR.		280.00	280.00
	DIAGNOSTIC AND PROGRAMMING.		480.00	480.00
	LEAKED CHECK, VACUUM & REGAS.	NOT NECESSARY	840.00	-
	TO ALIGN LED HEADLIGHT.		100.00	100.00
	WHEEL ALIGNMENT.		360.00	360.00
	R&R RIM BALANCE.		50.00	50.00
	LABOUR. INCLUSIVE OF THE REPAIR OF RHS FENDER.		5,040.00	1,680.00
	SPRAY PAINT.		3,200.00	1,600.00
			10,350.00	4,550.00
GRAND TOTAL			16,994.02	8,879.88
RECOMMENDED COST OF REPAIRS				8,879.88

Report Ref No. CS/UOI21004142/Evf3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.