

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# : XD8371X

Accident Date : 15/3/2021

Location : AYE TOWARDS TUAS BEFORE JURONG PORT ROAD EXIT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Model: SHACMAN SX4187JU361R

Date: (17/12/2013)

3P: XD4437S (ERGO)

S/Nos	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front bumper (Fiberglass) <i>Distal</i>	4686.50	✓	
2	10 pcs	Front bumper clips <i>Neu</i>		80.00	X
3	1 pc	Front bumper bracket <i> Bent</i>	945.60	✓	
4	1 pc	Front enforcement <i>Dented</i>	945.00	✓	
5	1 pc	Front enforcement (top) <i>Bent</i>	450.00	✓	
6	1 pc	Front grille (Fiberglass) <i>Cracked</i>	1450.60	✓	
7	10 pcs	Front grille clips <i>Neu</i>		30.00	✓
8	3pcs	Front grille garnish <i>2 piece dented</i>	545.60	450	
9	16pcs	Front grille garnish clips <i>Neu</i>		80.00	30
10	1 pc	Front grille 'SHACMAN' logo	120.50	✓	
11	1 pc	Front grille 'SHACMAN' emblem <i>3 tra</i>	110.40	✓	
12	1 pc	Front o/s & n/s head-lamp <i>2 B N/s cracked</i>	1450.60	725.30	
13	1 pc	Front o/s & n/s head-lamp garnish <i>N/s cracked</i>	320.00	✓	
14	2pcs	Front o/s & n/s fog lamp <i>N/s cracked</i>	860.60	430.30	
15	2pcs	Front o/s & n/s signal lamp <i>N/s cracked</i>	420.60	210.30	
16	2pcs	Front o/s & n/s side panel (fiberglass) <i>cracked</i>	1450.60	800	
17	12pcs	Front o/s & n/s side panel (fiberglass) clips <i>Neu</i>		60.00	✓
18	1 pc	Front n/s grille catch <i>Dented</i>	200.00	✓	
19	1 pc	Air con dryer <i>Dented</i>	450.60	✓	
20	1 pc	Front n/s lock assembly <i>Neu</i>	345.80	X	
21	1 pc	Front n/s wiring cover <i>cracked</i>	84.50	✓	
22	1 pc	Front cabin mounting <i>Neu</i>	500.00	X	
23	1 pc	Front reg. no. plate <i>Dented</i>		45.00	25
Sub-Total:			15,336.90	295.00	0.00
			5%	0%	10%
After Less %:			14,570.06	295.00	0.00
Labour					
1		To dismantle damaged parts, straighten and welding.	1,800.00	1400	
2		To spray painting.	1,200.00	1100	
3		To check wiring.	140.00	50	
4		To remove and refit front cabin mounting	400.00	X	
Sub-Total:			3,540.00		
Total:			18,405.06		
After Less 20%:			14,724.04		

2980
595

1250

780

2550.

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)

hist 10131.90 10201.90

un 10% 9187.71 9181.71

S-N: 205 145

Labour: 2550

hist 10131.90 11876.71

Admin Lj
2/5 28/04/21

05 Days.

