

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21004147/T1QF3N2**Date:** 25/08/2021REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNA00005782000
Claimant Vehicle No : GBK9197A **Insured Vehicle No :** SLM9408M
 Date of Loss: 19/03/2021 Nature of Claim: TP Claim No: SNM21D201599/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBK9197A**
 Make & Model: TOYOTA DYNA 150, 3.0 D 5MT (M) Engine No: 1KDB068812
 Reg. Date: 22/01/2021 (Man. Year: 2020) Chassis No: JTFAT35Y80K216265
 Colour: Grey Odometer: 4915 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/75 R15 Rear Tyre Size: 155/R12 (D)
 Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 7/7 mm
 Front Right Side: Bridgestone 7 mm Rear Right Side: Bridgestone 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,179.35	5,557.77	17,621.58	76.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,800.00	2,110.00	4,690.00	68.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,979.35	7,667.77	22,311.58	74.42
Approved Total (Overridden) (S\$)		6,100.00		
(S\$)	29,979.35	6,100.00	23,879.35	79.65
+ GST 7.00/7.00% (S\$)	2,098.55	427.00	1,671.55	79.65
Nett Amount (S\$)	32,077.90	6,527.00	25,550.90	79.65

INSPECTION

Date of Assignment: 31/03/2021
 Date Inspected: 31/03/2021 Inspected At: RICO 60 AUTO SERVICES PTE LTD (HQ)
 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT
 Singapore 415875
 Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source:	(Last Synchronised: 25 Aug 2021)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK9197A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Repair	1,794.20 FL	*- FL
2	1		*FRONT DOOR OUTER MOULDING RH	Not Necessary	159.80 FL	*- FL
3	1		*FRONT DOOR OUTER HANDLE RH	Not Necessary	277.50 FL	*- FL
4	2		*FRONT DOOR HINGE RH	Not Necessary	240.00 FL	*- FL
5	1		*FRONT DOOR CHECKER RH	Not Necessary	136.50 FL	*- FL
6	1		*FRONT DOOR INNER LOCK RH	Not Necessary	396.40 FL	*- FL
7	1		*FRONT DOOR LOCK CATCH RH	Not Necessary	46.00 FL	*- FL
8	1		*FRONT DOOR WEATHERSTRIP RH	Not Necessary	198.00 FL	*- FL
9	1		*FRONT DOOR REGULATOR MOTOR RH	Not Necessary	475.90 FL	*- FL
10	1		*FRONT DOOR REGULATOR GEAR RH	Not Necessary	321.00 FL	*- FL
11	1		*FRONT DOOR FRAME WEATHERSTRIP RH	Not Necessary	254.00 FL	*- FL
12	1		*FRONT DOOR SIDE RUBBER RH	Not Necessary	100.00 FL	*- FL
13	1		*FRONT DOOR BOTTOM RUBBER RH	Torn	100.00 FL	*100.00 FL
14	1		*FRONT DOOR LOWER STEP GARNISH RH	Cut	498.70 FL	*241.40 FL
15	1		*CABIN REAR PILLAR RH	Repair	693.50 FL	*- FL
16	1		*CABIN REAR PILLAR EMBLEM (D4D)	Necessary	96.80 FL	*96.80 FL
17	1		*FRONT MUDGUARD RH	Cut	374.20 FL	*225.00 FL
18	1		*FRONT ABSORBER RH	Not Necessary	207.70 FL	*- FL
19	1		*FRONT ABSORBER TOP MOUNTING RH	Not Necessary	90.00 FL	*- FL
20	1		*FRONT UPPER ARM RH	Not Necessary	1,720.50 FL	*- FL
21	1		*FRONT LOWER ARM RH	Not Necessary	1,029.60 FL	*- FL
22	1		*FRONT KNUCKLE ARM RH	Bent	518.70 FL	*421.00 FL
23	1		*FRONT WHEEL BEARING RH	Bent	128.70 FL	*128.70 FL
24	1		*AIR CLEANER BOX ASSY	Cracked	876.40 FL	*494.70 FL
25	1		*RADIATOR SPARE TANK	Cut	224.50 FL	*140.90 FL
26	1		*SIDE GATE RH	Bent	1,898.60 FL	*1,325.40 FL
27	1		*SIDE GATE FRONT HANDLE LOCK RH	Not Necessary	216.00 FL	*- FL
28	1		*SIDE GATE FRONT HANDLE LOCK BRACKET RH	Not Necessary	225.30 FL	*- FL
29	1		*SIDE GATE HINGE RH (6 Pcs)	Bent (3 Pcs only)	540.00 FL	*150.00 FL
30	1		*SIDE GATE BOTTOM PANEL RH	Bent	752.40 FL	*454.70 FL
31	1		*SIDE GATE BOTTOM STEP PANEL RH	Bent	244.30 FL	*155.00 FL
32	1		*TAIL GATE LOWER SIDE RAILING RH	Bent	246.00 FL	*246.00 FL
33	1		*TAIL GATE LOWER SIDE RAILING STOPPER RH	Cut	38.50 FL	*38.50 FL
34	2		*REAR MUDGUARD RH	Bent	744.80 FL	*225.00 FL
35	1		*REAR MUDGUARD BRACKET RH (4 Pcs)	Bent (2 Pcs only)	280.00 FL	*100.00 FL
36	1		*TAIL LAMP RH	Not Necessary	354.00 FL	*- FL
37	1		*TAIL LAMP BRACKET RH	Not Necessary	172.40 FL	*- FL
38	1		*DIESEL TANK	Bent	1,278.90 FL	*745.00 FL
39	2		*DIESEL TANK BELT	Cut	467.00 FL	*320.00 FL
40	1		*DIESEL TANK BELT BRACKET (2 Pcs)	Bent (1 Pc only)	834.00 FL	*255.60 FL
41	1		*REAR ABSORBER RH	Not Necessary	580.00 FL	*- FL
42	1		*REAR WHEEL BEARING RH	Not Necessary	790.00 FL	*- FL
43	1		*REAR AXLE BEAM	Not Necessary	2,245.00 FL	*- FL
44	1		*FRONT DOOR COMPANY STICKER	Necessary	300.00 FS	*150.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*FRONT DOOR COMPANY LETTERING	Necessary	60.00 FS	*40.00 FS
46	1		*CABIN REAR PILLAR SEALANT	Not Necessary	80.00 FS	*- FS
47	1		*RADIATOR COOLANT	Necessary	60.00 FS	*40.00 FS
48	1		*FRONT MUDGUARD CLIP	Necessary	50.00 FS	*10.00 FS
49	1		*FRONT MUDGUARD RH	Not Necessary	200.00 FS	*- FS
50	1		*REAR MUDGUARD CLIP	Not Necessary	50.00 FS	*- FS
51	2		*REAR MUDGUARD MUDFLAP	Not Necessary	80.00 FS	*- FS
52	1		*FRONT RIM RH	Dented	450.00 FS	*250.00 FS
53	1		*FRONT TYRE RH	Not Necessary	350.00 FS	*- FS
54	1		*REAR TYRE RH (2 Pcs)	Cut (1 Pc only)	600.00 FS	*120.00 FS
55	1		*REAR RIM RH (2 Pcs)	Cut (1 Pc only)	700.00 FS	*150.00 FS
56	1		*SIDE GATE COMPANY STICKER	Necessary	600.00 FS	*300.00 FS
57	1		*SIDE GATE TOP RAILING BAR	Not Necessary	1,500.00 FS	*- FS
58	1		*SIDE GATE INNER ALUMINIUM PLATE	Not Necessary	800.00 FS	*- FS
59	1		*RIVET	Necessary	150.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	28,895.80	7,023.70
- List Item Discount on L Items 25.00/25.00% (\$)	5,716.45	1,465.93
Total Parts (\$)	23,179.35	5,557.77

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,REMOVAL AND REPLACING PARTS	New	1,600.00	900.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,800.00	900.00
3	TO SPRAY TUFF COAT	New	600.00	30.00
4	WIRING,BULB CHECKING	New	600.00	0.00
5	REMOVE AND REFIX UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	400.00	0.00
6	REMOVE & REINSTALL FRONT DOOR MECHANISM PART	New	200.00	0.00
7	REMOVE & REINSTALL REAR DIESEL TANK	New	200.00	100.00
8	REMOVE AND INSTALL REAR UNDER CARRIAGE	New	600.00	0.00
9	REMOVE AND INSTALL FRONT UNDER CARRIAGE	New	600.00	100.00
10	TO CHECK FOUR WHEEL ALIGHMENT	New	200.00	80.00
Gross Labour Cost (\$)			6,800.00	2,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >