

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC4/AIG21004151/BPA3Q2

Date:

15/07/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Claimant Vehicle No : SJR3149Y

Date of Loss: 29/03/2021

Policy No:

2070161516

Insured Vehicle No :

SMW3526E

Nature of Claim:

TP

Claim No:

3012746683SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJR3149Y**

Make & Model: TOYOTA WISH, 1.8 X (A)

Reg. Date: 18/06/2009 (Man. Year: 2009)

Colour: Grey

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 2ZR0419044

Chassis No: ZGE200003838

Odometer: 314827 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Front Left Side: Touring 5 mm

Front Right Side: Touring 5 mm

Rear Tyre Size: 195/65 R15

Rear Left Side: Giti 5 mm

Rear Right Side: Giti 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,049.97	4,759.24	7,290.73	60.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,680.00	2,200.00	2,480.00	52.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,729.97	6,959.24	9,770.73	58.40
Approved Total (Overridden) (S\$)		5,550.00		

(S\$)	16,729.97	5,550.00	11,179.97	66.83
+ GST 7.00/7.00% (S\$)	1,171.10	388.50	782.60	66.83
Nett Amount (S\$)	17,901.07	5,938.50	11,962.57	66.83
+ Car Rental (8.0 x S\$120.00/day) (S\$)		960.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		6,934.95		
Global Sum Settlement (S\$)		6,930.00		

INSPECTION

Date of Assignment: 31/03/2021

Date Inspected: 31/03/2021

Estimated Period of Repair: 8.0 days

Inspected At:

160 SIN MING DRIVE #01-14

Repairer: Team Autopro Pte Ltd - Sin Ming (HQ)

Adjuster: Lim Teow Guan**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,840.20 FL	*1,272.00 FL
2	1		*TAILGATE LOGO	Necessary	68.00 FL	*68.00 FL
3	1		*TAILGATE LAMP	O/S Cut	718.40 FL	*359.20 FL
4	1		*TAILGATE EMBLEM VALVE MATIC	Necessary	98.60 FL	*62.20 FL
5	1		*TAILGATE OUTER CHROME GARNISH	Not Damaged	298.60 FL	*- FL
6	1		*TAILGATE INNER TRIM BOARD	Broken	580.10 FL	*420.10 FL
7	1		*TAILGATE WEATHERSTRIP	Torn	329.10 FL	*299.10 FL
8	1		*TAILGATE INNER LOCK	Not Damaged	409.00 FL	*- FL
9	1		*TAILGATE INNER LOCK STICKER	Not Damaged	38.00 FL	*- FL
10	1		*TAILGATE ANTENNA SENSOR	Not Damaged	171.60 FL	*- FL
11	2		*TAILGATE NUMBER PLATE LAMP	Not Damaged	134.00 FL	*- FL
12	1		*TAILGATE WINDSCREEN MOULDING	Necessary	65.80 FL	*65.80 FL
13	2		*TAILGATE WINDSCREEN SIDE MOULDING	Necessary	79.60 FL	*79.60 FL
14	1		*REAR BUMPER	Broken	968.00 FL	*566.01 FL
15	2		*REAR BUMPER SUPPORT BRACKET	No such part	194.20 FL	*- FL
16	2		*REAR BUMPER SIDE RETAINER	Necessary	217.20 FL	*196.00 FL
17	1		*REAR BUMPER REFLECTOR	O/S Broken	139.40 FL	*67.10 FL
18	1		*REAR END PANEL	Dented	827.80 FL	*560.94 FL
19	1		*REAR END PANEL TOP GARNISH	Broken	358.60 FL	*288.90 FL
20	1		*REAR FLOOR PANEL	Not Damaged	1,093.70 FL	*- FL
21	1		*REAR FLOOR PANEL INNER TRIM	Not Damaged	381.20 FL	*- FL
22	1		*SPARE TYRE TRANSFER	Not Damaged	247.00 FL	*- FL
23	2		*REAR FENDER INNER TRIM BOARD	Not Damaged	1,159.60 FL	*- FL
24	1		*TAILLAMP	O/S Cut	996.20 FL	*580.20 FL
25	2		*TAILLAMP LOWER BRACKET	Not Necessary	225.40 FL	*- FL
26	1		*EXHAUST PIPE	Dented	891.00 FL	*780.50 FL
27	2		*EXHAUST MOUNTING	Not Damaged	137.20 FL	*- FL
28	1		*EXHAUST HEAT SHIELD	No such part	145.80 FL	*- FL
29	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
30	1		*TAILGATE SEALANT	Necessary	100.00 FS	*40.00 FS
31	1		*TAILGATE LAMP SEAL	O/S Necessary	120.00 FS	*30.00 FS
32	2		*TAILGATE LAMP CLIPS	Necessary	100.00 FS	*- FS
33	1		*TAILGATE OUTER CHROME GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
34	1		*TAILGATE INNER TRIMBOARD CLIPS	Necessary	50.00 FS	*30.00 FS
35	1		*TAILGATE WINDSCREEN INNER SEAL	No such part	60.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*60.00 FS
37	1		*TAILGATE WINDSCREEN PRIMER AND CLEANER	Not Necessary	80.00 FS	*- FS
38	1		*TAILGATE WINDSCREEN CLIPS	No such part	50.00 FS	*- FS
39	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
40	2		*REAR BUMPER REVERSE SENSOR	Scratched	500.00 FS	*200.00 FS
41	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*40.00 FS
42	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
43	1		*REAR FLOOR PANEL SEALANT	Not Necessary	100.00 FS	*- FS
44	1		*REAR FLOOR PANEL INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
45	2		*REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	100.00 FS	*- FS
46	1		*TAILLAMP SEAL	O/S Necessary	120.00 FS	*30.00 FS
47	2		*TAILLAMP CLIPS	Not Necessary	100.00 FS	*- FS
48	1		*REVERSE CAMERA	Not Damaged	480.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	15,253.30	6,175.65
- List Item Discount on L Items 25.00/25.00% (\$)	3,203.33	1,416.41
Total Parts (\$)	12,049.97	4,759.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R TAILGATE COMPONENT	New	150.00	80.00
2	R&R TAILGATE WINDSCREEN	New	250.00	120.00
3	R&R REAR BUMPER REVERSE SENSOR	New	100.00	60.00
4	R&R REVERSE CAMERA	New	150.00	0.00
5	R&R EXHAUST PIPE	New	150.00	50.00
6	CONDUCT WATER LEAK TEST	New	180.00	0.00
7	DIAGNOSTIC RESET FAULT CODE	New	300.00	0.00
8	UPHOLSTERY	New	300.00	0.00
9	CHECK WIRING	New	100.00	30.00
10	PANEL BEATING	New	1,400.00	1,000.00
11	RUST PROOFING	New	200.00	60.00
12	SPRAY PAINTING	New	1,400.00	800.00
Gross Labour Cost (S\$)			4,680.00	2,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >