

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21004157/ABS3Q2
Date: 18/10/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SJM7193T	Insured Vehicle No :	SMA739T
Date of Loss:	30/03/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0001357

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJM7193T		
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Engine No:	1NZX815068
Reg. Date:	14/01/2009 (Man. Year: 2009)	Chassis No:	MR053HY9305085062
Colour:	Silver	Odometer:	204391 km
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,615.05	3,428.32	2,186.73	38.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,040.00	1,320.00	720.00	35.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,655.05	4,748.32	2,906.73	37.97
Approved Total (Overridden) (S\$)		3,700.00		

(S\$)	7,655.05	3,700.00	3,955.05	51.67
+ GST 7.00/7.00% (S\$)	535.85	259.00	276.85	51.67
Nett Amount (S\$)	8,190.90	3,959.00	4,231.90	51.67
+ Car Rental (7.0 x S\$120.00/day + 7.00% GST) (S\$)		898.80		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		100.00		
Nett Liability (S\$)		4,965.25		
Global Sum Settlement (S\$)		4,800.00		

INSPECTION

Date of Assignment: 31/03/2021

Date Inspected: 01/04/2021

Inspected At:

N-51 Automotive Pte Ltd (HQ)
 BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB
 Singapore 417921

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Sep 2021)
Parts:	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJM7193T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	495.70 FL	*495.70 FL
2	1		*FRONT BUMPER LOGO EMBLEM	Necessary	66.20 FL	*66.20 FL
3	1		*FRONT BUMPER RH FOGLAMP GARNISH	Cracked	84.70 FL	*84.70 FL
4	1		*FRONT BUMPER SIDE RETAINER L/R	O/S Damaged	129.20 FL	*64.60 FL
5	1		*FRONT RH FENDER	Dented	637.70 FL	*637.70 FL
6	1		*FRONT RH FENDER VVT.I EMBLEM	Necessary	58.00 FL	*58.00 FL
7	1		*FRONT RH FENDER INNER BRACKET	Not Necessary	58.00 FL	*- FL
8	1		*FRONT RH FENDER INNER GARNISH (VERTICAL)	Not Necessary	54.10 FL	*- FL
9	1		*FRONT RH FENDER INNER SHIELD COVER	Torn	175.60 FL	*175.60 FL
10	1		*FRONT RH HEADLAMP	Cracked	558.90 FL	*558.90 FL
11	1		*FRONT RH KNUCKLE ARM	Damaged	558.90 FL	*558.90 FL
12	1		*FRONT RH KNUCKLE ARM BEARING	Necessary	183.80 FL	*183.80 FL
13	1		*FRONT RH LOWER ARM	Bent	1,195.40 FL	*397.40 FL
14	1		*FRONT RH SHOCK ABSORBER	Bent	463.80 FL	*463.80 FL
15	1		*FRONT RH SHOCK ABSORBER TOP MOUNTING	Not Necessary	223.30 FL	*- FL
16	1		*FRONT RH STABILIZER LINK	Not Necessary	213.60 FL	*- FL
17	1		*FRONT RH TIE ROD END	Not Necessary	117.70 FL	*- FL
18	1		*FRONT WASHER TANK	Cracked	145.80 FL	*145.80 FL
19	1		*FRONT WASHER TANK MOTOR	Not Necessary	293.00 FL	*- FL
20	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
21	1		*FRONT RH 185/65R15 TYRE	Not Necessary	350.00 FS	*- FS
22	1		*SET FRONT RH FENDER INNER SHIELD COVER CLIPS	Necessary	30.00 FS	*30.00 FS
23	1		*FRONT RH SPORT RIM	Cut	900.00 FS	*450.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,043.40	4,401.10
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,428.35	972.78

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					5,615.05	3,428.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING AND RESETTNG HEADLAMP FOCUSSING (TO FR)	New	60.00	30.00
2	TO REMOVE ,CHARGE FRONT SUSPENSION PARTS ,ABSORBER ,LOWER ARM ,KNUCKLE ARM, WHEEL BEARING ,BEARING HUB ,DRIVE SHAFT ,ANTI-ROLL BAR ,TOP -ARM AND STEERING RACK AND PINION	New	280.00	220.00
3	TO ROAD TEST DRIVING ,CHECK AND RESETTNG WHEEL ALIGNMENT SYSTEM	New	100.00	80.00
4	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	800.00	450.00
5	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	700.00	500.00
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	100.00	40.00
Gross Labour Cost (\$\$)			2,040.00	1,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >