

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI21004159/BTF3Q2
Date: 08/06/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00179042000
Claimant Vehicle No :	SLQ2593K	Insured Vehicle No :	SMT7048H
Date of Loss:	22/03/2021	Nature of Claim:	TP
			Claim No: SNM21D201693/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ2593K		
Make & Model:	VOLKSWAGEN JETTA, 1.4 (A)	Engine No:	CAXF82956
Reg. Date:	30/06/2017 (Man. Year: 2015)	Chassis No:	WVWZZZ16ZGM009757
Colour:	Black	Odometer:	56835 km
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,613.42	6,153.71	3,459.71	35.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,220.00	960.00	1,260.00	56.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,833.42	7,113.71	4,719.71	39.88
Approved Total (Overridden) (S\$)		5,700.00		

(S\$)	11,833.42	5,700.00	6,133.42	51.83
+ GST 7.00/7.00% (S\$)	828.34	399.00	429.34	51.83
Nett Amount (S\$)	12,661.76	6,099.00	6,562.76	51.83

INSPECTION

Date of Assignment: 31/03/2021

Date Inspected: 30/04/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Bifrost Auto Pte Ltd (Kaki Bukit)
 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
 Singapore 415875

Adjuster: Lim Teow Guan**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Jun 2021)
Parts:	143	VOLKSWAGEN JETTA 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ2593K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	1,274.94 FL	*1,152.82 FL
2	1		*FRONT BUMPER LH SIDE BRACKET	Necessary	22.54 FL	*22.54 FL
3	1		*FRONT BUMPER LOWER SPOILER	No such part	503.60 FL	*- FL
4	1		*FRONT BUMPER REINFORCEMENT	Bent	635.15 FL	*598.00 FL
5	1		*FRONT BUMPER INNER SPONGE	Broken	89.45 FL	*89.45 FL
6	1		*FRONT BUMPER CENTRE BRACKET	Broken	114.33 FL	*114.33 FL
7	1		*FRONT BUMPER CENTRE LOWER GRILLE	Broken	226.58 FL	*226.58 FL
8	1		*FRONT BUMPER LH LOWER SIDE GRILLE	Broken	78.53 FL	*78.53 FL
9	1		*FRONT BUMPER LH LOWER SIDE FOG LAMP	Broken	374.16 FL	*374.16 FL
10	1		*FRONT BUMPER LH SIDE PARKING SENSOR	Scratched	238.18 FL	*205.00 FL
11	2		*FRONT BUMPER SIDE PARKING SENSOR BRACKETS	Necessary (1 PCS ONLY)	52.00 FL	*42.10 FL
12	1		*FRONT GRILLE	Broken	600.87 FL	*600.87 FL
13	1		*SUPPORT PANEL	Broken	1,168.65 FL	*1,055.00 FL
14	1		*LH HEADLAMP ASSY	Broken	3,574.80 FL	*1,955.35 FL
15	1		*LH HEADLAMP UPPER BRACKET	Broken	35.89 FL	*35.89 FL
16	1		*LH HEADLAMP WASHER NOZZLE COVER	Broken	24.12 FL	*24.12 FL
17	1		*LH HEADLAMP WASHER NOZZLE	Broken	173.83 FL	*173.83 FL
18	1		*FRONT LH FENDER	Repair	504.71 FL	*- FL
19	1		*AIRCON CONDENSER	Not Damaged	767.03 FL	*- FL
20	1		*SET FRONT BUMPER CLIPS	Necessary	70.00 FS	*30.00 FS
21	1		*FRONT NUMBER PLATE	Broken	70.00 FS	*50.00 FS
22	1		*RADIATOR COOLANT	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,659.36	6,828.57
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,045.94	674.86
Total Parts (\$\$)	9,613.42	6,153.71

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES TO REMOVE ,CHECK ,REPLACE AND REINSTALL DAMAGES BODYPARTS ,TO PANEL BEATING ,CUT /WELD AND RE-ALIGN ALL AFFECTED PANELS	New	800.00	500.00
2	SPRAY PAINTING ON AFFECTED PANELS	New	900.00	400.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	50.00	0.00
4	APPLY RUST COATING ON AFFECTED AREAS	New	40.00	0.00
5	REMOVE AND REPLACE AIRCON CONDENSER AND PIPES TO ASSIST REPAIRS .TO REFILL AIRCON GAS	New	180.00	0.00
6	REMOVE AND REINSTALL RADIATOR ,HOSES AND FAN ASSY TO ASSIST REPAIRS .TO REFILL RADIATOR COOLANT	New	180.00	0.00
7	REMOVE AND REPLACE FRONT BUMPER PARKING SENSORS	New	70.00	60.00
Gross Labour Cost (S\$)			2,220.00	960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >