

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21004160/URS3Q2
Date: 23/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100407349
Claimant Vehicle No :	SGX296D	Insured Vehicle No :	SKS1921E
Date of Loss:	30/03/2021	Nature of Claim:	TP
		Claim No:	3954170815SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGX296D		
Make & Model:	HONDA STREAM, 1.8 (A)	Engine No:	R18A1741642
Reg. Date:	08/08/2007 (Man. Year: 2007)	Chassis No:	RN61037047
Colour:	Silver	Odometer:	379932 km
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/50Z R17	Rear Tyre Size:	215/50Z R17
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,100.64	3,707.20	12,393.44	76.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,450.00	3,220.00	2,230.00	40.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,550.64	6,927.20	14,623.44	67.86
Approved Total (Overridden) (S\$)		4,000.00		

Nett Amount (S\$)	21,550.64	4,000.00	17,550.64	81.44
		+ Car Rental (9.0 x S\$100.00/day) (S\$)	900.00	
		+ Doc/Search Fee (S\$)	36.45	
		Nett Liability (S\$)	4,936.45	

INSPECTION

Date of Assignment: 31/03/2021

Date Inspected: 31/03/2021

Estimated Period of Repair: 8.0 days

Inspected At: Zoom Autowerks Pte Ltd
832 SIMS AVENUE #12-884 EUNOSVILLE
Singapore 400832

Adjuster: MARCUS CHUA**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	725.30 FL	*665.40 FL
2	2		*REAR BUMPER SIDE RETAINER	Not Necessary	98.80 FL	*- FL
3	1		*REAR BUMPER TOW COVER	Twisted	34.70 FL	*20.80 FL
4	1		*REAR BUMPER CLIPS	Necessary	60.00 FL	*39.00 FL
5	1		*REAR END PANEL TOP GARNISH	Distorted	195.60 FL	*168.00 FL
6	1		*REAR END PANEL	Badly Dented	545.90 FL	*306.00 FL
7	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	60.00 FL	*- FL
8	1		*REAR TAILGATE	Badly Dented	1,171.30 FL	*953.00 FL
9	1		*REAR TAILGATE INNER TRIMBOARD	Not Necessary	281.60 FL	*- FL
10	1		*REAR TAILGATE INNER TRIMBOARD CLIPS	Not Necessary	60.00 FL	*- FL
11	1		*REAR TAILGATE INNER LOCK	Shorted	245.90 FL	*145.50 FL
12	1		*REAR TAILGATE INNER HANDLE	Not Necessary	68.40 FL	*- FL
13	1		*REAR TAILGATE CENTRE GARNISH	Not Necessary	361.20 FL	*- FL
14	1		*REAR TAILGATE EMBLEM (STREAM)	Serviceable	72.40 FL	*- FL
15	1		*REAR TAILGATE LOGO	Not Necessary	98.40 FL	*- FL
16	2		*REAR TAILGATE DAMPER	Not Necessary	390.40 FL	*- FL
17	1		*REAR TAILGATE WEATHER STRIP	Twisted	214.50 FL	*109.20 FL
18	2		*REAR TAILLAMPS	Not Necessary	1,450.80 FL	*- FL
19	1		*REAR TAILLAMPS CLIPS	Not Necessary	32.00 FL	*- FL
20	2		*REAR FENDER INNER TRIMBOARD	Not Necessary	1,540.80 FL	*- FL
21	1		*REAR FENDER INNER TRIMBOARD CLIPS	Not Necessary	60.00 FL	*- FL
22	1		*SET REVERSE SENSOR	Shorted	304.00 FS	*200.00 FS
23	1		*REVERSE SENSOR HOLDER	Not Necessary	160.00 FL	*- FL
24	1		*REAR FLOOR PANEL TOP TRAY	Not Necessary	245.70 FL	*- FL
25	1		*REAR FLOOR PANEL	Repair	1,451.60 FL	*- FL
26	1		*REAR SPARE TYRE HOLDER	Not Necessary	425.80 FL	*- FL
27	1		*REAR EXHAUST CHROME MUFFLER	Not Necessary	120.00 FL	*- FL
28	1		*REAR EXHAUST END PIPE	Not Necessary	785.00 FL	*- FL
29	2		*REAR EXHAUST MOUNTING	Not Necessary	108.40 FL	*- FL
30	1		*FRONT BUMPER	Deformed / Torn	785.90 FL	*655.40 FL
31	2		*FRONT BUMPER FOG LAMP	Not Necessary	391.60 FL	*- FL
32	1		*FRONT BUMPER FOG LAMP GARNISH	Not Necessary	117.80 FL	*- FL
33	1		*FRONT BUMPER CENTRE AIR-GRILLE	Not Necessary	115.60 FL	*- FL
34	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	191.20 FL	*- FL
35	1		*FRONT BUMPER TOW GARNISH	Not Necessary	43.50 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*FRONT BUMPER REINFORCEMENT	Bent	258.40 FL	*228.20 FL
37	1		*FRONT BUMPER CLIPS	Necessary	60.00 FL	*39.00 FL
38	1		*RADIATOR GRILLE BASED	Cracked	286.70 FL	*282.00 FL
39	1		*RADIATOR GRILLE CHROME	Not Necessary	198.50 FL	*- FL
40	1		*RADIATOR GRILLE LOGO	Not Necessary	95.00 FL	*- FL
41	1		*RADIATOR GRILLE EMBLEM (RSZ)	Not Necessary	115.00 FL	*- FL
42	1		*FRONT BONNET	Bent / Buckled	738.60 FL	*685.00 FL
43	1		*FRONT BONNET LOCK	Not Necessary	125.80 FL	*- FL
44	1		*FRONT BONNET INSULATOR	Not Necessary	115.60 FL	*- FL
45	1		*FRONT BONNET INSULATOR CLIPS	Not Necessary	60.00 FL	*- FL
46	2		*HEADLAMP ASSY	Serviceable	1,561.80 FL	*- FL
47	2		*HEADLAMP BRACKET	Not Necessary	248.60 FL	*- FL
48	1		*FRONT SUPPORT PANEL	Repair	466.20 FL	*- FL
49	1		*AC CONDENSER	Not Necessary	956.80 FL	*- FL
50	1		*RADIATOR ASSY	Not Necessary	1,486.20 FL	*- FL
51	1		*REAR TAILGATE GLASS INNER SEAL	Necessary	75.00 FS	*30.00 FS
52	1		*REAR TAILGATE GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
53	1		*REAR NUMBER PLATE	Serviceable	55.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	19,997.30	4,566.50
- List Item Discount on L Items 20.00/20.00% (\$)	3,896.66	859.30
Total Parts (\$)	16,100.64	3,707.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REPAIR & RENEW AFFECTED REAR ACCIDENT AREAS	New	1,100.00	800.00
2	TO PUTTY ,SPRAY PAINT ON AFFECTED REAR ACCIDENT AREAS	New	1,200.00	1,000.00
3	TO REMOVE ,REPAIR & RENEW AFFECTED FRONT ACCIDENT AREAS	New	950.00	400.00
4	TO PUTTY ,SPRAY PAINT ON AFFECTED FRONT ACCIDENT AREAS	New	1,000.00	600.00
5	TO DISCHARGE & CHARGE UP GAS	New	120.00	0.00
6	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	20.00
7	TO REMOVE & INSTALL REAR TAILGATE GLASS	New	150.00	120.00
8	TO REMOVE & REFIT REAR TAILGATE COMPONENT TO ASSIST REPAIRS	New	100.00	60.00
9	TO REMOVE & INSTALL REAR BOOTLID COMPARTMENT TRIMS TO ASSIST REPAIRS	New	100.00	80.00
10	TO REMOVE & RE-POSITION REAR EXHAUST PIPE	New	150.00	0.00
11	TO CONDUCT REAR WATER SEEPAGE TEST	New	100.00	0.00
12	TO REMOVE & RE-POSITION REVERSE SENSOR	New	80.00	50.00
13	TO RE-PROGRAMME & RESET DIAGNOSTIC	New	250.00	0.00
14	TO RUST PROOF AFFECTED AREAS	New	100.00	90.00

Gross Labour Cost (S\$)

5,450.00

3,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >