

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21004161/T1QF3N2**Date:** 09/09/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNVV00006322101

Claimant Vehicle No : SDN2777H **Insured Vehicle No :** SJV3982L

Date of Loss: 26/03/2021 Nature of Claim: TP Claim No: SNM21D201780/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDN2777H**

Make & Model: JAGUAR XF, 2.0 P 250PS (A) Engine No: 190130Y0816PT204

Reg. Date: 15/10/2019 (Man. Year: 2019) Chassis No: SAJBB4AX3KCY80216

Colour: White Odometer: 28649 km

Engine Capacity: 1997 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 R18 Rear Tyre Size: 245/45 R18

Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	42,708.10	21,382.60	21,325.50	49.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,610.00	1,890.00	3,720.00	66.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	48,318.10	23,272.60	25,045.50	51.83
Approved Total (Overridden) (\$\$)		17,250.00		
(\$\$)	48,318.10	17,250.00	31,068.10	64.30
+ GST 7.00/7.00% (\$\$)	3,382.27	1,207.50	2,174.77	64.30
Nett Amount (\$\$)	51,700.37	18,457.50	33,242.87	64.30

INSPECTION

Date of Assignment: 31/03/2021

Date Inspected: 31/03/2021 Inspected At: RICO 60 AUTO SERVICES PTE LTD (HQ)
8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Sep 2021)
Parts:	143	JAGUAR XF 2.0 P 250PS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDN2777H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	3,320.00 F	*3,320.00 F
2	1		*BOOTLID LOCK	Bent	568.00 F	*568.00 F
3	1		*BOOTLID LOGO	Necessary	156.90 F	*156.90 F
4	1		*BOOTLID EMBLEM (JAGUAR)	Necessary	147.80 F	*147.80 F
5	1		*BOOTLID EMBLEM (XF)	Necessary	89.00 F	*89.00 F
6	1		*BOOTLID EMBLEM (2.5E)	Necessary	77.50 F	*77.50 F
7	1		*BOOTLID INNER LOCK	Not Necessary	495.30 F	*- F
8	1		*BOOTLID WEATHERSTRIP	Cut	458.00 F	*348.00 F
9	1		*BOOTLID INNER TRIM	Not Necessary	455.00 F	*- F
10	2		*BOOTLID ANTI CLAIM SENSOR	Not Necessary	1,454.00 F	*- F
11	2		*BOOTLID SIDE GUARD GARNISH	Not Necessary	438.00 F	*- F
12	1		*BOOTLID DETECTOR SENSOR	Cracked	482.40 F	*295.00 F
13	1		*REAR BUMPER	Deformed	1,589.00 F	*1,507.00 F
14	2		*REAR BUMPER SIDE RETAINER	Not Necessary	300.00 F	*- F
15	2		*REAR BUMPER ATTACHMENT RETAINER	Not Necessary	240.00 F	*- F
16	1		*REAR BUMPER CENTER RETAINER	Deformed	452.00 F	*317.00 F
17	1		*REAR BUMPER REVERSE SENSOR (4 Pcs)	Not Working (3 Pcs only)	1,940.00 F	*1,186.20 F
18	4		*REAR BUMPER REVERSE SENSOR HOLDER	Necessary	120.00 F	*120.00 F
19	1		*REAR BUMPER REVERSE SENSOR WIRE	Cut	1,542.00 F	*977.20 F
20	1		*REAR BUMPER REINFORCEMENT	Bent	982.40 F	*641.00 F
21	2		*REAR BUMPER BRACKET	Not Necessary	432.00 F	*- F
22	1		*REAR BUMPER LOWER SPOILER	Deformed	655.00 F	*655.00 F
23	1		*SET REAR BUMPER SIDE SCAN SENSOR	Not Necessary	672.30 F	*- F
24	2		*REAR BUMPER SIDE SCAN SENSOR UNIT	Cracked	1,690.00 F	*1,690.00 F
25	2		*TAILLAMP	Cracked	3,690.00 F	*2,426.00 F
26	2		*TAILLAMP RAILING GARNISH	Not Necessary	744.00 F	*- F
27	2		*TAILLAMP LOWER BRACKET	Not Necessary	310.00 F	*- F
28	2		*REAR FENDER INNER TRIM	Not Necessary	1,335.80 F	*- F
29	2		*REAR FENDER INNER COWLING	Not Necessary	478.60 F	*- F
30	1		*REAR END PANEL	Bent	1,885.00 F	*1,198.00 F
31	1		*REAR END PANEL TOP GARNISH	Deformed	411.00 F	*338.00 F
32	1		*REAR FLOOR PANEL	Not Necessary	1,310.00 F	*- F
33	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	1,254.00 F	*- F
34	1		*REAR FLOOR PANEL TOP TOOL SPONGE	Not Necessary	554.30 F	*- F
35	1		*REAR FLOOR PANEL UNDER COVER	Cracked	488.90 F	*321.00 F
36	2		*REAR EXHAUST PIPE	Bent	3,960.00 F	*3,960.00 F
37	1		*REAR EXHAUST MOUNTING (4 Pcs)	Deformed (2 Pcs only)	448.00 F	*224.00 F
38	1		*REAR EXHAUST GASKET (2 Pcs)	Necessary (1 Pc only)	100.00 F	*50.00 F
39	2		*REAR EXHAUST INSULATOR TOP	Not Necessary	1,084.00 F	*- F
40	2		*REAR EXHAUST INSULATOR SIDE	Bent	670.00 F	*670.00 F
41	1		*CENTER EXHAUST CENTER PIPE	Not Necessary	2,447.90 F	*- F
42	1		*EXHAUST DOWN PIPE	Not Necessary	2,170.00 F	*- F
43	1		*BOOTLID INNER TRIM CLIP	Not Necessary	50.00 FS	*- FS
44	1		*REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*TAILLAMP CLIPS	Necessary	40.00 FS	*20.00 FS
46	1		*TAILLAMP RAILING GARNISH CLIP	Not Necessary	40.00 FS	*- FS
47	1		*REAR FENDER INNER TRIM CLIP	Not Necessary	60.00 FS	*- FS
48	1		*REAR FENDER COWLING CLIPS	Not Necessary	30.00 FS	*- FS
49	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS
50	1		*REAR END PANEL SEALANT	Necessary	150.00 FS	*40.00 FS
51	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	150.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)						42,708.10 21,382.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,REMOVAL AND REPLACING PARTS	New	1,800.00	700.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	800.00
3	TUFF COAT	New	250.00	30.00
4	WIRING CHECK	New	600.00	30.00
5	REMOVE AND REFIX CUSHION,CARPET AND SEAT	New	300.00	60.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	120.00	30.00
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	120.00	30.00
8	REAR CHASSIS ALIGNMENT	New	300.00	0.00
9	TRANFER BOOTLID MECHANISM	New	120.00	60.00
10	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
11	REMOVE AND REFIX REAR EXHAUST PIPE	New	300.00	150.00
Gross Labour Cost (\$\$)			5,610.00	1,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >