

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21004162/EPS3Q2
Date: 11/08/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100341337
Claimant Vehicle No :	FBN486J	Insured Vehicle No :	SKJ9897L
Date of Loss:	25/03/2021	Nature of Claim:	TP
		Claim No:	8926093421SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBN486J	Engine No:	G3E3E0046755
Make & Model:	YAMAHA FZN150, 149cc	Chassis No:	ME1RG1619G2002452
Reg. Date:	20/06/2018 (Man. Year: 2016)	Odometer:	40065 km
Colour:	Red		
Engine Capacity:	149 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	110/70-17	Rear Tyre Size:	140/70-17
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	547.20	506.70	40.50	7.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	350.00	320.00	30.00	8.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	897.20	826.70	70.50	7.86
Approved Total (Overridden) (S\$)		650.00		

(S\$)	897.20	650.00	247.20	27.55
+ GST 7.00/7.00% (S\$)	62.80	45.50	17.30	27.55
Nett Amount (S\$)	960.00	695.50	264.50	27.55
+ Loss of Use (3.0 x S\$25.00/day) (S\$)		75.00		
+ Medical Costs (S\$)		264.50		
Nett Liability (S\$)		1,035.00		

INSPECTION

Date of Assignment: 31/03/2021

Date Inspected: 05/04/2021

Estimated Period of Repair: 3.0 days

Inspected At: Southern Motor (HQ)
BLK 1006 BUKIT MERAH LANE 2, #01-10
Singapore 159762**Adjuster:** CHEN TSUE YEE**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Bent	68.00 FL	*68.00 FL
2	1		*HANDLE GRIP	Cut	35.00 FL	*35.00 FL
3	1		*HANDLE BALANCER	Cut	25.00 FL	*25.00 FL
4	1		*EXHAUST PIPE PROTECTOR	Cut	85.00 FL	*85.00 FL
5	1		*GIVI BOX	Cut	350.00 FL	*350.00 FL
6	1		*FRONT SIGNAL	Not Necessary	45.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	608.00	563.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	60.80	56.30
Total Parts (\$\$)	547.20	506.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TRANSPORT	New	30.00	30.00
2	ALIGNMENT FORK	New	75.00	75.00
3	ALIGNMENT FRONT RIM	New	65.00	65.00
4	LABOR	New	180.00	150.00
Gross Labour Cost (\$\$)			350.00	320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >