



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2103945

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 07/06/2021
Reference CC4/FCI21004166/R1es3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. FBJ 2573Z
Insured Veh. SHB 8340Z
Claim No. D21001003MFSH/1
Policy No. D-20094922MFSH
Accident Date 14/12/2020
Inspection Date 31/03/2021

Description	Total
Survey Inspection	329.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	329.00
GST (7%)	23.03
Grand Total	352.03

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI21004166/R1es3q2 Date: 07/06/2021 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 8340Z	Veh. Inspected	FBJ 2573Z	
Policy No.	D-20094922MFSH	Coverage (\$)	0.00	
Claim No.	D21001003MFSH/1	Excess (\$)	0.00	
Assign From	VIC	Assign Date	31/03/2021	
2. Vehicle Particulars & Condition				
Make & Model	K.T.M. 390 DUKE	c.c	373	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	VBKJGJ406DC214980	Colour	MULTI	
Odometer	25917 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	120/70-17	IRC	4 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	160/60-17	IRC	4 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/12/2020	Inspection Date	31/03/2021	
Survey held at	53 UBI AVE 1 #01-24			
Repairer	KARZ WORK SOLUTIONS			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBJ 2573Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT FORK	BENT	550.00	550.00
1	FRONT FORK BRACKET	SERVICEABLE	350.00	-
1	SET BALANCER	SCRATCHED	150.00	68.00
1	HANDLE BAR	BENT	280.00	280.00
1	FRONT FAIRING UPPER LH }	SCRATCHED	450.00	648.00
1	FRONT FAIRING LOWER LH }	CRACKED	450.00	-
1	FRONT FAIRING BOTTOM LH }	CRACKED	350.00	-
1	RADIATOR	BENT	600.00	580.00
1	RADIATOR COVER LH	MISSING	180.00	180.00
1	RADIATOR COVER RH	SERVICEABLE	180.00	-
1	RADIATOR FAN COWLING	DEFORMED	300.00	300.00
1	FRONT FAIRING UPPER RH	SERVICEABLE	400.00	-
1	FRONT FAIRING LOWER RH	SERVICEABLE	400.00	-
1	BODY FRAME BRACKET LH	TO REPAIR SEE LABOUR	200.00	-
1	BRAKE PEDAL	BROKEN	90.00	90.00
1	FOOTREST LH	SERVICEABLE	70.00	-
1	FOOTREST BRACKET LH	SERVICEABLE	90.00	-
1	FOOTREST RUBBER LH	SERVICEABLE	60.00	-
1	FOOTREST RH	SCRATCHED	70.00	70.00
1	FOOTREST BRACKET RH	SCRATCHED	90.00	90.00
1	FOOTREST RUBBER RH	SERVICEABLE	60.00	-
1	FRONT FENDER	SCRATCHED	250.00	250.00
1	PILLION FOOTREST RH	SCRATCHED	70.00	70.00
	LESS 10% DISCOUNT		-569.00	-317.60
			5,121.00	2,858.40
	<u>SPECIAL NETT ITEMS</u>			
1	RIM (SN)	SERVICEABLE	300.00	-
1	TYRE (SN)	SERVICEABLE	300.00	-
2	GEAR SHAFT OIL SEAL (SN)	NECESSARY	24.00	24.00
1	BOT FORK OIL SEAL (SN)	NECESSARY	120.00	60.00

Report Ref No. CC4/FCI21004166/R1es3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FORK OIL (SN)	NECESSARY	60.00	40.00
1	BRAKE LEVER (AFTER MARKET) (SN) (ADDITIONAL)	SCRATCHED	80.00	65.00
1	SET WING MIRROR (AFTER MARKER) (SN) (ADDITIONAL)	SCRATCHED	180.00	70.00
1	BODY SLIDER (SN) (ADDITIONAL)	SCRATCHED	150.00	120.00
1	STICKERS (SN) (ADDITIONAL)	NECESSARY	500.00	200.00
			1,714.00	579.00
	LABOUR			
	TO CHECK WIRIGN SYSTEM.	NOT NECESSARY	60.00	-
	TO CHECK FORK ALIGNMENT.		200.00	50.00
	TO REALIGN BODY FRAME .		350.00	150.00
	TO R&R SUSPENSION ,HANDLE BAR ,HEADLAMP & FAIRING.INCLUSIVE OF THE REPAIR OF BODY FRAME BRACKET LH .		400.00	250.00
	TO SPRAY FENDER ,SIDE FAIRING AND AFFECTED AREAS.		500.00	200.00
			1,510.00	650.00
GRAND TOTAL			8,345.00	4,087.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,250.00

Report Ref No. CC4/FCI21004166/R1es3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBJ 2573Z

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBJ 2573Z

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

