1/18/22, 11:57 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21004169/T1RS3Q2

18/01/2022 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100345422 **Claimant Vehicle** SHC6387J Insured Vehicle No: SKK3716K No:

Date of Loss: 30/03/2021 Nature of Claim: TP Claim No: 4042278049SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC6387J

Make & Model: KIA OPTIMA, 1.7 D (A) Engine No: D4FDEH313316 Reg. Date: 13/02/2015 (Man. Year: 2014) Chassis No: KNAGM414MF5578137

Odometer: Colour: 763532 km Silver

Engine Capacity: 1685 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65 R15 Rear Tyre Size: 205/65 R15 Front Left Side: Rear Left Side: Maxxis 6 mm Maxxis 6 mm Front Right Side: Maxxis 6 mm Rear Right Side: Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,032.20	902.90	2,129.30	70.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,620.00	1,340.00	1,280.00	48.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,652.20	2,242.90	3,409.30	60.32
Approved Total (Overridden) (S\$)		1,800.00		
(\$\$)	5,652.20	1,800.00	3,852.20	68.15
+ GST 7.00/7.00% (S\$)	395.65	126.00	269.65	68.15
Nett Amount (S\$)	6,047.85	1,926.00	4,121.85	68.15
+ Loss of Use (3.0 x S	\$\$50.00/day) (S\$)	150.00		
+ Car Rental (3.0 x S	\$\$62.76/day) (S\$)	188.28		
	(S\$)	2,264.28		
Liable Amou	unt (50.00%) (S\$)	1,132.14		
+ Doc	/Search Fee (S\$)	2.00		
N	Nett Liability (S\$)			

INSPECTION

Date of Assignment: 31/03/2021

Premier Automotive Services Pte Ltd (HQ) Inspected At: Date Inspected: 05/04/2021

23 Changi South Ave 2, #01-02

Singapore 486443

Estimated Period of Repair: 3.0 days

MOHD TAUFIKH BIN HAMID Adjuster: Jaslin Kok Chin Yi Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	696.00 FL	*- FL
2	2		*REAR BUMPER N/S & O/S SIDE BRACKET	Not Necessary	58.00 FL	*- FL
3	1		*REAR O/S WHEEL COVER	Cut	116.00 FL	*116.00 FL
4	1		*REAR O/S FENDER	Repair	1,205.00 FL	*- FL
5	1		*REAR O/S DOOR	Bent	765.00 FL	*765.00 FL
6	1		*REAR WINDSCREEN MOULDING	Not Necessary	98.00 FL	*- FL
7	1		*SET REAR BUMPER CLIPS	Not Necessary	48.00 FS	*- FS
8	1		*REAR BUMPER TOP PROTECTOR	Not Necessary	80.00 FS	*- FS
9	1		*REAR O/S FENDER STICKER	Necessary	60.00 FS	*30.00 FS
10	1		*SET O/S DOOR STICKERS	Necessary	100.00 FS	*80.00 FS
11	1		*SET SEALANT	Not Necessary	50.00 FS	*- FS
12	1		*SUNDRY	Not Necessary	50.00 FS	*- FS
F=Fra	anchise	part. S=SpcN	lett. L=ListItemDisc.	-		
				Sub Total (S\$)	3,326.00	991.00
			- List Item Discount on L Items	s 10.00/10.00% (S\$)	293.80	88.10
				Total Parts (S\$)	3,032.20	902.90
			Report was unsubmitted during this p	orint-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labo</u>	our Items			
1	TO CHECK REAR O/S WHEEL ALIGNMENT	New	80.00	80.00
2	TO DISMANTLE AND REFIT OLD WINDSCREEN GLASS ONTO NEW MOULDING	New	120.00	0.00
3	TO DISMANTLE /REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME	New	120.00	30.00
4	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT ,CARPET ,ETC TO FACILITATE REPAIRS	New	180.00	0.00
5	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS .TO HEAT/WELD & CUT REAR O/S FENDER .INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR ,RESHAPE AND ADJUST OF THE SAME ,ETC .REFITTING OF REAR O/S DOOR INNER COMPONENTS		1,000.00	400.00
6	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER ,REAR O/S FENDER ,REAR O/S DOOR ,FRONT O/S DOOR ,O/S ROCKER PANEL GARNISH	New	1,000.00	800.00
7	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	120.00	30.00
	Gross Labou	ır Cost (S\$)	2,620.00	1,340.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >