

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG21004174/R1QF3E2

**Date:** 13/04/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100460087  
**Claimant Vehicle No :** FBR8736P **Insured Vehicle No :** SLB6094L  
Date of Loss: 26/03/2021 Nature of Claim: TP Claim No: 8858955544SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBR8736P**  
Make & Model: YAMAHA R15, 155cc ABS Engine No: G3N4E0061959  
Reg. Date: 19/11/2020 (Man. Year: 2020) Chassis No: ME1RG6719L0044598  
Colour: Multi-colour Odometer: 10276 km  
Engine Capacity: 155 cc  
Market Value/New Car Price: N/A  
Sum Insured (\$\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 110/70 R17 Rear Tyre Size: 140/70 R17  
Front Left Side: Bridgestone 4 mm Rear Left Side: Bridgestone 4 mm  
Front Right Side: 0 mm Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 31/03/2021  
Date Inspected: 31/03/2021 Inspected At: Sincerelead Garage Pte Ltd - Buroh (HQ)  
2 Buroh Crescent, #02-09 Ace@Buroh  
Singapore 627546  
Estimated Period of Repair: 5.0 days

**Adjuster:** MOHD RASUL

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RIM	Scratched	0.00 F	*- F
2	1		*FRONT FENDER WHEEL GUARD	Scratched	0.00 F	*- F
3	1		*FRONT BRAKE DISC	Scratched	0.00 F	*- F
4	1		*FRONT FORK ASSY	Bent	0.00 F	*- F
5	1		*FRONT FORK OIL SEAL	Necessary	0.00 F	*- F
6	1		*FRONT HEADLAMP	Scratched	0.00 F	*- F
7	1		*FRONT HEADLAMP FAIRING	Scratched	0.00 F	*- F
8	2		*FRONT WING MIRROR	Broken	0.00 F	*- F
9	1		*FRONT LH SIGNAL LAMP	Broken	0.00 F	*- F
10	1		*HANDLE BAR LH	Bent	0.00 F	*- F
11	1		*HANDLE BAR GRIP	Cut	0.00 F	*- F
12	1		*CLUTCH LEVER	Scratched	0.00 F	*- F
13	2		*SIDE FAIRING	Scratched	0.00 F	*- F
14	1		*REAR FAIRING RH	Scratched	0.00 F	*- F
15	1		*FAIRING LOWER RH	Scratched	0.00 F	*- F
16	1		*SEAT ASSY	Cut	0.00 F	*- F
17	1		*FOOT BRAKE	Scratched	0.00 F	*- F
18	1		*FRONT FOOT REST	Scratched	0.00 F	*- F
19	1		*FRONT FOOT REST BRACKET	Scratched	0.00 F	*- F
20	1		*FOOT GEAR SHIFTER	Bent	0.00 F	*- F
21	1		*REAR FOOT REST	Scratched	0.00 F	*- F
22	1		*EXHAUST MUFFLER HEAT SHIELD	Scratched	0.00 F	*- F
23	1		*REAR LH SIGNAL LAMP	Distorted	0.00 F	*- F
F=Franchise part.						
					<b>Total Parts (\$\$)</b>	<b>0.00 0.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >