CS4 FC121004180/RIV+3 REFE ASS. REC. BY: ASSIGNMENT 4N5689K Yr Regn: 2014, July From: Date: Veh No: Estimated Cost: * Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover / OD/TPIWSITP RESIDD RESIEVA / INV I MIV Truck / Trailer or ROAD SWEEDER To Inspect Vehicle No: UN 5689K DULEVO SOOD VELICGE EUS. C.C 5883 at Workshop m/s 10010 Colour WHITE Insured / Std / NI / NA 18, GUL CRESCENT T/Radio: Insured / Std / NI / NA Sp.Reading Insured: Eng/No: ZA95502065AC381-83 Policy No. C/No: Gen. Cond: Good / Fall Poor / Burnt D21001017mFVS Claims No. Steering: Inorded Jammed / Leaked / Burnt or Sum Insured: Excess: Brake: Inorder / Jammed / Leaked / Burnt or (Client's Record) Modi: MIP I SIRIM I STD AVRIM or Make of Veh: 235/60R22-Tyre Size: (Policy Condition) Remark: The veh had commenced Its N/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / repair at the time of inspection. FIREWZA TOYO / YOKO or . Bal. or Market Value: Front Rear R/Bal. R/Bal. Consistent?: Yes or No IDAC Accident Roort: UBal. L/Bal. Consistent? : Yes or No GIA / PR Seen: mm D.O.A. 231 D.O.I. Est. Repairs: Res.: Yes or No 3 Val.: Yes or No ENCO Survey held at Lum Sum: Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or CA I REV I REP. 1 24 HRS ENGINE COMPARTMENT Vehicle: IN / OUT Person Contacted: The U/C / Chassis frame / Body Structure affected due to collision. Date / Time Action / Instruction epour liwit - Bak Submit CTL-MV:\$103,000 (est) LTA: \$14,044 NV:\$88,956 27/5/21 Dale/Time, File Pass to? Days Of Repair: : Prell. Report Resurvey No. of Trip: Survey Fee: : Final Report Date/Time, File Return to? Transportation: Investigation S+RS,__SI 500 Add Fee: :Site Insp (\$ 2) 27/5/21-Typist Interview (\$ Photos : Tech. Invs (\$ Repersonner: Others Lucin Similaria (# Weekend (\$ TOTAL

0		15011	110	
13	111	11	101	

REF: CS4/FCI21004180/P

ASSIGNMENT

From: Date:	Veh No: TN 5689K Yr Regn: July 12014.
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Corry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck/Trailer or Road Sweeper
To Inspect Vehicle No:	Make: DULEVO c.c 5883 -
at Workshop m/s	Colour Gree A/C: Insured LSTOJ NI / NA
of	Sp.Reading T/Radio: Insured / Std / NI / NA
Insured:	Eng/No: 1176284
Policy No.	C/No: 2A9S5020ESAC38183
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inerder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: morder ammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
(Policy Condition) Remark: The veh had commenced its repair at the time of inspection.	Tyre Size: F: 295/60 122-5 R: II BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/ TOYO/YOKO or Flre/26
Bal. or Market Value:	
IDAC Accident Rport: Consistent?: Yes or No	R/Bal. (O mm R/Bal. 10 mm
GIA / PR Seen: Consistent?: Yes or No	1/20
Est. Repairs: days Res.: Yes or No	
Lum Sum: % 3 Val.: Yes or No	
70 0 0 10	TO SO TO CONTROLLED
CA / REV / REP. / 24 HRS Vehicle: IN / OUT	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or Engine danged.
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction MV - \$103 K Rebute - \$14 K NC - \$89 K.	
	Pays Of Repair: Resurvey No. of Trip: Survey Fee: Transportation:
Add Fee:	: Site Insp (\$)s+Rssi
	:Interview (\$) Photos
Report Format :	: Tech. Invs (\$) Others
Lump Sum / I.B.I: (\$:Weekend (\$
	TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	246G
Vehicle Details	
Vehicle No.:	YN5689K
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Apr 2021
Vehicle Make:	DULEVO
Vehicle Model:	5000 VELOCE EU5 A/T 2WD ROAD SWEEPER
Primary Colour:	White
Secondary Colour:	Grey
Manufacturing Year:	2014
Engine No.:	1176284
Chassis No.:	ZA9S5020E5AC38183
Maximum Power Output:	· · · · · · · · · · · · · · · · · · ·
Open Market Value:	\$225,152.00
Original Registration Date:	26 Jul 2014
First Registration Date:	26 Jul 2014
Transfer Count:	0
Actual ARF Paid:	\$11,258.00
Intended PARE Rebate Details	Para Kataban Madalah Banda Banda Managara
PARF Eligibility:	No
PARF Eligibility Expiry Date:	*
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	25 Jul 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$43,001.00
COE Rebate Amount:	\$14,044.00
Total Rebate Amount:	\$14,044.00

The information contained herein is correct as at 19 Apr 2021

Enquire Vehicle Transfer Fee

Vehicle Details

Vehicle No. YN5689K
Make / Model DULEVO / 5000 VELOCE EU5 A/T 2WD ROAD SWEEPER
Vehicle Type : B66 - Goods (Open) Garbage/Sanitary Wagon Vehicle Attachment 1 : With Road Sweeper
Vehicle Scheme :
Normal
Chassis No.:
ZA9S5020E5AC38183
Propellant:
Diesel
Engine No.:
1176284
Motor No.:
Engine Capacity:
5883 cc
Power Rating:
= Tower Nating.
Maximum Power Output :
-

	Maximum Laden Weight:
	12160 kg
	Unladen Weight:
	8200 kg
	Year Of Manufacture :
	2014
	Original Registration Date :
	26 Jul 2014
/	Lifespan Expiry Date :
	25 Jul 2034
1	COE Category:
	C - Goods Vehicle & Bus
	Quota Premium:
	\$43,001.00
	COE Expiry Date:
	25 Jul 2024
	Road Tax Expiry Date :
	25 Jul 2021
	PARF Eligibility Expiry Date:
	Inspection Due Date:
	25 Jul 2021
	Intended Transfer Date :
	23 Apr 2021
	CO2 Emission :
	=
	CEV/VES Rebate Utilised Amount :
	*
	CO Emission :
	HC Emission:
	TIC ETHISSION.
	NOx Emission:
	•
	PM Emission:

Fees To Be Paid For Transfer

Transfer Fees \$25.00

Print

ОК →

Save as PDF

Copy as Text

Ramky Cleantech Services Pte. Ltd.		PAGE 1 of 4	
TITLE: AC	ccident / Incident Reporting Form (Non-Injury)	DOCUMENT NO: QHSE-FR-09-05	Rev No:

Instructions:

- 1) For incidents not involving Ramky's employee, please fill up Section A, C D,
- 2) For incidents involving Ramky's employee, please fill up ALL the sections,
- All completed and endorsed forms are to be submitted to HR/ Admin Department within 3 Calendar Days from date of incident.
- 4) To attach behind: Traffic Police report (for traffic accidents only), GIA (General Insurance Association) report (for traffic accidents only), Police report (for loss/ theft of company asset incidents) & Photo(s) of damage/ incident site (if available)

NATURE OF EVENT:		
Road Traffic Accident	☐ Dangerous Occurrence¹ ☐ Property Damage	
Loss/ Theft of Company Asset Others, please Indicate:		
Dangerous Occurrence:	townlosing/ Colleges of postfold as goodele	
Collapse/ failure of lifting equipment/ Fire or	explosion/ Collapse of scarfold or gondola	
	HSE/Case Event No:	
	(INDIPERIT	
SECTION A: DETAILS OF ACCIDENT		
Site / Division: Rublic Cleansin	Address / Location of Event :	
Rublic Cleansin	1301 Bedok North Avenue 4	
	1501 BEDGE NOWN FLYENCE -1	
Date of Event : 23/03/2021	Time of Event: 8300krs	
	Time of Event: 6300krs	
SECTION B: PARTICULARS OF EMP	Time of Event: 6300krs	
SECTION B: PARTICULARS OF EMP	LOYEE INVOLVED NRIC / FIN / Work Permit / Passport No:	
SECTION B: PARTICULARS OF EMP	LOYEE INVOLVED NRIC / FIN / Work Permit / Passport No:	

SECTION C: DESCRIPTION OF ACCIDENT / INCIDENT

Description of Accident / Incident:

(Please be as descriptive as possible:

What were the events that led to the incident?

What machines/ equipment/ tools were involved?

What are the details of 3rd Party (Full name, NRIC, contact number, company name), if relevant Provide photos/ sketches if available.)

Provide photos/sketches if available.)

is y ms 1/105891K

on 23/03/2021 at around 0215hrs, I was travelling along East Coast Parkway. I

noticed that there was hydraulic oil leaking from side brush - Hence, I drove back to

depot to change vehicle. When I reached the bus stop opposite depot around 0220hrs,

the engine was suddenly off itself and the signal (Engine Stop) on. I thied Scural times to

start the vehicle but could not. Then I smalled burning and immediately got down from whate to check.

I saw the smoke coming out from engine parts and there was a lady who passed by cauled SCDF.

If was around 0200hrs and two men from bus stop team assisted to put out the fire using their equipment.

About 0310hrs SCDF and police reached the scene while the fire had been totally purf out.

They have done their investigation at 0340hrs and the vehicle was towed to the workshop.

No igjury involved.

HAMS.	Ramky CI	leantech Se	rvices P	te. Ltd.			PAGE 2 of
TITLE: AC	cident / Inc	ident Repo	orting Fo	orm (Non-Inj	ury)	DOCUMENT N QHSE-FR-09-05	NO: Rev No:
The second second	D: OTHER INCID						
Select the a	appropriate optic	ons:					
Did the ever	nt results in any d	damages to gove	ernment pro	operty?	Yes	No No	
Did the ever	nt involve any gov	vernment officia	ls?		Yes	No.	_
from the gov	nt results in any n vernment or buildi ise attach a copy	ling owner?	ns/summon:	s/infringements	Yes	No -	
Any witnes	s to the acciden	t / incident / ev	ent?	Y 7		No.	*
				Yes		No	
If yes,	Name	: 17:1					
	Contact No.	116:					
*Delete acc	ordingly					-	70=
SECTION E	ROOT CAUSE	& CORRECTIV	E/ PREVEN	NTIVE ACTION(S)	(To be	completed by Supe	ervisor/OM)
Root Cause	e(s) of Accident	/ Incident / Eve	ent:				1.65
Defective	e/faulty tools/equip	pment		Inadequate/La		ervicing/maintenanc	e on
☐ Imprope	r tools/equipment	used		Incorrect body	positio	n/posture	
Lack of s	situational/spatial	awareness		Lack of knowl	edge/tra	aining	
Lack of s	supervisory contro	ol		SOP/instruction	ns not	communicated/uncl	ear/lacking
	essment not com	8	rmed	Miscommunic	ation		
1	disaster/Act of God	d/		Fatigued work	er (exc	essive work hours)	
Beyond worker's control Worker did not follow SOP (Including not wearing PPE)					wooring DDE\		
	vailable to worker				LIUIIUW	SOP (including not	wearing PPE)
7.00	ols specify:						_
	Preventive Activ	on(s) : (Action it	ems to be i	mplemented to pre	vent sir	milar accident / incident	dent /occurrence)
Corrective/	TTO TOTAL	ontol i (stodon il					
Corrective/		rrective/ Prevent				erson In Charge	Target Date
						erson In Charge	

1		
2	,	
3		
4		
5		
		<u> </u>

^{*} Delete as appropriate



Ramky Cleantech Services Pte. Ltd.

PAGE 3 of 4

TITLE: Accident / Incident Reporting Form (Non-Injury)

DOCUMENT NO: Rev No:

SECTION F: DISCIPLINARY ACTIONS (To be completed)	ted by Supervisor/OM)	
Type of discipline action/s taken:		
Verbal Warning 1st Warning Letter	2 nd Warning Letter	Not Applicable.
Details of Employee:		
Employee Name & Number:	Designation:	
Site:	Cost Centre:	
Reason(s) for discipline action:		
	- III	
DEDUCTION		
This incident would Incur a deduction of SGD\$	on your Performance Allowa	nce.
The Management takes a serious view on such negligen should be aware that the impact of this situation may have	ce. We would like to urge you to ve a negative result on your perf	excel in your work and you ormance.
You are warned against committing any further offence, termination or dismissal, would be meted out.	failing which stricter disciplinary	actions, including up to
CLAIM FOR LOSS/ DAMAGE TO RAMKY PROPERTY		*
This incident would incur an amount of SGD\$ replacement of such lost/ damaged Company Property to neglect or default.	_, payable to the Company, for nat has been issued & entrusted	the purposes of repair/ to you, as a result of your
Please elaborate and provide exact breakdown of reason (attach relevant documents if available)	nable replacement/ repair costs	pelow:
*Delete accordingly		70
0 1 2 1 11	re that the information provide	nd by me in this incident
report is true to the best of my knowledge.	re that the information provide	d by me in this incident
Name & Signature of Injured Workman/ Person invol-	ved in incident	Date
Fong Jia Yuan Zu.		
Name & Signature of Recording Officer/ Supervisor		Date
Name & Signature of Manager		Date

N. Committee	
PAIVE	

Ramky Cleantech Services Pte. Ltd.

PAGE 4 of 4

TITLE: Accident / Incident Reporting Form (Non-Injury)

DOCUMENT NO: Rev No: QHSE-FR-09-05 2

SECTION G: APPROVAL OF SUBMISSION (To be completed by HSE Dept/HOD)

Risk Assessment reviewed? Yes	N/A	
Other comments on accident /recommends	ations:	
Name:	Signature :	Date :
(HSE Department)		
Approve / Rejected.*		
Name: (Head Of Division)	Signature :	Date :

REVISION HISTORY

Revision No.	Revision Date	Reference	Revision Details / Changes		
0	02/01/2015	HSE Procedure 5.4.5(L), QHSE Procedure Sect 9.0	Implementation of form		
1	29/03/2016	RAMKY-QHSE-SP-001 Accident/ Incident Management and Reporting	Revised entire form layout		
2	15/04/2016	RAMKY-QHSE-SP-001 Accident/ Incident Management and Reporting	Amended incident description prompts; Amended list of root causes; Included field for 'Person In Charge' for corrective/ preventive actions; Amended language from deduction of 'monthly salary', to deduction of 'performance allowance'; Added section as provision for claim process - for loss/ damage to Ramky property due to neglect or default		

^{*} Delete as appropriate





better products

KLENCO (SINGAPORE) PTE LTD cleaner environment

info@klenco-asia.com www.klenco-asia.com Service 18, Gul Crescent Singapore 629527 Tel: (65) 6862 3388 Tel: (65) 6861 9613 Fax: (65) 6861 3400 Fax: (65) 6861 7575

COMPANY REGISTRATION NO: 197100402R GST REGISTRATION NO: M2-0011931-2

TKD5000V-0003 TKD5000V-0000 TKDM-5000VEL

HYDRAULIC DUMPING UP TO 2200MM

DULEVO 5000 VELOCE ROAD SWEEPER

STOCK CODE

DESCRIPTION

TKD5000V-0201

TKD5000V-0505

ADDITIONAL VARTEX PRE-FILTER

TKD5000V-0204

TKD5000V-0800

TKD5000V-0907

CONTAINER INSPECTION DOOR

TKD-GE8682

TKD5000V-0701

HYDRAULIC JACK

REFLECTING STRIPES

SPARE TIRE

(NOT ON BOARD

4.00 4.00

UNIT

4.00

TKD5000V-1324 TKD5000V-0705

TKD5000V-2113

ADDITIONAL SIDE CAMERA

CUSTOMER NAME & ADDRESS

HOI HUP BUILDING, RAMKY CLEANTECH SERVICES PTE LTD R01142M TEL: 6876 5400 16 JALAN KILANG #02-01 FAX: 6876 5499 S'PORE 159416

DELIVER TO

24, LOYANG CRESCENT TAN MUNG KHOO SE 508987

HP: MR. 9452 4618

TAX INVOICE

L127194

DATE 01/08/2014

SALESMAN OUR REF RI DL142571 TERMS

30 DAYS

SALES DEPT YOUR REF NO 09

MR DELONE 4100002648

CONTACT NO ORDERED BY CHAN

CENTRALIZED MANUAL GREASING SYSTEM WITHOUT PUMP WATER SPRINKLING EXTENSION FOR FRONT EXTENDALE BRUSH UNIT WATER SPRINKLING SYSTEM FOR SIDE BRUSHES W. 180" RIGHT HAND/LEFT HAND FRONT EXTENDABLE STRAINER FOR DULEVO 5000 DUST CONTAINER BUSH UNIT 425L WATER TANK REF 4.00 4.00 4.00 4.00 4.00 4.00 4.00 4.00 OTY 4.00 MON UNIT UNIT UNIT UNIT UNIT PC 317,880.00 UNIT PRICE 1,271,520.00 AMOUNT

REMARKS

GESW-4163

LED

DIRECTIONAL BLINKING ARROW



klenco (s) Pie Ltd. Goods sold are not refurnable, discrepancies will only be entertainted within 14 days of invoice date. For product warranty policy please refer to our website www.klenco-asia.com. Cheque/s should be crossed and made payable to







better products

cleaner environment

KLENCO (SINGAPORE) PTE LTD

info@klenco-asia.com www.klenco-asia.com Service Tel: (65) 6861 9613 Fax: (65) 6861 3400 18, Gul Crescent Singapore 629527
Office Tel: (65) 6862 3388 Fax: (65) 6861 7575

GST REGISTRATION NO: M2-9011931-2 COMPANY REGISTRATION NO: 197100402R

CUSTOMER NAME & ADDRESS

HOI HUP BUILDING, R01142M TEL: 6876 5400 16 JALAN KILANG RAMKY CLEANTECH SERVICES PTE LTD #02-01 FAX: 6876 5499 S'PORE 159416

DELIVER TO:

MR. 9452 4618 TAN MUNG KHOO

LOYANG CRESCENT

SE 508987

TAX
NV
OICE
111
LI

27194

DATE CONTACT NO ORDERED BY SALES DEPT SALESMAN OUR REF PAGE YOUR REF NO TERMS : MR DELONE CHAN :4100002648 RI DL142571 01/08/2014 30 DAYS

11/1

STOCK CODE	DESCRIPTION	REF	QTY UOM	MOU	UNIT PRICE	AMOUN
TKD5000V-0302	HEAVY DUTY SUCTION SYSTEM WITHOUT HOSE		4.00	PC		
TKD5000V-0305	DIA 150MM HOSE - LENGTH 5 MT		4.00	PC		
	12 x MONTHLY SERVICING, (LABOUR ONLY,			1		
	COST OF PARTS REPLACED NOT INCLUDED.)					
	VINYL STICKER LOGO					
	ADD GST @7.00% FOR 1,271,520.00					2000000

REMARKS



Cheque/s should be crossed and made payable to klenco (s) Pte Ltd. Goods sold are not returnable, discrepancies will only be entertainted within 14 days of invoice date. For product warranty policy. please refer to our website www.ktenco-asia.com

KLENCO (S) PTE LTP

\$3

1,360,526.40 st Private Limited Tel: 87752555

SO-2021-98719

Service Order Date:

01/04/2021



To:

RAMKY CLEANTECH SERVICES PTE LTD

Address:

16 Jalan Kilang #02-01

Hoi Hup Building

Location:

SELF COLLECTION

Attn:

CC:

MR VINCENT HO

Email:

vincent.ho@ramky.com.sg

Phone No.:

6876 5481

Fax No.: -

Model No.:

DULEVO 5000

Running-Hour Meter .:

Serial No.:

5020V00183

Do Number:

Date of Purchase:

Quotation Description.:

RE: TO REPAIR 1 UNIT DULEVO 5000 SWEEPER -YN5689K

I am pleased to quote the following spare parts:-

SN	Item	Description	Qty	UOM	Unit Price	Amount
Need	to Repair :	/				
1	TKD-D65VW00000	ENGINE - DULEVO 5000 C/A X nn	1	PC	59,918.40	59,918.40
2	TKD-D651T00000	ENGINE VIBRATION DAMPING - DU 5000 (TAV7.6/P6>	4	PC	348.20	1,392.80
3	TKD-F043600000	HERMETIC BOX 7. MIS	1	PC	237.90	237.90
4	TKD-4150046STW	ENGINE HYD VALVE ASSY - DU5000 .	1	PC	647.00	647.00
5	TKD-6000046071	TRANSMISSION CONTROL ELECTRO 1000 VALVE	1	PC	1,567.50	1,567.50
6	TKD-6020046GEK	RADIATOR SUPPORT -	1	PC	879.00	879.00
7	TKD-6110046EGP	RUBBER GASKET ?	1	PC	156.00	156.00
8	TKD-6110046ATT	RUBBER GASKET ?	1	PC	77.00	77.00
9	TKD-D73L300000	AIR FILTER ?	1	PC	599.70	599.70
10	TKD-4160046GDI	WIRE HARNESS (CABIN TO ENGINE SWAN / CONTROL BOX) - DU5000	1	PC	3,124.80	3,124.80
11	TKD-6140046BMY	HOSE ?	1	PC	37.00	37.00
12	TKD-AAM0200000	CLAMP?	1	PC	7.00	7.00
13	TKD-C190600000	LIQUID CONTAINER .	1	PC	61.80	61.80
14	TKD-F205000000	CONDENSER + ELECTRIC FAN - DU5000 CAN /	1	PC	1,893.20	1,893.20
15	TKD-6020043211	CONDENSER PLATE SUPPORT TO THE SUPPO	_ 1	PC	38.25	38.25
16	TKD-F201200000	FILTER SUPPORT - DU5000 <tav8.11 p6=""></tav8.11>	1	PC	100.70	100.70
17	TKD-F201000000	DEHYDRATING FILTER - DU5000 3 5 cm/	1	PC	220.40	220.40
18	TKD-F201100000	AIR PRESSURE SWITCH - DU50007 2000 / CTAV8.11/P8>	1	PC	262.00	262.00
19	TKD-C070625020	D25 X 20 SHOCK MOUNT - DU50007? <tav8.11 p13=""></tav8.11>	4	PC	8.30	33.20
20	TKD-E332000000	24V 20A RELAY - DU5000 -	1	PC	109.60	109.60
21	TKD-6170046163	LOWER FRONT PANEL - D5000 <t9.5 p3=""> 2 burn</t9.5>	1	PC	563.70	563.70

KLENCO (SINGAPORE) PTE LTD

SO-2021-98719

Service Order Date:

01/04/2021



better products cleaner environment

		h .		cleaner	environme	110
22	TKD-6170046164	UPPER FRONT PANEL - D5000 <t9.5 p4=""></t9.5>	1	PC	513.90	513.90
23	TKD-C195800000	WASHER - DU5000 7	11	PC	10.80	118.80
24	TKD-C6020046BYF	RH RADIATOR PROTECTION PLATE	1	PC	650.00	650.00
25	TKD-E113200000	SIDE LIGHT - DU5000 <tav11.3 p4=""></tav11.3>	1	PC	74.60	74.60
26	TKD-A150808020	SCREW - DU1100 <tav6.1 p13=""> 7</tav6.1>	4	PC	1.50	6.00
27	TKD-6110046GFW	RELAY BOX RUBBER 1	1	PC	86.50	86.50
28	TKD-4160046BMP	5020V-06 ENG WIRING - DULEVO 5000	1	PC	2,750.60	2,750.60
29	TKD-T0805-1	* OIL FILTER HOSE - DU5000 <tav7.8 p4=""> Zohum</tav7.8>	2	PC	130.20	260.40
30	TKD-T0805-2	* O RING FOR TKD-T0805-1 OIL FILTER 3? HOSE- DU5000 .TAV7.8/P4>	4	PC	6.00	24.00
31	TKD-D6501X0000	FILTER, FUEL WATER SEPARATOR	1	PC	76.50	76.50
32	TKD-6000046864-1	* FUEL HOSE - DU5000 <tav7.8 p7=""></tav7.8>	5	PC	24.00	120.00
33	TKD-6140046131Q	FUEL HOSE 7 NUC	1	PC	116.50	116.50
34	GESW	HYDRAULIC HOSES 7	1	LOT	5,000.00	5,000.00
35	TKD-C39B90000	GASKET 7	1	PC	22.00	22.00
36	TKD-6000046122	## 13/32" CONDITIONER HOSE - DU50007 CTAV8.12/P4>	1	PC	306.10	306.10
37	TKD-6140046BQE	5/16" HOSE - DU5000 <tav8.12 p5=""></tav8.12>	1	PC	140.20	140.20
38	TKD-6000046123	1/2" CONDITIONER HOSE - DU5000	1	PC	438.10	438.10
39	TKD-F201700000	5/16" HOSE - DU5000 <tav8.12 p11=""> 7</tav8.12>	1	PC	342.60	342.60
40	TKD-D68G800000	WATER REGULATION VALVE ?	1	PC	1,212.40	1,212.40
41	TKD-E177500000	UREA TEMPEARTURE AND LEVEL 7 INDICATOR	1	PC	2,777.80	2,777.80
42	TKD-E633100000	DUMP SENSOR ?	1	PC	2,748.90	2,748.90
43	TKD-6140046FYD	INLET INJ HOSE, UREA DENOX - DU5000 . <tav8.10.1 p8=""></tav8.10.1>	1	PC	671.00	671.00
44	TKD-6140046FYE	RETURN INJECTOR UREA DENOX HOSE - DU5000 (TAV8.10.1/P6)	1	PC	637.50	637.50
45	TKD-E344600000	DENOX AREA CONTROL AMP	1	PC	9,485.00	9,485.00
					1	100,506.35
	1	ess 20.00% for 100,506.35				20,101.27
		TO DEPOS OF THE PROPERTY OF TH			S	80 405 08

80,405.08

Repair Labour Charge

TO DISMANTLE & REINSTALL ENGINE. CHANGE OTHER DAMAGED PARTS. TO REPLACE WIRE HARDNESS & TO RECTIFY AIR-CON SYSTEM FAULTY. CHANGE DAMAGED PARTS. TO RECTIFY AD-BLUE SYSTEM FAULTY. CHANGE DAMAGED PARTS. TO RECTIFY HYDRAULIC SYSTEM FAULTY. CHANGE HYDRAULIC HOSES & DAMAGED PARTS.

2240

SO-2021-98719

Service Order Date:

01/04/2021



better products cleaner environment

				Cicaric	CHVIIOIIIIC	10
	S	Sub Total				83,205.0
				Ord	er Confirmation	
				Name / Signatur	e / Comp Stamp /	Date
	A Company of the Comp			realite / Olgitatal	e / comp ctamp /	Date
wear 1	& Tear Items : TKD-6276141687	RH, RUBBER SLIDE HOLDER , SIDE 3 7 BRUSH - DULEVO 5000	1	PC	393.40	393.4
2	TKD-6276141686	LH, RUBBER SLIDE HOLDER, SIDE BRUSH 2 ?	1	PC	393.40	393.4
3	TKD-5040042957	## (5040042957-1) RH SIDE SLIDE- DU 500027 <tav1.1 p32=""></tav1.1>	1	PC	664.10	664.1
4	TKD-5040042956	## (5040042956-1) LH SIDE SLIDE- DU 5000 3 ? <tav1.1 p32=""></tav1.1>	1	PC	664.10	664.1
5	TKD-6177760528	ANTIDUST PACKAGE, LWR CONVEYOR - 27 DU5000 <t2.2 p18=""></t2.2>	1	PC	137.70	137.7
6	TKD-6110046FCL	SIDE GASKET, LOWER CONVEYOR - 37 DU5000 <tav2.2 p25=""></tav2.2>	2	PC	53.30	106.6
					-	2,359.
	L	Less 20.00% for 2,359.30			-	471.8
						1,887.4
	V	Vear & Tear Labour Charge				280.0
		O DISMANTLE & REPLACE MAIN BRUSH SKIRT & SIDE	SLIDES	. ?		
	S	Sub Total			-	2,167.4
				Ord	er Confirmation	
				Name / Signatur	e / Comp Stamp /	Date
Drovo	ntive Maintenance :		_			
1	TKD-GE8481	* ENGINE OIL, 15W40, CI-4 (PER LITRE) A	15	LIT	6.20	93.0
2	TKD-D73P300000	HYDRAULIC OIL FILTER CARTRIDGE - DULEVO 5000	1	PC	561.60	561.6
3	TKD-D6501A0000-1	me-/	1	PC	273.00	273.0
4	TKD-D800900000-1	* ENGINE AIR FILTER - DU5000 MIL	1	PC	130.00	130.0
5	TKD-GE8471	* DIFFERENTIAL Gear Oil SAE80W, GL-4 X	11	LIT	12.80	140.8
6	TKD-D6501X0000	FILTER, FUEL WATER SEPARATOR	1	PC	76.50	76.
7	TKD-GE8681	* HYDRAULIC OIL, ZS-68 (PER LITRE)	120	LIT	6.20	744.0
8	TKD-D651U00000	FUEL FILTER - DULEVO 5000 MM	1	PC	81.70	81.7
9	GE8502	RADIATOR COOLANT (0.5 LITRE)	4	TIN	4.20	16.8

SO-2021-98719

Service Order Date:

01/04/2021



2,117.40 Less 20.00% for 2.117.40 423.48 1,693.92 Preventive Labour Charge 280.00 TO CHANGE HYDRAULIC OIL & FILTERS.CHANGE GEAR OIL. Sub Total 1,973.92 Order Confirmation Name / Signature / Comp Stamp / Date 0.00 Transport Charge Total SGD Excl. GST \$87,346.44 7% GST 6,114.25 Total SGD Incl. GST 93 460 69

Remarks:

The above quotation are only the estimated cost of repair. An additional works and parts be required during the course of repair, a supplementary quote will be submitted. We trust that the above quotation is acceptable

to you. Machine will be disposed without further notice if no confirmation from customer is received after 3

months from date of quotation.

Charges:

As work has to be carried out to determine the fault, a minimum service charge of S\$60.00 per set for

Commercial Equipment and \$\$150.00 per set for Industrial Equipment inclusive of transportation charge will be

levied if the quotation for the repair/service is not accepted.

Validity:

validity: 30 days

Quoted By: Huang Bing Approved By:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

14 days EXCESS:TBA 27/04/21 @ 1520 Rever Roas before paper

KLENCO (SINGAPORE) PTE LTD

18 Gul Crescent, Singapore 629527 * Tel: (65) 6861 9613 / 8721 * Fax: 6861 3400 * Email: service@klenco-asia.com (Service Dept) Company Registration No.: 197100402R