

AIR ESTIMATE*

VEHICLE NO SHA7743T

25/03/21

MAKE :

CHIANG/CHINA

MODEL IONIQ G

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER		de \$459.40
2	REAR BUMPER SIDE BRACKET RH /LH		\$55.80 ? \$111.60
10	REAR BUMPER CLIPS		na ✓ \$22.00
1	REAR BUMPER REINFORCEMENT		cur ✓ \$394.80
2	REAR BUMPER REINFORCEMENT BRACKET LH/RH		\$138.10 ? \$276.20
1	BOOTLID		bt ✓ \$2,480.40
1	BOOTLID TRIMBOARD		? \$343.90
2	BOOTLID HINGE LH/RH		\$31.30 R ✓ \$71.30
1	BOOTLID LOCK UPPER		? \$224.00
1	BOOTLID H EMBLEM		na ✓ \$28.00
1	BOOTLID HYBRID		na ✓ \$24.30
1	BOOTLID LONIQ		na ✓ \$31.30
2	BOOTLID LAMP LH /RH		cur ✓ \$794.40 \$1,588.80
1	BOOTLID UPPER GLASS		X \$907.20
1	BOOTLID LOWER GLASS		X \$584.90
2	TAIL LAMP LH/RH		\$870.40 ? \$1,740.80
1	REAR BUMPER CENTRE MOULDING		de ✓ \$451.25
1	REAR BUMPER LOWER MOULDING		? \$155.00
1	REAR TOW HOOK COVER		X \$94.60
1	REAR BUMPER FOG LAMP		? \$201.50
2	NUMBER PLATE LAMP LH/RH		\$85.30 ? \$170.60
1	REAR BUMPER CENTRE UNDER COVER		? \$123.85
1	REAR END PANEL		bt ✓ \$532.00
1	REAR PANEL GARNISH		de ✓ \$346.80
2	REAR BUMPER REFLECTOR LH /RH		\$41.45 X \$82.90
1	BLIND SPOT RADAR		? \$125.00
1	ANTENNA ASSY -SMART		? \$40.50
1	REAR BUMPER TOW COVER		X \$98.80
SUB TOTAL			\$11,711.70
20.00%			\$2,342.34
DISCOUNTED TOTAL			\$9,369.52
1	REAR NUMBER PLATE/W HOLDER		X \$55.00
1	REAR REVERSE SENSOR		na ✓ \$180.00
1	BOOTLID APP LOGO STCKER		na ✓ \$40.00
2	BOOTLID COMFORT LOGO/TEL NO. STICKER		na ✓ \$60.00
Labour Charge			\$335.00
Panel Beating			750 \$1,400.00
Spray Painting Charge			750 \$1,000.00
Check wiring			\$0. \$60.00
Diagnose/reset erase fault code			Report, 150 ? \$240.00
Tuff Kote			30 \$120.00
Remove/refix Reverse sensor			30 \$60.00

ESTIMATE TOTAL

\$12,584.52

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanphir 97495744 MIC

'WP' 26/3/71 @ 12pm

P/P Resurvey before paint.

3-4 days.

Tanphir @ McAnbrown

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 25.03.2021 15:48 Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305460503

STOMER

VMS COMFORT TRANSPORTATION PTE LTD

STOMER NO. 7010045

DRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717

(R) 65508755 (O)
(P)

ICOUNT CARD NO.

REGN NO.:

SHA7743T

MILEAGE

MAKE :

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G3)

DATE/TIME IN

25.03.2021 14:10

YR OF MANU.

30.09.2020

TARGET DATE

CHASSIS CODE

KMHC851CVLU189609

COMPLETION DATE/TIME:

JOB DESCRIPTION


Accident Date: 25.03.2021

NATURE: 3P 25.03.2021

S/NO

LABOR CODE

DESCRIPTION



ECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

nowledgement Slip

Exit Pass

e No.: SHA7743T

CHIANG

Vehicle No.:

SHA7743T

of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard