

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Page No.:1 of 1

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT SOMPO INSURANCE SINGAPORE PL CS3/SMO21004195/Uqf3e2 Ref: 50 RAFFLES PLACE #03-03 SINGAPORE LAND Date: 23/04/2021 **TOWERSINGAPORE 048623** Code: SMO 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. YK 9372M SJK 5547E Veh. Inspected Policy No. D20MTPCVE001972 Coverage (\$) 0.00 Claim No. CMTD2100927/GPL Excess (\$) 0.00 **GRACE TEO Assign Date** 01/04/2021 Assign From **Vehicle Particulars & Condition** 2. HONDA FREED (A) 1496 Make & Model C.C HIDDEN 2008 Engine No. Year of Reg. GB31023367 **MAROON** Chassis No. Colour Odometer 232143 KM Steering IN ORDER **IN ORDER** SPORTS RIM **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 205/50Z R16 WINDFORCE 6 mm WINDFORCE L/H Front Tyre 205/50Z R16 6 mm 205/50Z R16 WINDFORCE R/H Rear Tyre 6 mm WINDFORCE L/H Rear Tyre 205/50Z R16 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. 5. **General Information** 24/03/2021 09/04/2021 (10:00 AM) **Accident Date** Inspect Date / Time 25 kaki bukit rd 4 #08-43 Synergy@KB Singapore 417 Survey held at Repairer TRIPLE-T AUTOMOBILE 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000

Report Ref No. CS3/SMO21004195/Uqf3e2

Estimate Days of Repair

Inspected By

ESTIMATED NORMAL PERIOD FOR REPAIR:

5b.

CHUA KANG SENG Licensed Appraiser K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

5 Working Days

REGD Auto Consultant-SAE, Licensed Appraiser