

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 1235C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	COVER, RR BUMPER ASSY (DISC 25%)	DEFORMED	423.90	317.93
2	PAD, RR BUMPER, RH & LH, 1 @\$3.80 (DISC 25%)	NECESSARY	7.60	5.70
2	PAD, RR BUMPER, RH & LH, 2 @\$3.80 (DISC 25%)	NECESSARY	7.60	5.70
2	PAD, RR BUMPER, RH & LH, 3 @\$3.80 (DISC 25%)	NECESSARY	7.60	5.70
3	PAD, RR BUMPER, CTR @\$2.20 (DISC 25%)	NECESSARY	6.60	4.95
10	CLIPS PIECE, FRT & RR BUMPER @\$1.50 (DISC 25%)	NECESSARY	15.00	11.25
1	GUARD, RR BUMPER, LOWER (DISC 25%)	SCRATCHED	558.30	418.73
1	REAR BUMPER REINFORCEMENT (DISC 25%)	BENT	318.80	239.10
1	COVER, REAR FLOOR UNDER CENTER (DISC 25%)	DEFORMED	222.60	166.95
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	SENSOR REVERSE (SN)	SHORTED	180.00	180.00
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	318.80	-
1	SEAL, RR BUMPER ARM, RH & LH	SERVICEABLE	11.00	-
1	RETAINER, RR BUMPER, RH	SERVICEABLE	112.70	-
1	RETAINER, RR BUMPER, LH	SERVICEABLE	111.50	-
1	SEAL, RR BUMPER, RH	SERVICEABLE	85.20	-
1	SEAL, RR BUMPER, LH	SERVICEABLE	85.20	-
1	FILLER, RR BUMPER, RH	SERVICEABLE	119.90	-
1	FILLER, RR BUMPER, LH	SERVICEABLE	119.90	-
1	COVER, GUARD RR BUMPER LOWER	SERVICEABLE	14.80	-
1	ANTENNA, ELECTRICAL KEY	SERVICEABLE	60.30	-
1	LENS & BODY, REAR COMBINATION LAMP, RH	SERVICEABLE	438.10	-
1	LENS & BODY, REAR COMBINATION LAMP, LH	SERVICEABLE	438.10	-
1	LENS & BODY ASSY, RH BUMPER, RH	SERVICEABLE	486.80	-
1	LENS & BODY ASSY, RR BUMPER, LH	SERVICEABLE	486.80	-
1	COVER, REAR FLOOR UNDER, RH	SERVICEABLE	169.50	-
1	COVER, REAR FLOOR UNDER, LH	SERVICEABLE	234.30	-
1	COVER, REAR FLOOR UNDER CENTER	SERVICEABLE	222.60	-
1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB	SERVICEABLE	891.20	-

Report Ref No. NS/INC21004196/Qqce2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





Page No.:2 of 2

1,700.00

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	NAME PLATE (HYBRID), LUGGAGE COMPARTMENT	SERVICEABLE	52.30	-
1	NAME PLATE (PRIUS), LUGGAGE COMPARTMENT	SERVICEABLE	52.30	-
1	SMRT LOGO	SERVICEABLE	7.80	-
1	STICKER DECAL 6555 8888	SERVICEABLE	21.60	-
1	END PANEL SUB-ASSY, BODY LOWER BACK	SERVICEABLE	629.80	-
1	SEALANT SIKAFLEX	SERVICEABLE	37.00	-
			7,075.50	1,476.01
	<u>LABOUR</u>			
	PANEL BEATING & BODY WORK.		707.00	300.00
	SPRAY PAINT.		1,478.00	300.00
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	30.00
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			2,545.00	650.00
	GRAND TOTAL		9,620.50	2,126.01

(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)

Report Ref No. NS/INC21004196/Qqce2

RECOMMENDED COST OF LUMP SUM REPAIRS

Jæ

OI SUN PIN

Asst. Automotive Assessor

1

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser