

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21004208/APS3Q2
Date: 12/07/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900010510
Claimant Vehicle No :	GBG3346Y	Insured Vehicle No :	SMJ133T
Date of Loss:	31/03/2021	Nature of Claim:	TP
		Claim No:	4295819767SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG3346Y		
Make & Model:	SUZUKI EVERY, 660cc GA (M)	Engine No:	R06A1991551
Reg. Date:	21/07/2017 (Man. Year: 2016)	Chassis No:	DA17V813423
Colour:	Black	Odometer:	60950 km
Engine Capacity:	658 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	155 R12C	Rear Tyre Size:	155 R12C
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,846.78	1,156.92	689.86	37.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,700.00	910.00	790.00	46.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,546.78	2,066.92	1,479.86	41.72
Approved Total (Overridden) (S\$)		1,650.00		

(S\$)	3,546.78	1,650.00	1,896.78	53.48
+ GST 7.00/7.00% (S\$)	248.27	115.50	132.77	53.48
Nett Amount (S\$)	3,795.05	1,765.50	2,029.55	53.48
+ Loss of Use (3.0 x S\$80.00/day) (S\$)		240.00		
(S\$)		2,005.50		
Liabie Amount (50.00%) (S\$)		1,002.75		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,004.75		
Global Sum Settlement (S\$)		1,000.00		

INSPECTION

Date of Assignment: 15/04/2021

Date Inspected: 15/04/2021

Inspected At:

Modern Automotive Pte Ltd (HQ)
 Blk 3023A Ubi Road 1, #01-61 & #01-58
 Singapore 408717

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	685.60 FL	*685.60 FL
2	1		*FRONT BUMPER SIDE HOLDER -LH	Necessary	25.00 FL	*25.00 FL
3	1		*FRONT FEDER -LH	Repair	495.40 FL	*- FL
4	1		*FRONT FENDER INNER SHIELD -LH	Not Necessary	123.60 FL	*- FL
5	1		*HEAD LAMP -LH	Cut	544.60 FL	*544.60 FL
6	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
7	1		*SET FRONT FENDER INNER SHIELD CLIPS -LH	Not Necessary	30.00 FS	*- FS
8	1		*FRONT WHEEL RIM CAP -LH	Cut	100.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,034.20	1,345.20
- List Item Discount on L Items 10.00/15.00% (\$)	187.42	188.28
Total Parts (\$)	1,846.78	1,156.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCKING & PULL OUT FRONT PORTION & RENEW ABOVE PARTS	New	700.00	400.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	800.00	400.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
Gross Labour Cost (\$\$)			1,700.00	910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >