

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21004212/QTF3E2

Date: 13/04/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070143174
Claimant Vehicle No :	FBH8964A	Insured Vehicle No :	GBK6710M
Date of Loss:	26/03/2021	Nature of Claim:	TP
		Claim No:	8383040087SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBH8964A	Engine No:	M356M1005242
Make & Model:	APRILIA SR MAX 300, 278cc CVT	Chassis No:	ZAPM3560001004924
Reg. Date:	30/10/2013 (Man. Year: 2013)	Odometer:	93420 km
Colour:	White		
Engine Capacity:	278 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	140/70-14	Rear Tyre Size:	140/70-14
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	01/04/2021		
Date Inspected:	01/04/2021	Inspected At:	Owner House Sembawang Canberra Crescent Singapore 75119
Estimated Period of Repair:	3.0 days		

Adjuster: OI SUN PIN

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

NOTE: OWNER HAVE NOT DECIDE ON REPAIR SHOP

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER WHEEL GUARD	Scratched	0.00 F	*- F
2	1		*FRONT LH SIGNAL LAMP	Scratched	0.00 F	*- F
3	1		*FRONT RH SIGNAL LAMP	Crumpled	0.00 F	*- F
4	1		*HAND BRAKE LEVER	Bent	0.00 F	*- F
5	2		*SIDE FAIRING FRONT LH / RH	Crumpled	0.00 F	*- F
6	2		*SIDE FAIRING INNER GARNISH LH / RH	Crumpled	0.00 F	*- F
7	1		*REAR FAIRING RH	Scratched	0.00 F	*- F
8	2		*LH / RH REAR STEP BOARD GARNISH	Scratched	0.00 F	*- F
9	1		*REAR LOWER FAIRING LH	Scratched	0.00 F	*- F
10	1		*REAR ENGINE COVER	Crumpled	0.00 F	*- F
11	1		*REAR ENGINE COVER (BIG)	Scratched	0.00 F	*- F
12	1		*REAR FOOT REST RH	Scratched	0.00 F	*- F
13	1		*EXHAUST MUFFLER COVER	Crumpled	0.00 F	*- F
F=Franchise part.						
					Total Parts (\$\$)	0.00 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >