A-PAC Adjusters & Surveyors Pte Ltd

A-PAC

Company Registration No.: 201705143H 28 Sin Ming Lane #06 - 141, Midview City, Singapore 573972 Tel: +65 6904 4922 Fax: +65 6904 4922

VEHICLE SURVEY REPORT

De Rozario Dennis Dominic C/O: JEC Auto Service Pte Ltd

1 Kaki Bukit Ave 6 #02-11 Autobay @ Kaki Bukit Singapore 417833

Our Ref

: JEC/TP/21-03001

Date

: 30/4/2021

REFERENCE

Vehicle No Claim Type : SLU 2847 H

: Third Party

Date of Accident

Survey Date

: 30/3/2021

: 1/4/2021

DESCRIPTION & IDENTIFICATION OF THIRD PARTY

Make & Model

: Honda Vezel Hybrid 1.5X

Engine No Chassis No : 28/11/2017

: LEB5959970 : RU31259953

Registration Date

Sum Insured (S\$)

: 1496 cc

Colour

: Red

Engine Capacity Odometer

: 63878

: Market Value/New Car Price

: 72,800.00 Market Value (S\$) COE/PARF Rebate (S\$) : 41,702.00

CONDITION OF VEHICLE

General Condition

: Good

: Serviceable

Modification Air-Conditioner : No : Yes

Steering Audio Player

· Yes

Seat Belts Footbrake : Yes

Handbrake

: Serviceable

: Serviceable : Good

Wing Mirror

: Yes

Paint Work

CONDITION OF TYRES (The below values represent the remaining tyre treads depth) Front Tyre Size

: 205/60/R16

Rear Tyre Size

: 205/60/R16

Front Left Side

: Good Year 7mm

Rear Left Side Rear Right Side : Good Year 7mm

Front Right Side

: Good Year 7mm

: Good Year 7mm

GENERAL DESCRIPTION OF DAMAGE


The inspected vehicle sustained damage at the REAR portion.

The damages observed during our survey were generally at the tailgate, rear bumper, rear floor panel, rear end panel, tailagate lamp left & right, and among other parts were affected.

All stated damage is subject to the consistency of the accident reports.

The Hybrid Lithium battery pack was affected adversely. Error Messages as attached

This survey was conducted strictly on a 'Without Prejudice' basis, and we have not authorised any repair.





Our Ref : JEC/TP/21-03001

Assessor's Recommendation

Workshop's Estimate (S\$)

Parts : 35,333.36 Special Nett Items : 1,650.00 Labour : 8,900.00

GST (7.00%)

Total

: -: 45,883.36 Adjuster's Adjustment (S\$)

Parts : 26,737.96 Special Nett Items : 1,110.00 Labour : 5,880.00

GST (7.00%)

Total : 33,727.96

•

: -

JEC Auto Service Pte Ltd estimated a repair cost of \$\$45,883.36. We had adjusted it to \$\$33,727.96. We would like to recommend that the repair cost would therefore be at SGD 33,727.96 on a Part by Part basis.

The repairs would require a period of 15.0 working days.

Surveyed By

: Patrick Favacho
AMME

Report Prepared By

: Patrick Soo Director

A-PAC

Our Ref : JEC/TP/21-03001

					The state of the s	2/17/21-03001
RECON	MEN	DED PAR	TS TS		Workshop	Adjusted
No.	Qty	The second second	. Descriptions	Condition	Estimate	Cost
1	1		TAILGATE	Dented	1,580.00	1,210.00
2	1	_	TAILGATE OUTER GARNISH	Cracked	455.00	395.00
3	1	-	TAILGATE TOP SPOILER HE MAN	Cracked	525.00	438.80 ×
4	1	-	TAILGATE " HONDA " LOGO	Necessary	86.00	68.30
5	1		REAR EMBLEM - VEZEL	Necessary	89.00	78.00
6	1	_	REAR EMBLEM - HYBRID	Necessary	83.00	66.20
7	1	2	REAR WINDSCREEN	Shattered	1,810.00	1,650.30
8	1	_	REAR WINDSCREEN MOULDING	Necessary	225.00	187.50
9	1	_	TAILGATE WEATHERSTRIP	Cut	238.50	195.50
10	1	¥ .	TAILGATE INNER TRIM	Cracked	553.80	453.50 28 5
11	1	2	TAILGATE DAMPER LH	Bent	231.00	180.00
12	1	-	TAILGATE DAMPER RH	Bent	231.00	180.00
13	1	-	TAILGATE HINGE IH 2	Bent	175.00	110.50 ⊀
14	1	•	TAILGATE HINGE RH	Bent	175.00	110.50 X
15	1	_	WINDSCREEN WIPER MOTOR	Malfunctioned	295.50	205.00
16	1		WINDSCREEN WIPER ARM	Bent	125.00	80.00
17	1	-	REAR BUMPER	Deformed	1,315.00	925.80 880
18	1	-	REAR BUMPER SIDE PANEL LH	Deformed	385.00	275.00 185
19	1	_	REAR BUMPER SIDE PANEL RH	Deformed	385.00	275.00 185
20	1	SV PAG	REAR BUMPER SIDE RETAINER LH	Cracked	71.50	55.70
21	1	-	REAR BUMPER SIDE RETAINER RH	Cracked	71.50	55.70
22	1	-	REAR BUMPER REFLECTOR LH	Holder Cracked	263.00	210.50
23	1	-	REAR BUMPER REFLECTOR RH	Holder Cracked	263.00	210.50 141,
24	1	(=)	REAR END PANEL	Dented/Bent	715.00	535.50
25	1	-	REAR END PANEL GARNISH	Cracked	255.00	175.40
26	1	-	REAR FLOOR PANEL	Bent/Dented	1,551.40	1,108.50
27	1		REAR FENDER INNER TRIM LH	Cracked	515.80	412.50 332
28	1	.=	REAR FENDER INNER TRIM RH	Cracked	515.80	412.50 333
29	1	-	REAR BUMPER LOWER GARNISH	Deformed	488.00	421.00 . 285
30	1	-	REAR TOOL COMPARTMENT TRAY	Cracked	258.90	167.50
31	1	-	REAR TAILGATE LAMP LH	Cracked	688.00	515.30
32	1	_	REAR TAILGATE LAMP RH	Cracked	688.00	515.30 413
33	1	_	REAR TAILLAMP LH	Cracked	635.50	476.60
34	1		REAR TAILLAMP RH	Cracked	635.50	476.60
	1		REAR NUMBER PLATE LAMP LH	Necessary	69.80	47.50
35			REAR NUMBER PLATE LAMP RH	Necessary	69.80	47.50
36	1	-	REAR REVERSE CAMERA	Malfunctioned	800.00	629.20 380 (sw)
37	1	-	REAR SHOCK ABSORBER LH The New	Bent	338.00	237.00
38	1	-	REAR BUZZER	Malfunctioned	255.60	144.50 85
39	1	-	REAR ANTENNA SENSOR	Malfunctioned	242.60	175.50
40	1		REAR TAILGATE LOCK ASSY	Bent	213.00	188.50
41	1	-		Bent	95.00	65.00
42	1	-	REAR TAILGATE LOCK STRIKER REAR EXHAUST HEAT SHIELD	Bent	225.00	125.00 88
43	1			Bent	1,215.00	755.30 518
44	1	-	REAR EXHAUST CENTER PIPE	Bent	895.00	599.00
45	1	-	INC. III CAN III CON CONTRACTOR C	Bent	254.00	185.00- 100((1)
46	1	-	REAR EXHAUST MUFFLER CHROME TIP	Buckled	1,315.00	931.80 🗶
47	1	-	REAR FENDER RH Penis	Duckleu	1,313.00	7

A-PAC

Our Ref : JEC/TP/21-03001

ECON	MEN	DED PAR	rs	EL LA SERVICIO DE LA COMPANION	Workshop	Adjusted
Vo.	Qty	Part No.	Descriptions	Condition	Estimate	Cost
48	1	-	REAR FENDER LH	Buckled	1,315.00	931.80
49	1	-	REAR WHEEL ARCH GARNISH LH	Cracked	295.00	235.00
50	1	-	REAR WHEEL ARCH GARNISH RH	Cracked	295.00	235.00
1	1	-	REAR AIR VENT LH	Cracked	88.00	63.00
2	1	-	REAR HYBRID BATTERY TOP PROTECTOR COVER	Cracked	432.60	315.45
3	1	-	REAR HYBRID BATTERY COOLING FAN ASSY	Cracked	715.00	590.00
54	1	-	REAR HYBRID BATTERY CONTAINER BOX	Cracked	365.00	266.80
55	1	-	REAR HYBRID BATTERY PACK ASSY - LITHIUM ION	Shorted	15,800.00	12,300.00 50
56	1	-	REAR HYBRID BATTERY AIR VENT ASSY -LONG	Deformed	384.60	280.60
7	1	-	REAR HYBRID BATTERY AIR VENT ASSY -SHORT	Deformed	150.00	80.00
8	1	3. = 1	REAR HYBRID BATTERY MOTHER BOARD	Shorted	1,180.00	735.00
9	1	-	REAR HYBRID DISTRIBUTOR HUB	Shorted	580.00	425.00
			15836.15 S-N	5480		
			10000 0 210	Sub Total (S\$):		33,422.45
			1268.82	Discount (20%):	8,833.34	6,684.49
			7000 12	Total Parts (S\$):	35,333.36	26,737.96

RECOMMENDED SPECIAL NETT ITEMS						Workshop	Adjusted
No.	Qty	Part No.	Descriptions		Condition	Estimate	Cost
1	1SET	-	REAR BUMPER CLIPS		Necessary	100.00	50.00 3
2	1SET		REAR FENDER CLIPS		Necessary	100.00	50.00
3	1	_	REAR CAMCORDER CAMERA		Necessary	600.00	400.00
4	1	-	REAR REVERSE SENSOR		Necessary	550.00	450.00 200
- 37	1	_	REAR WINDSCREEN SEALANT		Necessary	150.00	80.00-60
5	1		REAR NUMBER PALTE WITH CASING	0)	Cracked	150.00	80.00-60
6	1	-	REAR NOWIDER PALTE WITH CASING	MM	OT GOTTON		
				000	Sub Total (S\$):	1,650.00	1,110.00

RECOMIN	IENDED LABOUR	Workshop	Adjusted
No.	Descriptions	Estimate	Cost
	LABOURITEMS		10
1	TO REPLACE, REFIX AND PANEL BEAT THE ACCIDENT AFFECTED AREAS.	2,800.00	2,100.00 /80
2	TO VACUUM AND REMOVAL DEBRIS.	350.00	220.00 /00
3	TO REMOVE AND REFIX UPHOLSTERY TO FACILITATE REPAIRS.	350.00	250.00
4	TO REMOVE AND REFIX REAR EXHAUSY ASSY.	500.00	350.00 80
5	TO REMOVE AND REFIX FUEL TANK TO FACILITATE REPAIRS.	250.00	150.00 8
6	TO REMOVE AND REFIX REAR WINDSCREEN.	250.00	180.00-124
7	TO REMOVE AND REFIX REAR LEFT UNDERCARRIAGE.	450.00	220.00 *
8	TO REMOVE AND REFIX NEW SET OF LITHIUM BATTERY.	350.00	250.00
9	TO DIAGNOSE ON THE MEMORY AND RESET THE HEADLAMP FOCUS.	550.00	350.00 /50
10	TO REMOVE AND ADJUST HEADLAMP ASSY AND CHECK WIRING.	250.00	60.00 30
11	TO REMOVE AND REFIX REAR CAMERA AND REAR CAMCODER CAMERA.	350.00	150.00 /00
12	TO REMOVE AND REFIX REAR REVERSE SENSOR.	200.00	80.00 50
13	TO APPLY ANTI TUFF-KOTE ON THE ACCDENET AFFECTED AREAS.	250.00	120.00
	PAINTWORK LABOUR		
1	TO SPRAY PAINTING ON THE AFFECTED AREA.	2,000.00	1,400.00
	Total Labour (S	\$): 8,900.00	5,880.00

A-PAC

Our Ref : JEC/TP/21-03001

OST OF	CLAIMS		Workshop	Adjusted		
			Estimate	Cost		
1	PARTS		35,333.36	26,737.96		
2	SPECIAL NETT ITEMS		1,650.00	1,110.00		
3	LABOUR		6,900.00	4,480.00		
4	PAINTWORK LABOUR		2,000.00	1,400.00		
		Gross Total (S\$) :	45,883.36	33,727.96		
		GST 7.00% (S\$):	-			
		Total Amount (S\$):	45,883.36	33,727.96		

total: 23478.52 45: 18.7K.

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: