

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21004216/AVCE2

Date: 08/09/2021

REFERENCE

Insured/Claimant:	TAY CHING HOCK	Policy No:	1900173682		
Date of Loss:	31/03/2021	Nature of Claim:	OD	Claim No:	6510009842SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP9739E		
Make & Model:	AUDI A6, 2.0 TFSI (A)	Engine No:	DLH065560
Reg. Date:	24/10/2019 (Man. Year: 2019)	Chassis No:	WAUZZZF29LN016034
Colour:	White	Odometer:	28856 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$177,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R19	Rear Tyre Size:	245/45 R19
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	55,295.00	35,531.52	19,763.48	35.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	18,744.00	11,254.00	7,490.00	39.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	74,039.00	46,785.52	27,253.48	36.81
- Excess (S\$)	1,600.00	1,600.00	0.00	0.00
(S\$)	72,439.00	45,185.52	27,253.48	37.62
+ GST 7.00/7.00% (S\$)	5,070.73	3,162.99	1,907.74	37.62
Nett Amount (S\$)	77,509.73	48,348.51	29,161.22	37.62

INSPECTION

Date of Assignment:	01/04/2021		
Date Inspected:	01/04/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	14.0 days		

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	2,832.00 FS	*2,265.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	650.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT - CTR	Cracked	222.00 FS	*177.60 FS
4	2		*FRONT BUMPER ADAPTER - LH / RH	Not Necessary	78.00 FS	*- FS
5	2		*FRONT BUMPER REINFORCEMENT - LH / RH	Not Necessary	222.00 FS	*- FS
6	1		*FRONT BUMPER LOWER GRILLE - CTR	Deformed	153.00 FS	*122.00 FS
7	1		*FRONT BUMPER LOWER CLOSING ELEMENT	Not Necessary	210.00 FS	*- FS
8	1		*FRONT BUMPER SPOILER	Not Necessary	252.00 FS	*- FS
9	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	868.00 FS	*- FS
10	2		*FRONT BUMPER OUTER AIR GUIDE - LH / RH	Not Necessary	58.00 FS	*- FS
11	2		*FRONT BUMPER INNER AIR GUIDE - LH / RH	Not Necessary	42.00 FS	*- FS
12	1		*FRONT RADIATOR GRILLE	Smashed	2,217.00 FS	*1,773.60 FS
13	1		*FRONT RADIATOR GRILLE COVER	Damaged	54.00 FS	*43.20 FS
14	1		*FRONT RADIATOR COVER CAP	Damaged	89.00 FS	*70.96 FS
15	1		*FRONT RADIATOR BRACKET	Damaged	93.00 FS	*74.32 FS
16	1		*FRONT RADIATOR SECURING PLATE	Damaged	84.00 FS	*66.72 FS
17	1		*FRONT CAMERA	Cut	906.00 FS	*724.80 FS
18	1		*FRONT CAMERA ADAPTER CABLE	Not Necessary	416.00 FS	*- FS
19	1		*FRONT CAMERA FLAT CONNECTOR BRACKET	Not Necessary	14.00 FS	*- FS
20	1		*FRONT CAMERA CONNECTOR HOUSING BRACKET	Not Necessary	28.00 FS	*- FS
21	1		*SET FRONT BUMPER WIRING	Not Necessary	577.00 FS	*- FS
22	4		*FRONT PARKING AID SENSOR	Not Necessary	1,074.00 FS	*- FS
23	1		*FRONT PARKING AID SENSOR ASSIST	Not Necessary	268.00 FS	*- FS
24	6		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	21.00 FS	*- FS
25	1		*FRONT BUMPER FOAM FILLER PIECE	Deformed	226.00 FS	*180.40 FS
26	1		*FRONT BUMPER CARRIER	Bent	1,012.00 FS	*809.60 FS
27	6		*FRONT BUMPER POP RIVERT	Necessary	5.00 FS	*3.84 FS
28	2		*FRONT BUMPER SUPPORT	Cracked	59.00 FS	*47.20 FS
29	2		*FRONT BUMPER BRACKET - LH / RH	Cracked	108.00 FS	*86.40 FS
30	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Damaged	88.00 FS	*70.24 FS
31	1		*FRONT BUMPER COVER	Cracked	126.00 FS	*100.40 FS
32	1		*WARNING SIGN	Necessary	30.00 FS	*24.00 FS
33	1		*AIR CONDITIONER STICKER	Necessary	8.00 FS	*5.68 FS
34	2		*FRONT FANFARE HORN - HIGH / LOW TONE - LH / RH	Not Necessary	432.00 FS	*- FS
35	2		*FRONT FANFARE HORN SPRING SHACKLE	Not Necessary	94.00 FS	*- FS
36	2		*FRONT FENDER - LH / RH	O/S Cracked / N/S Buckled	2,936.00 FS	*2,348.80 FS
37	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	42.00 FS	*- FS
38	2		*FRONT FENDER BRACE - LH / RH	Bent	236.00 FS	*188.80 FS
39	2		*FRONT FENDER BRACKET - LH / RH	Not Necessary	88.00 FS	*- FS
40	2		*FRONT FENDER CLOSING ELEMENT - LH / RH	Not Necessary	106.00 FS	*- FS
41	1		*FRONT WHEEL HOUSING LINER LH	Not Necessary	275.00 FS	*- FS
42	1		*FRONT WHEEL HOUSING LINER RH	Not Necessary	266.00 FS	*- FS
43	1		*WHEEL HOUSING LINER ATTACHMENT PART	Not Necessary	71.00 FS	*- FS
44	2		*FRONT WHEEL SPOILER LH / RH	Not Necessary	332.00 FS	*- FS
45	2		*FRONT STONE CHIP GUARD LH / RH	Not Necessary	102.00 FS	*- FS
46	2		*SILL PANEL TRIM BRACKET LH / RH	Not Necessary	80.00 FS	*- FS
47	1		*BONNET	Distorted	5,528.00 FS	*4,422.40 FS
48	2		*BONNET HINGE LH / RH	Bent	344.00 FS	*274.40 FS
49	1		*BONNET ATTACHMENT PARTS	Not Necessary	233.00 FS	*- FS
50	1		*BONNET ABSORBER	N/S Damaged	241.00 FS	*96.40 FS
51	2		*BONNET IMPACT PROTECTION LH / RH	Necessary	38.00 FS	*30.56 FS
52	1		*BONNET IMPACT PROTECTION CTR	Necessary	44.00 FS	*35.12 FS
53	2		*BONNET STRIKER LH / RH	Bent	220.00 FS	*175.20 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	2		*BONNET LOCK WITH SWITCH	Damaged	419.00 FS	*335.20 FS
55	1		*FRONT FENDER TOP COVER LH / RH	N/S Deformed	64.00 FS	*25.52 FS
56	1		*BONNET HINGE COVER LH / RH (2PCS)	Cracked	88.00 FS	*68.97 FS
57	1		*PLENUM CHAMBER COVER	Not Necessary	200.00 FS	*- FS
58	1		*FRONT FENDER TOP LEDGE COVER	N/S Deformed	72.00 FS	*28.24 FS
59	2		*BOWDEN CABLE	Cut	58.00 FS	*46.00 FS
60	1		*RELEASE ELEMENT	Bent	58.00 FS	*46.00 FS
61	1		*RELEASE LEVER	Cut	14.00 FS	*10.48 FS
62	1		*RELEASE CABLE COVER	Cracked	10.00 FS	*7.60 FS
63	2		*HEADLIGHT MOUNTING LH / RH	Cracked	236.00 FS	*188.80 FS
64	2		*LED HEADLIGHT LH / RH	N/S Smashed / O/S Cracked	17,248.00 FS	*13,798.40 FS
65	1		*LED HEADLIGHT CAP LH	Damaged	58.00 FS	*46.00 FS
66	1		*LED HEADLIGHT HOSE LH	Cut	29.00 FS	*22.48 FS
67	2		*LIFT CYLINDER LH / RH	Not Necessary	396.00 FS	*- FS
68	1		*LIFT CYLINDER BRACKET LH	Not Necessary	6.00 FS	*- FS
69	1		*LIFT CYLINDE HOSE	Not Necessary	182.00 FS	*- FS
70	1		*LOCK CARRIER	Cracked	1,234.00 FS	*987.20 FS
71	2		*LOCK CARRIER LOWER SUPPORT LH / RH	Deformed	44.00 FS	*34.56 FS
72	1		*A/C CONDENSER	Bent	622.00 FS	*497.60 FS
73	1		*A/C CONDENSER O-RING	Not Necessary	10.00 FS	*- FS
74	1		*A/C CONDENSER SEAL RING	Not Necessary	7.00 FS	*- FS
75	1		*A/C CONDENSER SEAL RING	Not Necessary	10.00 FS	*- FS
76	1		*A/C PRESSURE SENSOR	Not Necessary	186.00 FS	*- FS
77	1		*A/C CONDENSOR SAFETY SWITCH VALVE	Not Necessary	51.00 FS	*- FS
78	1		*A/C REFRIGERANT LINE	Not Necessary	248.00 FS	*- FS
79	1		*A/C REFRIGERANT LINE	Not Necessary	264.00 FS	*- FS
80	1		*A/C REFRIGERANT LINE BRACKET	Not Necessary	23.00 FS	*- FS
81	1		*OUTSIDE TEMPERATURE SENSOR	Not Necessary	58.00 FS	*- FS
82	1		*CHARGE AIR COOLER	Not Necessary	587.00 FS	*- FS
83	1		*CHARGE AIR COOLER SEAL RING	Not Necessary	56.00 FS	*- FS
84	1		*CHARGE AIR COOLER PRESSURE PIPE	Not Necessary	375.00 FS	*- FS
85	1		*RADIATOR	Bent	904.00 FS	*722.80 FS
86	4		*RADIATOR COOLANT	Necessary	179.00 FS	*143.04 FS
87	2		*RADIATOR AIR GUIDE LH / RH	Cracked	78.00 FS	*60.96 FS
88	1		*RADIATOR AIR GUIDE UPPER	Cracked	30.00 FS	*23.76 FS
89	1		*RADIATOR AIR GUIDE LOWER	Not Necessary	33.00 FS	*- FS
90	1		*WATER DEFLECTOR STRIP LH	Cut	59.00 FS	*46.88 FS
91	2		*WINDOW SLOT SEAL LH - OUTER	Not Necessary	400.00 FS	*- FS
92	1		*WINDOW SLOT SEAL RH - OUTER	Not Necessary	46.00 FS	*- FS
93	1		*INTAKE AIR GUIDE - FRONT	Not Necessary	84.00 FS	*- FS
94	1		*INTAKE AIR GUIDE - REAR	Not Necessary	150.00 FS	*- FS
95	1		*AIR FILTER	Not Necessary	302.00 FS	*- FS
96	1		*FRONT NUMBER PLATE	Distorted	60.00 FS	*60.00 FS
97	1		*SUNDRIES	Necessary	400.00 FS	*228.22 FS
98	1		*FAN RING (Supplementary)	Scratched	267.00 FS	*213.20 FS
99	1		*RADIATOR FAN (Supplementary)	Scratched	2,318.00 FS	*1,854.40 FS
100	1		*WIRE CONNECTOR (Supplementary)	Cracked	26.00 FS	*20.64 FS
101	2		*HEADLIGHT COMPENSATING PIECE - LH / RH (Supplementary)	Cracked	160.00 FS	*127.36 FS
102	1		*WIRE CONNECTOR (Supplementary)	Broken	8.00 FS	*5.93 FS
103	1		*STARTER GENERATOR (ALTERNATOR) (Supplementary)	Damaged	1,987.00 FS	*1,589.60 FS
104	1		*COOLANT PIPE (Supplementary)	Bent	54.00 FS	*42.64 FS
105	1		*COOLANT RETURN PIPE (Supplementary)	Broken	39.00 FS	*30.80 FS

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR. HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS (R134)	New	1,700.00	1,700.00
3	TO DISMANTLE AND REINSTALL BOTH FRONT DOOR PANEL TRIMS. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSYS	New	800.00	360.00
4	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNITS AND POWER MODULES	New	800.00	500.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDERS, BONNET AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	6,300.00	3,500.00
6	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDERS, BOTH UPPER A-PILLARS AND BOTH FRONT DOORS	New	7,800.00	3,850.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	384.00	384.00
8	TO RENEW STARTER GENERATOR AND OTHER ENGINE COMPONENTS. (Supplementary)	New	480.00	480.00
Gross Labour Cost (S\$)			18,744.00	11,254.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >