

[Service Requests](#)[Messages](#)[Claims](#)

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	TPVD UNKNOWN (SDN65S)
Date of Loss	31 March 2021
Time of Loss	7:10
Loss Description	SJG799Z (INSD) > SDN65S (TP) >SLK2718A
Comment	

Workshop Details

Total Rebate Amount	0
Nett Loss Amount	-\$23,444.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (TP)
Days of work completion *	20



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

SDN65S

Registration State

SINGAPORE

Mileage

344061

Purchase Date

DD/MM/YYYY



Registration Date *

04/07/2006



Age of Vehicle

14

CATEGORY

POLICY
INFORMATION

ASSESSMENT INFORMATION

Manufacturing
Year

2006

Driver Details

CATEGORY



FNOL INFORMATION

POST SURVEY
INFORMATION


Driver Name

TBC

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Make	TPVD	<input type="text" value="TOYOTA"/>
Model	UNKNOWN	<input type="text" value="ESTIMA AERAS 2.4 A"/>
Type		<input type="text" value=""/>
Type of Paint		<input type="text" value=""/>
Chassis No		<input type="text" value="ACR507028487"/>
Engine No		<input type="text" value="2AZC047664"/>
Engine Capacity		<input type="text" value="2362"/>
Sum Insured		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Date of Birth		<input type="text" value="DD/MM/YYYY"/> 
Age	0	
Occupation	Unknown	<input type="text" value=""/>
Education Qualification	Other	<input type="text" value=""/>
Driving Experience	0	
Driver License #		<input type="text" value=""/>
License Type		<input type="text" value=""/>
License Issue Date		<input type="text" value="DD/MM/YYYY"/> 

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Market Value		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Expiration Date		<input type="text" value="DD/MM/YYYY"/> 
Address	TBC, Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value="v"/>
Gender	Unknown	<input type="text" value="v"/>
Marital status	Unknown	<input type="text" value="v"/>
Identification #	TBC	<input type="text"/>



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

01/04/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver Excess

0

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake
(Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Other Excess

0

Tyre Condition

Age of Tyres

Front Tyre Size

Front left side

Front right side

Spare wheel

Rear Tyre Size

Rear left side

Rear right side

215/55R17

LINGLONG7mm

LINGLONG7mm

215/55R17

LINGLONG6mm

LINGLONG6mm



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%	<input type="text" value="0"/>	Salvage%	<input type="text" value="0"/>
Discount%	<input type="text" value="25"/>	Settlement%	<input type="text" value="100"/>

Paint Labour/Material Ratio

Paint Labour Ratio	<input type="text" value="20"/>	Cash Loss	<div><div>Yes</div><div>No</div></div>	Part supplied by
Paint Material Ratio	<input type="text" value="80"/>			

A
X
A

Save



Service Requests

Messages

Claims















Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Parts







<div>AddApproveDenySubmit All</div>													
EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		TAILGATE	Bent	0	1585	No	0	25	0	0	1188.75
	0	1		TAILGATE TOYOTA LOGO	Necessary	0	61.9	No	0	25	0	0	46.43
	0	1		TAILGATE ESTIMA EMBLEM	Necessary	0	58.5	No	0	25	0	0	43.88
	0	1		TAILGATE AERAS EMBLEM	Necessary	0	56.2	No	0	25	0	0	42.15
	0	1		TAILGATE INNER LOCK	Damaged	0	356	No	0	25	0	0	267
	0	1		TAILGATE WIPER MOTOR	Serviceable	0	0	No	0	0	0	0	0





EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		TAILGATE INNER TRIM BOARD	Cracked	0	491.2	No	0	25	0	0	368.4
	0	2		TAILGATE SHOCK ABSORBER	Serviceable	0	0	No	0	0	0	0	0
	0	1		TAILGATE WINDSCREEN RUBBER MOULDING	Necessary	0	138.9	No	0	25	0	0	104.18
	0	1		TAILGATE ELECTRIC KEY ANTENNA	Dented	0	164.8	No	0	25	0	0	123.6
	0	1		REAR BUMPER	Bent	0	681	No	0	25	0	0	510.75
	0	1		REAR BUMPER TOWING COVER	Dented	0	45.8	No	0	25	0	0	34.35
	0	1		REAR BUMPER REFLECTOR RHS	Cracked	0	55	No	0	25	0	0	41.25
	0	1		REAR BUMPER SIDE REFLECTOR (LONG) RHS	Damaged	0	46.8	No	0	25	0	0	35.1

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		REAR BUMPER SIDE RETAINER (SHORT) RHS	Damaged	0	43.5	No	0	25	0	0	32.63
	0	1		REAR END PANEL TOP GARNISH	Damaged	0	274.5	No	0	25	0	0	205.88
	0	1		REAR END PANEL	Bent	0	561	No	0	25	0	0	420.75
	0	1		REAR FENDER INNER TRIM BOARD RHS	Buckled	0	658.8	No	0	25	0	0	494.1

Labour

Add	Approve	Deny	Submit All
-----	---------	------	------------

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		TO RENEW THE DAMAGED PARTS AT THE ACCIDENT AREA. TO CUT & WELD THE REAR END PANEL	0	800	0	0	Reviewing		
	0		TO REMOVE & REFIT THE REAR WINDSCREEN TO FACILITATE THE REPAIRS	0	120	0	0	Reviewing		
	0		TO ASSEMBLE THE WIRING FOR THE TAILGATE REVERSE CAMERA AND THE REVERSE PARKING SENSORS. TO CHECK FOR PROPER FUNCTIONS	0	60	0	0	Reviewing		

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		TO SPRAY PAINT TAILGATE, REAR BUMPER, REAR END PANEL, SPARE TYRE FLOOR PANEL	0	800	0	0	Reviewing		
	0		TO CARRY OUT ANTI-RUST TREATMENT AT THE ACCIDENT AREA	0	60	0	0	Reviewing		



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition









Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add		Approve		Deny		Submit All	
EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	DAYS OF REPAIR : 6 DAYS	Reviewing	0	0		
	0	BOOT WEATHERSTRIP (\$363.40) (50%)	Reviewing	0	181.7	DENTED / DISTORTED	
	0	TAILGATE REVERSE CAMERA	Deny	0	0	SERVICEABLE	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	REAR WINDSCREEN SEALANT	Reviewing	0	40	NECESSARY	
	0	REAR BUMPER REVERSE PARKING SENSOR	Reviewing	0	200	DENTED	
	0	1 SET REAR BUMPER CLIPS	Reviewing	0	35	NECESSARY	
	0	REAR END PANEL SEALANT	Reviewing	0	30	NECESSARY	

[Service Requests](#)[Messages](#)[Claims](#)

Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)

Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$6,285.90
------------------------	--------	-----------------------	------------

CATEGORY	ESTIMATE	ADJUSTED
Spare Parts		
Labour		
Spare Parts		
Miscellaneous		

Submit for Review



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT

SR
NO

NAME

ACTION

ESTIMATED
AMOUNT

ADJUSTED
AMOUNT

COMMENT

REMOVE



0

FINAL
LUMP
SUM

Reviewing

0

5200





Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$5,200.00
------------------------	--------	-----------------------	------------

CATEGORY

ESTIMATE

ADJUSTED

Miscellaneous

Submit for Review