

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21004222/TGA3Q2**Date:** 19/07/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SLE5502S**Insured Vehicle No :** SMN3287S

Date of Loss: 29/03/2021

Nature of Claim: TP

Claim No: 7806807739SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLE5502S**

Make & Model: HONDA SHUTTLE, 1.5 G CVT ABS (A)

Engine No: L15B3535445

Reg. Date: 26/07/2016 (Man. Year: 2016)

Chassis No: GK81004643

Colour: Black

Odometer: 81561 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size: 185/60 R15

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,314.06	9,079.91	10,234.15	52.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,700.00	2,930.00	4,770.00	61.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,014.06	12,009.91	15,004.15	55.54
Approved Total (Overridden) (S\$)		9,600.00		
(S\$)	27,014.06	9,600.00	17,414.06	64.46
+ GST 7.00/7.00% (S\$)	1,890.98	672.00	1,218.98	64.46
Nett Amount (S\$)	28,905.04	10,272.00	18,633.04	64.46
+ Car Rental (11.0 x S\$100.00/day + 7.00% GST) (S\$)		1,177.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		11,456.45		
Global Sum Settlement (S\$)		11,450.00		

INSPECTION

Date of Assignment: 01/04/2021

Date Inspected: 01/04/2021 Inspected At:

AP Automotive Services Pte Ltd (HQ)
Blk 9006 Tampines Street 93, #01-202
Singapore 528840

Estimated Period of Repair: 8.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	897.23 FL	*897.23 FL
2	1		*TAILGATE SPOILER (NPA)	Not Necessary	0.00 FL	*- FL
3	1		*TAILGATE SPOILER LAMP (NPA)	Not Necessary	0.00 FL	*- FL
4	1		*TAILGATE WINDSCREEN	Broken	1,240.00 FL	*1,120.00 FL
5	1		*TAILGATE WINDSCREEN MOULDING	Necessary	126.75 FL	*126.75 FL
6	2		*TAILGATE WINDSCREEN SIDE GARNIS L+R (NPA)	Not Necessary	0.00 FL	*- FL
7	2		*TAILGATE LAMP L+R	Cracked	624.90 FL	*624.90 FL
8	1		*TAILGATE GARNISH	Cracked	347.61 FL	*285.10 FL
9	1		*TAILGATE CHROME	Cut	385.65 FL	*241.20 FL
10	1		*TAILGATE LOGO -HONDA	Necessary	79.12 FL	*79.12 FL
11	1		*TAILGATE EMBLEM -SHUTTLE	Necessary	65.95 FL	*65.95 FL
12	1		*TAILGATE HANDLE SWITCH (NPA)	Not Necessary	0.00 FL	*- FL
13	2		*TAILGATE NUMBER PLATE LAMP L+R	Not Necessary	170.60 FL	*- FL
14	1		*TAILGATE LOCK	Bent	281.77 FL	*196.20 FL
15	1		*TAILGATE LOCK CATCH	Bent	75.50 FL	*75.50 FL
16	2		*TAILGATE INNER TRIM TOP L+R	Not Necessary	382.90 FL	*- FL
17	1		*TAILGATE INNER TRIM BOTTOM	Deformed	237.81 FL	*237.81 FL
18	1		*TAILGATE INNER HANDLE	Cracked	45.82 FL	*45.82 FL
19	2		*SET TAILGATE HINGE	Repair	190.40 FL	*- FL
20	2		*SET TAILGATE DAMPER	Repair	359.70 FL	*- FL
21	1		*TAILGATE WEATHERSTRIP	Twisted	149.63 FL	*149.63 FL
22	2		*TAIL LAMP L+R	Cracked	843.12 FL	*843.12 FL
23	1		*TAIL LAMP PANEL L+R	N/S Repair / O/S Damaged	428.50 FL	*163.50 FL
24	1		*REAR BUMPER	Deformed	1,247.91 FL	*958.00 FL
25	1		*REAR BUMPER REFLECTOR L+R	N/S Not Necessary / O/S Cut	141.14 FL	*70.57 FL
26	1		*REAR BUMPER REFLECTOR GARNISH L+R	N/S Not Necessary / O/SCracked	112.44 FL	*56.22 FL
27	2		*REAR BUMPER REFLECTOR SPONGE L+R	Cracked	103.84 FL	*103.84 FL
28	2		*SET REAR BUMPER REVERSE SENSOR	Not Working	344.90 FL	*250.00 FL
29	1		*REAR BUMPER TOW COVER	Deformed	85.90 FL	*85.90 FL
30	2		*REAR BUMPER RETAINER L+R	Necessary	161.24 FL	*161.24 FL
31	1		*REAR BUMPER BRACKET	Cracked	105.23 FL	*105.23 FL
32	1		*REAR BUMPER UNDERCOVER	Not Necessary	472.45 FL	*- FL
33	2		*REAR FENDER L+R	Repair	2,049.38 FL	*- FL
34	1		*REAR FENDER INNER TRIM TOP L+R	N/S Not Necessary/O/SDeformed	642.82 FL	*321.41 FL
35	1		*REAR FENDER INNER TRIM BOTTOM L+R	N/S Not Necessary/O/SDeformed	873.18 FL	*312.10 FL
36	1		*REAR FENDER COWLING L+R	N/S Not Necessary/O/SDeformed	255.70 FL	*127.85 FL
37	1		*END PANEL	Bent	492.60 FL	*434.50 FL
38	1		*END PANEL INNER PANEL	Repair	603.75 FL	*- FL
39	1		*END PANEL TOP GARNISH	Deformed	134.10 FL	*134.10 FL
40	1		*REAR SMART LOCK ANTENNA	Cracked	194.50 FL	*194.50 FL
41	1		*REAR BUZZER	Cracked	145.70 FL	*145.70 FL
42	1		*SPARWHEEL PANEL	Repair	936.54 FL	*- FL
43	1		*SPAREWHEEL PANEL TOP BOARD	Deformed	589.40 FL	*398.00 FL
44	1		*SPAREWHEEL PANEL TOOLS SPONGE	Deformed	143.97 FL	*143.97 FL
45	1		*SPAREWHEEL PANEL ACCESSORIES TRAY	Deformed	411.25 FL	*295.00 FL
46	1		*SPAREWHEEL PANEL ACCESSORIES TRAY FRONT COVER	Deformed	178.67 FL	*178.67 FL
47	1		*SPAREWHEEL PANEL ACCESSORIES TRAY BOTTOM COVER	Deformed	182.51 FL	*182.51 FL
48	2		*REAR PASSENGER SEATBELT L+R	Jammed	1,968.00 FL	*700.00 FL
49	1		*REAR RH DOOR WEATHERSTRIP	Cut	120.00 FL	*120.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*TAILGATE WINDSCREEN SEALANT	Necessary	150.00 FS	*50.00 FS
51	1		*TAILGATE INNER TRIM CLIPS	Necessary	250.00 FS	*20.00 FS
52	1		*REVERSE CAMERA	Distorted	800.00 FS	*250.00 FS
53	1		*TAIL LAMP CLIPS	Necessary	50.00 FS	*20.00 FS
54	1		*TAIL LAMP PANEL SEALANT	Not Necessary	240.00 FS	*- FS
55	1		*REAR NUMBER PLATE	Bent	120.00 FS	*45.00 FS
56	1		*REAR BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
57	2		*REAR FENDER SEALANT	Necessary	500.00 FS	*40.00 FS
58	2		*REAR FENDER INNER TRIM TOP CLIPS	Not Necessary	200.00 FS	*- FS
59	2		*REAR FENDER INNER TRIM BOTTOM CLIPS	Necessary	200.00 FS	*20.00 FS
60	2		*REAR FENDER COWLING CLIPS	Necessary	200.00 FS	*10.00 FS
61	1		*END PANEL SEALANT }	Necessary	200.00 FS	*40.00 FS
62	1		*END PANEL INNER PANEL SEALANT }		200.00 FS	*- FS
63	1		*END PANEL TOP GARNISH CLIPS	Necessary	100.00 FS	*10.00 FS
64	1		*SPAREWHEEL PANEL SEALANT	Necessary	300.00 FS	*40.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$\$)	23,240.08 11,206.14
- List Item Discount on L Items 20.00/20.00% (\$\$)					3,926.02	2,126.23
					Total Parts (\$\$)	19,314.06 9,079.91

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	1,400.00	1,200.00
2	SPRAY PAINT ON AFFECTED AREAS	New	1,800.00	1,200.00
3	TO RNR REAR WINDSCREEN	New	350.00	120.00
4	TO RNR REAR EXHAUST	New	250.00	60.00
5	TO RNR REAR PASSENGER SEATBELT	New	400.00	60.00
6	TO CHECK WIRING AND TAILLAMP FUNCTION }	New	150.00	40.00
7	TO CHECK WIRING AND TAILGATE LAMP FUNCTION }	New	150.00	0.00
8	TO RNR REAR INNER TRIM AND UPHOLSTERY	New	400.00	60.00
9	TO CHECK WHEEL ALIGNMENT AND ADJUST	New	250.00	0.00
10	TO RNR UNDERCARRIAGE	New	250.00	0.00
11	TO CHECK WATER LEAK	New	150.00	30.00
12	TO RNR FUEL TANK	New	250.00	0.00
13	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	600.00	0.00
14	TO RNR REAR TAILGATE MECHANISM	New	350.00	60.00
15	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	New	150.00	30.00
16	TO PERFORM RUST PROOFING	New	400.00	40.00
17	TO CLEAN AND VACUUM GLASSES	New	400.00	30.00
Gross Labour Cost (\$\$)			7,700.00	2,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >