

AP AUTOMOTIVE SERVICES PTE LTD ROC: 202022890H BLOCK 9006 TAMPINES STREET 93 #01-202 SINGAPORE 528840 TEL: 6784 4465 FAX: 6787 4886

Estimation

Date

Vehicle

SLE 5502 S

Make/Model

HONDA SHUTTLE

Chassis No.

GK81004643

No.	Description		Unit	Τ	Unit Price	1	Amor	ınt	7
	Parts Replacment			1					1
1	TAILGATE		1	\$	897.23	\$	6+1	897.23	
_2	TAIL GATE SPOILER		1	Ť		\$	KIN		1
-3	TALLCATE SPOLLED LAMP		1			\$	≺ nn	_	1
4	TAILGATE WINDSCREEN	1120	1			\$	p101	CONHEI	1
5	TAILGATE WINDSCREEN MOULDING		1	\$	126.75	\$	nu/	126.75	1
	TALL GATE WINDSCREEN SIDE CARNIELL.	9-	1		معددة الربيبية المستدف	\$	X nn.	-	
7	TAILGATE LAMP L+R		2	\$	312.45	\$	Cug -	624.90	
8	TAILGATE GARNISH	285.10	1	\$	347.61	\$	Coop i	CU 347.61	1
9	TAILGATE CHROME	241.20	1	\$	385.65	\$	Con	385.65]
10	TAILGATE LOGO - HONDA		1	\$	79.12	\$	ny-	79.12	}
11	TAILGATE EMBLEM - SHUTTLE		1	\$	65.95	\$	wor	65.95	
12	TAILGATE HANDLE SWITCH		1	\$	267.84	\$	×wv		1
13	TAILGATE NUMBER PLATE LAMP L+R		2	\$	85.30	\$	Zun.	170.60	v
14	TAILGATE LOCK	196.20	1	\$	281.77	\$	64/	281.77	}
15	TAILGATE LOCK CATCH		1	\$	75.50	\$	bt	75.50	
16	TAILGATE INNER TRIM TOP L+R		2	\$	191.45	\$	~w	382.90]
17	TAILGATE INNER TRIM BOTTOM		1	\$	237.81	\$	de	237.81	1
18	TAILGATE INNER HANDLE		1	\$	45.82	\$	cry	45.82	
19	TAILGATE HINGE SET		2	\$	95.20	\$	RY	190.40	
20	TAILGATE DAMPER SET		2	\$	179.85	\$	Rig	359.70	
21	TAILGATE WEATHERSTRIP		1	\$	149,63	\$	fui/	149.63	
22	TAIL LAMP L+R		2	\$	421.56	\$	Cuq	,843.12	
23	TAIL LAMP PANEL L+R	163.50	2	\$	(214.25)	\$,	IHRY, R	428.50	V DAN
24	REAR BUMPER	958	1	\$	1,247.91	\$	ale !	1,247.91	
25	REAR BUMPER REFLECTOR L+R		2	\$	(70.57)	\$ -	LHX" RHU		
26	REAR BUMPER REFLECTOR GARNISH L+R		2	\$	(56.22)		24 X 1/2 H		
27	REAR BUMPER REFLECTOR SPONGE L+R		2	\$	51.92	\$	*tôna/	103.84	1
28	REAR BUMPER REVERSE SENSOR SET	250	2	\$	172.45	\$	nu/	344.90	
29	REAR BUMPER TOW COVER		1	5	85.90	\$	del	85.90	
30	REAR BUMPER RETAINER L+R		2	\$	80.62	\$	no /	161.24	
31	REAR BUMPER BRACKET		1	\$	105.23	\$	Erni -	105.23	
32	REAR BUMPER UNDERCOVER		1	\$	472.45	\$	Xnn	472.45	1
	REAR FENDER L+R	784	2	\$	1,024.69	\$ /	HIRHIR	× 2,049.38	RY
	REAR FENDER INNER TRIM TOP L+R		2	\$	(321.41)	\$ 2	HXPH-1	642.82	/
	REAR FENDER INNER TRIM BOTTOM L+R	031210	2	\$	436.59	-	HANNEHOL		
	REAR FENDER COWLING L+R		2	\$	J. 27.85		HENNEY I	255.70	
	END PANEL	434.50.	1	\$	492.60	\$	N7/	492 60	

m. 4.21.31

			1		1		
38	END PANEL INNER PANEL - 1 hu. H 420.11	1 1	\$	603.75	\$	177	603.75
39	END PANEL TOP GARNISH	1	\$	134.10	\$	06-	134.10
40	REAR SMART LOCK ANTENNA 47.9	9 1	\$	194.50	\$	ions-	194.50
41	REAR BUZZER 80-10	⊢ 1	\$	145.70	\$? cuar	145.70
42	SPAREWHEEL PANEL 596-4	0 1	\$	936.54	\$	All bie	€X 936.54
43	SPAREWHEEL PANEL TOP BOARD 398	1	\$	589.40	\$	ac/	589.40
44	SPAREWHEEL PANEL TOOLS SPONGE	1	\$	143.97	\$	36/	143.97
45	SPAREWHEEL PANEL ACCESSORIES TRAY 295	1	\$	411.25	\$	de V	411.25
46	SPAREWHEEL PANEL ACCESSORIES TRAY FRONT COVER	1	\$	178.67	\$	al-	178.67
47	SPAREWHEEL PANEL ACCESSORIES TRAY BOTTOM COVER	1	\$	182.51	\$	3Ll/	182.51
48	REAR PASSENGER SEATBELT L+R 6350	7	4	984	\$	"jm.	19(5:5)
	for PII to a Right			Total	\$	80.017.19	16,569.92
	Near RH door weathership and 1 \$1:	20	L	ess 20%	\$		3,313.90
				Total	\$	15,608.06	13,255.94

16,744.83 (17,996.66)

	S/Nett Items			
1	TAILGATE WINDSCREEN SEALANT	1	150	\$ \$ 50 me - 150.00
2	TAILGATE INNER TRIM CLIPS	1	250	\$ 20 ue - 250.00
3	REVERSE CAMERA	1	800	\$ 250 800.00
4	TAIL LAMP CLIPS	1	50	\$ 20 00 50.00
5	TAIL LAMP PANEL SEALANT	2	120	\$ 1 1 1 240.00
6	REAR NUMBER PLATE	1	120	\$ 45 ht 120.00
7	REAR BUMPER CLIPS	1	100	\$ 30-2- 100.00
3	REAR FENDER SEALANT	2	250	\$ 4000 - 500.00
9	REAR FENDER INNER TRIM TOP CLIPS	2	100	\$ 200.00
10	REAR FENDER INNER TRIM BOTTOM CLIPS	2	100	
11	REAR FENDER COWLING CLIPS	2	100	\$ 10.4x V 200.00
12	END PANEL SEALANT	1	200	\$7 40 noc 200.00
13	END PANEL INNER PANEL SEALANT	1	200	\$
14	END PANEL TOP GARNISH CLIPS	1	100	\$ 10000 100.00
15	SPAREWHEEL PANEL SEALANT	1	300	72
			Total	\$ 3,610.00

	LABOUR		ě	1200	·
1	PANEL BEATING ON AFFECTED AREAS	1	1400	\$ -1000	1,400.00
2	SPRAY PAINT ON AFFECTED AREAS	1	1800	\$ 1200	1,800.00
3	TO RNR REAR WINDSCREEN	1	350	\$ 1200.	350.00
4	TO RNR REAR EXHAUST	1	250	\$ 60.	250.00
5	TO RNR REAR PASSENGER SEATBELT	1	400	\$ 60	400.00
6	TO CHECK WIRING AND TAILLAMP FUNCTION	1	150	\$7 30	
7	TO CHECK WIRING AND TAILGATE LAMP FUNCTION	1	150	\$ 40	150.00
8	TO RNR REAR INNER TRIM AND UPHOISTERY	1	400	\$ 60	150.00
9	TO CHECK WHEEL ALIGNMENT AND ADJUST		250		400.00
10	TO RNR UNDERCARRIAGE	1	250	1 1 1	250.00
11	TO CHECK WATER LEAK	1 1	150		250.00
	TO RNR FUEL TANK			\$ 30	150.00
~	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	1	250	\$ X NM	250.00
	TO RNR REAR TAILGATE MECHANISM		500	\$ X NN	600.00
	TO THE MECHANISM		350	\$ 60	350.00

RX

Rr

700

3527.23

575

1200

2930

30,

					450.00
16	TO PERFORM RUST PROOFING	1	400	\$ 40	400.00
17	TO CLEAN AND VACUUM GLASSES	1	400	\$ 30.	400.00
		•	Total Labour	\$	7,700.00
	Parts F	teplacem	ent Amount	\$	16,865.94
				26,914	.06
		Total	Amount	\$	24-565-04

852723 Taughti 97415249 2930 12032.23 UP 14/21 C 5pm 1/5\$9600 1/5 Resymy after reps. L. 8days * farfin O/hhartann Edays.

150

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:

15 TO RNR REAF REVERSE SENSOR AND CHECK FUNCTION