

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

| PRE-REPAIR INSPECTION REPORT       |   |                          |                     |                         |  |
|------------------------------------|---|--------------------------|---------------------|-------------------------|--|
|                                    | AXA INSURANCE   |                          | Ref:                | CS3/ASM21004228/Qtce2   |  |
|                                    | 8 SHENTON WAY<br>TOWERSINGAPOR  |                          | Date:               | 20/04/2021              |  |
|                                    | ATTN: YU DOMINI   | C YISHAN                 | Code:               | ASM                     |  |
| 1.                                 | Policy Particulars :- (THIRD PARTY CLAIM)   |                          |                     |                         |  |
|                                    | Insured Veh.  | SH 6645H                 | Veh. Inspected      | GBH 7053K               |  |
|                                    | Policy No.  | VFX/P2419138             | Coverage (\$)       | 0.00                    |  |
|                                    | Claim No.   | S1M036YU                 | Excess (\$)         | 0.00                    |  |
|                                    | Assign From   | YU DOMINIC YISHAN        | Assign Date         | 01/04/2021              |  |
| 2. Vehicle Particulars & Condition |   |                          |                     |                         |  |
|                                    | Make & Model  | TOYOTA DYNA 150          | c.c                 | 2982                    |  |
|                                    | Engine No.  | HIDDEN                   | Year of Reg.        | 2018                    |  |
|                                    | Chassis No.   | JTFAT35Y50K210634        | Colour              | WHITE                   |  |
|                                    | Odometer  | 70086 KM                 | Steering            | IN ORDER                |  |
|                                    | Brakes  | IN ORDER                 | Modification        | STANDARD ALLOY RIM      |  |
|                                    | General   | FAIR                     |                     |                         |  |
| 3. Conditions of Tyres             |   |                          |                     |                         |  |
|                                    |   | Size                     | Make                | Balance                 |  |
|                                    | R/H Front Tyre  | 195/75 R15               | BRIDGESTONE         | 6 mm                    |  |
|                                    | L/H Front Tyre  | 195/75 R15               | BRIDGESTONE         | 6 mm                    |  |
|                                    | R/H Rear Tyre   | 195/75 R15               | BRIDGESTONE         | 6 mm                    |  |
|                                    | L/H Rear Tyre   | 195/75 R15               | BRIDGESTONE         | 6 mm                    |  |
| 4. Description of Damages          |   |                          |                     |                         |  |
|                                    | THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.  |                          |                     |                         |  |
| 5.                                 | 5. General Information  |                          |                     |                         |  |
|                                    | Accident Date   | 30/03/2021               | Inspect Date / Time | 13/04/2021 ( 11:33 AM ) |  |
|                                    | Survey held at  | SEAH MOTOR TRADING CO LL |                     |                         |  |
|                                    | 60 JALAN LAM HUAT #07-60 CARROS CENTRE SINGAPORE 737869   |                          |                     |                         |  |
| 5a.                                | Remarks   |                          |                     |                         |  |
|                                    | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000 |                          |                     |                         |  |
| 5b. Estimate Days of Repair        |   |                          |                     |                         |  |
|                                    | ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days  |                          |                     |                         |  |
|                                    | D   |                          |                     |                         |  |

Report Ref No. CS3/ASM21004228/Qtce2

Inspected By

OI SUN PIN

K.K.LAU CPT(RET)

Asst. Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser