

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21004234/EQCE2

Date: 03/08/2021

REFERENCE

Insured/Claimant:	LOW ENG KWANG	Policy No:	1900006954-01	
Date of Loss:	30/03/2021	Nature of Claim:	OD	Claim No: 5863110279SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH3361S	Engine No:	CVK073829
Make & Model:	AUDI A4, 2.0 TFSI S-TRONIC (A)	Chassis No:	WAUZZZF44KA009550
Reg. Date:	18/01/2019 (Man. Year: 2018)	Odometer:	30683 km
Colour:	Blue		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$116,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	43,847.00	18,158.00	25,689.00	58.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,782.00	7,702.00	4,080.00	34.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	55,629.00	25,860.00	29,769.00	53.51
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	54,829.00	25,060.00	29,769.00	54.29
+ GST 7.00/7.00% (S\$)	3,838.03	1,754.20	2,083.83	54.29
Nett Amount (S\$)	58,667.03	26,814.20	31,852.83	54.29

INSPECTION

Date of Assignment:	01/04/2021		
Date Inspected:	01/04/2021	Inspected At:	24 BENOI SECTOR Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	13.0 days		

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Broken	1,787.00 FS	*1,429.60 FS
2	1		*FRONT BUMPER COVER FIXING PARTS	Not Necessary	587.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	71.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	196.00 FS	*- FS
5	1		*FRONT BUMPER LOWER CLOSING ELEMENT - CENTER	Not Necessary	210.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE - LH	Not Necessary	63.00 FS	*- FS
7	1		*FRONT RADIATOR GIRLLE	Broken	1,332.00 FS	*1,065.60 FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Broken	135.00 FS	*108.00 FS
9	2		*FRONT BUMPER CARRIER	Not Necessary	845.00 FS	*- FS
10	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	124.00 FS	*- FS
11	1		*FRONT BUMPER REINFORCEMENT COVER	Broken	127.00 FS	*101.60 FS
12	1		*FRONT BUMPER GUIDE SECTION - LH	Broken	36.00 FS	*28.72 FS
13	1		*CAUTION STICKER	Necessary	14.00 FS	*10.88 FS
14	1		*AIR CONDITIONER STICKER	Necessary	8.00 FS	*5.68 FS
15	1		*FRONT BUMPER BRACKET	Broken	137.00 FS	*109.60 FS
16	2		*FRONT BUMPER CARRIER SUPPORT - LH / RH	Not Necessary	58.00 FS	*- FS
17	1		*FRONT HIGH TONE HORN - LH	Not Necessary	126.00 FS	*- FS
18	1		*FRONT HIGH TONE HORN SPRING SHACKLE - LH	Not Necessary	29.00 FS	*- FS
19	1		*FRONT FENDER - LH	Dented	767.00 FS	*613.20 FS
20	1		*FRONT FENDER ATTACHMENT PARTS - LH	Not Necessary	202.00 FS	*- FS
21	1		*FRONT FENDER CLOSING ELEMENT - LH	Necessary	72.00 FS	*57.52 FS
22	1		*FRONT FENDER BRACKET - LH	Bent	35.00 FS	*27.92 FS
23	1		*FRONT FENDER DEFORMATION BRACKET - LH	Not Necessary	49.00 FS	*- FS
24	1		*FRONT FENDER POP RIVERT (6PCS)	Necessary	20.00 FS	*15.84 FS
25	1		*FRONT FENDER BRACE - LH	Bent	118.00 FS	*94.40 FS
26	1		*FRONT FENDER INNER BRACKET - LH	Not Necessary	32.00 FS	*- FS
27	1		*FRONT WHEEL HOUSING LINER - LH	Torn	240.00 FS	*191.60 FS
28	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS - LH	Not Necessary	233.00 FS	*- FS
29	1		*FRONT WHEEL SPOILER - LH	Broken	73.00 FS	*58.40 FS
30	1		*FRONT WHEEL SPOILER TRIM - LH	Not Necessary	35.00 FS	*- FS
31	1		*FRONT FENDER STONE CHIP GUARD	Cut	51.00 FS	*40.32 FS
32	1		*FRONT FENDER LONG LEDGE COVER - LH	Necessary	31.00 FS	*24.64 FS
33	1		*FRONT FENDER SHORT LEDGE COVER - LH	Necessary	23.00 FS	*17.92 FS
34	1		*FRONT BONNET	Dented	3,246.00 FS	*2,596.80 FS
35	1		*FRONT BONNET ATTACHMENT PARTS	Not Necessary	412.00 FS	*- FS
36	2		*FRONT BONNET LID HINGE - LH / RH	Not Necessary	610.00 FS	*- FS
37	1		*FRONT BONNET IMPACT PROTECTION - LH / RH / CTR (3PCS)	Necessary	84.00 FS	*65.68 FS
38	1		*FRONT FENDER LEDGE COVER - LH	Not Necessary	62.00 FS	*- FS
39	1		*FRONT BONNET STRIKER - LH	Not Necessary	50.00 FS	*- FS
40	1		*FRONT BONNET LID LOCK	Not Necessary	214.00 FS	*- FS
41	1		*HEADLIGHT - LH	Broken	7,693.00 FS	*6,154.40 FS
42	1		*HEADLIGHT POWER MODULE	Not Necessary	761.00 FS	*- FS
43	1		*HEADLIGHT CONTROL UNIT	Not Necessary	751.00 FS	*- FS
44	2		*HEADLIGHT HOSE - LH	Not Necessary	36.00 FS	*- FS
45	1		*HEADLIGHT LIFT CYLINDER - LH	Not Necessary	210.00 FS	*- FS
46	1		*HEADLIGHT CORRUGATED PIPE	Not Necessary	93.00 FS	*- FS
47	1		*FRONT ALUMINIUM RIM - LH	Cut	1,142.00 FS	*913.60 FS
48	1		*FRONT ASSEMBLY CARRIER	Not Necessary	1,891.00 FS	*- FS
49	1		*FRONT WISHBONE LINK - LH	Bent	539.00 FS	*430.80 FS
50	1		*FRONT SUSPENSION GUIDE - LH	Bent	943.00 FS	*754.40 FS
51	2		*FRONT SUSPENSION CONTROL GUIDE	Not Necessary	1,024.00 FS	*- FS
52	1		*FRONT WHEEL BEARING HOUSING - LH	Necessary	968.00 FS	*774.00 FS
53	1		*FRONT WHEEL SWIVEL JOINT - LH	Bent	193.00 FS	*154.40 FS
54	1		*FRONT WHEEL HUB - LH	Necessary	479.00 FS	*383.20 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
55	1	*FRONT WHEEL BALL BEARING	Necessary	246.00 FS	*196.80 FS
56	1	*FRONT SUSPENSION FORKS	Not Necessary	264.00 FS	*- FS
57	1	*FRONT COUPLING ROD	Not Necessary	127.00 FS	*- FS
58	1	*FRONT ANTI ROLL BAR	Not Necessary	433.00 FS	*- FS
59	1	*FRONT GAS SHOCK ABSORBER	Not Necessary	301.00 FS	*- FS
60	1	*FRONT DRIVE SHAFT	Not Necessary	2,650.00 FS	*- FS
61	1	*STEERING GEAR	Not Necessary	6,787.00 FS	*- FS
62	1	*STEERING GEAR GREASE	Not Necessary	43.00 FS	*- FS
63	1	*FRONT INNER TRACK ROD	Bent	99.00 FS	*78.88 FS
64	2	*FRONT INNER TIE ROD	Bent	197.00 FS	*157.20 FS
65	1	*FRONT PLENUM CHAMBER COVER	Not Necessary	97.00 FS	*- FS
66	1	*FRONT NUMBER PLATE	Necessary	60.00 FS	*60.00 FS
67	1	*FRONT TIRE - LH	Not Necessary	270.00 FS	*- FS
68	1	*SUNDRIES	Necessary	350.00 FS	*132.00 FS
69	1	*SIDE MIRROR MOUNTING - LH	Cut	1,089.00 FS	*871.20 FS
70	1	*RADIATOR AIR GUIDE - OUTER LH (Supplementary)	Broken	12.00 FS	*9.44 FS
71	1	*REFRIGERANT PIPE (Supplementary)	Bent	523.00 FS	*418.00 FS
72	1	*REFRIGERANT PIPE BRACKET (Supplementary)	Bent	8.00 FS	*5.76 FS
73	1	*FRONT UPPER LINK GUIDE - LH FRONT (Supplementary)	Not Necessary	512.00 FS	*- FS
74	1	*FRONT UPPER LINK GUIDE - LH REAR (Supplementary)	Not Necessary	512.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$) **43,847.00** **18,158.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY & FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO DISMANTLE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY	New	280.00	0.00
4	TO REMOVE AND RENEW LHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME	New	2,400.00	2,400.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,800.00	1,500.00
6	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET, HINGES & LHS FRONT DOOR	New	3,900.00	1,650.00
7	TO RENEW LHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	520.00
8	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
9	TO DISMANTLE AND REINSTALL LHS FRONT DOOR PANEL. TO REMOVE AND RENEW LHS SIDE MIRROR MOUNTING	New	280.00	280.00
10	TO RESPRAY LHS MIRROR COVER	New	300.00	150.00
11	TO RENEW AIRCOND REFRIGERANT PIPE. (Supplementary)	New	280.00	280.00
Gross Labour Cost (\$\$)			11,782.00	7,702.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >