

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 21X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (CONSISTENT)	BUCKLED / MTG CRACKED	3,500.00	2,235.40
1	REAR BUMPER RETAINER-R/H (CONSISTENT)	CRACKED	511.00	511.00
1	REAR LOWER ARM -RH (CONSISTENT)	BENT	1,050.00	1,050.00
1	REAR KNUCKLE -R/H (CONSISTENT)	BENT	1,512.00	1,512.00
1	REAR KNUCKLE BEARING -R/H (CONSISTENT)	NECESSARY	235.20	235.20
1	REAR FENDER DUST COVER -R/H (ADDITIONAL) (CONSISTENT)	CRACKED	480.00	320.00
1	REAR LOWER ARM (SMALL) -R/H(ADDITIONAL) (CONSISTENT)	DISTORTED	476.00	476.00
1	REAR LOWER STABILIZER BAR -R/H (ADDITIONAL) (CONSISTENT)	DISTORTED	1,265.60	812.00
	LESS 10% DISCOUNT		-902.98	-715.16
			8,126.82	6,436.44
	SPECIAL NETT ITEMS			
1	REAR SPORT RIM -RH (SN) (CONSISTENT)	DENTED	650.00	650.00
			650.00	650.00
	<u>LABOUR</u>			
	TO PULL & KNOCK ON REAR ACCIDENT PORTION .		480.00	420.00
	TO SPRAY & PAINT ON REAR ACCIDENT PORTION .		680.00	500.00
	TO ANTI-RUST REAR AFFECTED AREAS .	NOT NECESSARY	60.00	-
	TO DISMANTLE & REPLACE UNDERCARRIAGE .		250.00	20.00
	TO COMPUTER FOUR WHEEL ALIGNMENT.		150.00	80.00
	TO CHECK ON WIRING FUNCTION.		30.00	20.00
			1,650.00	1,040.00
	GRAND TOTAL		10,426.82	8,126.44



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		6,500.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM21004240/Kea3q2

KONG SENG CHEONG

Licensed Appraiser