

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21004244/KEA3Q2**Date:** 10/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900262027
Claimant Vehicle No :	GBG7071M	Insured Vehicle No :	SMR2031Z
Date of Loss:	26/03/2021	Nature of Claim:	TP
		Claim No:	9620551660SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG7071M		
Make & Model:	NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (A)	Engine No:	ZD30025787N
Reg. Date:	28/09/2017 (Man. Year: 2016)	Chassis No:	JN1SC2F24Z0860153
Colour:	Silver	Odometer:	102892 km
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185 R15X8	Rear Tyre Size:	155 R12X8 (D)
Front Left Side:	West Lake 6 mm	Rear Left Side:	Dunlop 4/4 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	Dunlop 4/4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,419.74	2,419.74	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,100.00	990.00	110.00	10.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,519.74	3,409.74	110.00	3.13
Approved Total (Overridden) (S\$)		2,700.00		
(S\$)	3,519.74	2,700.00	819.74	23.29
+ GST 7.00/7.00% (S\$)	246.38	189.00	57.38	23.29
Nett Amount (S\$)	3,766.12	2,889.00	877.12	23.29
+ Loss of Use (5.0 x S\$80.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,291.00		

INSPECTION

Date of Assignment:	01/04/2021	
Date Inspected:	23/04/2021	Inspected At: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,399.70 FN	*1,399.70 FN
2	1		*TAILGATE STICKER -NISSAN	Necessary	141.40 FN	*141.40 FN
3	1		*TAILGATE LH LOCK HANDLE	Distorted / Dented	173.40 FN	*173.40 FN
4	1		*TAILLAMP LH	Cracked	248.60 FN	*248.60 FN
5	1		*TAILLAMP PANEL LH	Bent	125.50 FN	*125.50 FN
6	1		*SET REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
7	1		*STICKER -70KM/H	Necessary	10.00 FS	*10.00 FS
8	1		*STICKER -8 PAX	Necessary	10.00 FS	*10.00 FS
9	1		*TAILGATE INNER PROTECTOR	Distorted	280.00 FS	*280.00 FS
10	16		*TAILGATE INNER PROTECTOR RIVETS	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	2,628.60	2,628.60
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	208.86	208.86
Total Parts (\$\$)	2,419.74	2,419.74

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX TAILGATE ASSY ,INNER PROTECTOR ,TAILLAMP ,TO KNOCK & REPAIR TAILGATE LOWER MEMBER ,REAR STEP PANEL ,LH SIDE GATE LOWER MEMBER ,REAR LH CORNAL PILLAR & REALIGN THE SAME	New	600.00	540.00
2	PUTTY & RESPRAY ON TAILGATE ,TAILGATE LOWER MEMBER ,REAR STEP BAR ,REAR LH CORNAL PILLAR & LH SIDE GATE LOWER MEMBER	New	500.00	450.00
Gross Labour Cost (\$\$)			1,100.00	990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >