Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### **VEHICLE DAMAGE INSPECTION REPORT**

Our File No: CC4/AXA16011529/KPA3Q2-1

**Date:** 13/04/2021

**REFERENCE** 

Handling Insurer: AXA Insurance Pte Ltd Policy No: GA070278

Claimant

EY928H Insured Vehicle No: SKH2017S

Vehicle No:

Date of Loss: 18/06/2016 Insured Vehicle No: SKH20175

Nature of Claim: TP Claim No: C0388314

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: EY928H

Make & Model: PORSCHE BOXSTER, S Engine No: 65V16067

Reg. Date: 14/10/1997 (Man. Year: 1997) Chassis No: WPOZZZ98ZVS609775

Colour: Metallic Silver Odometer: 79170 km

Engine Capacity: 2480 cc
Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 205/55Z R16 Rear Tyre Size: 205/55Z R16
Front Left Side: Michelin 8 mm Rear Left Side: Michelin 3 mm
Front Right Side: Michelin 8 mm Rear Right Side: Michelin 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,323.60	6,121.73	1,201.87	16.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,900.00	1,640.00	260.00	13.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,223.60	7,761.73	1,461.87	15.85
Approved Total (Overridden) (S\$)		6,100.00		
(S\$)	9,223.60	6,100.00	3,123.60	33.87
+ GST 7.00/7.00% (S\$)	645.65	427.00	218.65	33.87
Nett Amount (S\$)	9,869.25	6,527.00	3,342.25	33.87
+ Loss of Use (8.0 x S\$1	50.00/day) (S\$)	1,200.00		
Ne	tt Liability (S\$)	7,727.00		

**INSPECTION** 

Date of Assignment: 21/06/2016

Date Inspected: 22/06/2016 Inspected At: Alan's United Auto Pte Ltd (HQ)

Blk 7 Sin Ming Industrial Estate, #01-

76

Singapore 575642

Estimated Period of Repair: 6.0 days

Adjuster Report Page 2 of 4

Adjuster: KENNETH KONG Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

Reference				
Part Source:		(Last Synchronised: 09 Apr 2019)		
Parts:	N/A	PORSCHE BOXSTER S (Model not available in database)		
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code:	: (Unsubmitted, no print-code for EY928H)			
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.				

# **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER FASCIA (CONSISTENT)	Bent	1,484.50 FL	*1,484.50 FL
2	1		*REAR BUMPER REINFORCEMENT (CONSISTENT)	Bent	680.70 FL	*680.70 FL
3	1		*REAR BUMPER TOP GARNISH (CONSISTENT)	Buckled	77.50 FL	*77.50 FL
4	1		*REAR BUMPER INNER SPONGE (CONSISTENT)	Cracked	121.50 FL	*121.50 FL
5	1		*FRONT BUMPER REINFORCEMENT COVER (CONSISTENT)	Dented	88.50 FL	*88.50 FL
6	1		*REAR REINFORCEMENT ABSORBER (CONSISTENT)	Serviceable	83.60 FL	*- FL
7	1		*REAR INFORCEMENT ABSORBER SEAL (CONSISTENT)	Serviceable	11.20 FL	*- FL
8	1		*REAR BUMPER SIDE RETAINER (CONSISTENT)	N/S Distorted	413.40 FL	*206.70 FL
9	2		*REAR LICENSE PLATE LAMP (CONSISTENT)	Cracked	144.60 FL	*144.60 FL
10	1		*REAR END PANEL (CONSISTENT)	Bent	582.40 FL	*582.40 FL
11	1		*REAR EXHAUST SILENCE BOX (CONSISTENT)	Bent	3,215.50 FL	*3,215.50 FL
12	2		*REAR EXHAUST CONNECTING JOINT (CONSISTENT)	Necessary	177.80 FL	*177.80 FL
13	2		*TAILLAMP (CONSISTENT)	Serviceable	1,022.80 FL	*-FL
14	1		*REAR NO PLATE (CONSISTENT)	Cracked	30.00 FS	*20.00 FS
F=Fra	anchise	part. S=S	SpcNett. L=ListItemDisc.		r	
				Sub Total (S\$)	,	6,799.70
			- List Item Discount on L Items 10.0	)0/10.00% (S\$)	810.40	677.97
			Т	otal Parts (S\$)	7,323.60	6,121.73

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

#### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE REAR BOOT CARPET ,SIDE TRIM FOR RENEW END PANEL	New	120.00	80.00
2	TO APPLY UNDERSEALING	New	80.00	60.00
3	TO PUTTY AND SPRAY REPLACED PARTS	New	800.00	700.00
4	TO REMOVE, CUT -OUT DAMAGED PARTS , PANEL BEATING , WELDING , ALIGN, REFIX AND TO RENEW ABOVE PARTS	New	900.00	800.00
	Gross Lab	our Cost (S\$)	1,900.00	1,640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >