

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 2782A

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|--|-------------------------|-------------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | FRONT BUMPER (CONSISTENT) | BROKEN | 1,158.00 | 858.00 |
| 2 | FRONT BUMPER BRACKET LEFT & RIGHT (CONSISTENT) | NECESSARY | 120.00 | 90.00 |
| 1 | FRONT BUMPER TOP CHROME & GRILLE (CONSISTENT) | BROKEN | 454.00 | 374.00 |
| 1 | FRONT BUMPER TOP PANEL GARNISH (CONSISTENT) | NOT DAMAGED | 163.00 | - |
| 1 | FRONT BUMPER LOWER CHROME & GRILLE (CONSISTENT) | NOT DAMAGED | 495.00 | - |
| 1 | FRONT BUMPER FOGLAMP COVER LEFT (CONSISTENT) | NOT DAMAGED | 60.00 | - |
| 1 | FRONT BUMPER FOGLAMP COVER RIGHT (CONSISTENT) | NOT DAMAGED | 60.00 | - |
| 1 | FRONT BUMPER FOGLAMP LEFT (CONSISTENT) | NOT DAMAGED | 374.00 | - |
| 1 | FRONT BUMPER FOGLAMP RIGHT(CONSISTENT) | NOT DAMAGED | 374.00 | - |
| 2 | FRONT BUMPER DAYLIGHT LEFT AND RIGHT (CONSISTENT) | NOT DAMAGED | 1,008.00 | - |
| 1 | FRONT BUMPER TOWING COVER (CONSISTENT) | DISLODGE | 66.00 | 59.40 |
| 1 | FRONT BUMPER LOWER UP (CARBON FIBRE) (CONSISTENT) | DISLODGE | 350.00 | 315.00 |
| 1 | FRONT HEADLAMP LEFT (CONSISTENT) | NOT DAMAGED | 798.00 | - |
| 1 | FRONT HEADLAMP RIGHT (CONSISTENT) | NOT DAMAGED | 798.00 | - |
| 1 | FRONT REINFORCEMENT (CONSISTENT) | NOT DAMAGED | 490.00 | - |
| 1 | FRONT BONNET (CONSISTENT) | TO REPAIR SEE LABOUR | 809.00 | - |
| 1 | FRONT BONNET LOCK (CONSISTENT) | NOT DAMAGED | 80.00 | - |
| 1 | FRONT BONNET DAMPER (CONSISTENT) | NOT DAMAGED | 20.00 | - |
| 1 | FRONT FENDER LEFT (CONSISTENT) | DENTED | 688.00 | 619.20 |
| 1 | FRONT FENDER RIGHT (CONSISTENT) | NOT DAMAGED | 688.00 | - |
| 1 | REAR BUMPER (CONSISTENT) | BROKEN | 1,015.00 | 855.00 |
| 2 | REAR BUMPER BRACKET LEFT & RIGHT (CONSISTENT) | NECESSARY | 90.00 | 81.00 |
| 1 | REAR BUMPER REFLECTOR (CONSISTENT) | NOT DAMAGED | 148.00 | - |
| 2 | REAR REVERSE SENSOR (CONSISTENT) | SCRATCHED | 280.00 | 200.00 |
| 1 | REAR BUMPER TOWING COVER (CONSISTENT) | NOT DAMAGED | 50.00 | - |
| 1 | REAR INNER PANEL (CONSISTENT) | TO REPAIR SEE LABOUR | 590.00 | - |

Report Ref No. CS3/ASM20014094/Bga3q2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|---|-------------------------|-------------------------------|-------------------|
| 1 | REAR BOOT (CONSISTENT) | TO REPAIR SEE LABOUR | 993.00 | - |
| 1 | REAR BOOT LOCK (CONSISTENT) | NOT DAMAGED | 97.00 | - |
| 1 | REAR BOOT EMBLEM 'LOGO'(CONSISTENT) | NECESSARY | 57.00 | 51.30 |
| 1 | REAR BOOT EMBLEM 'LANCER EX'(CONSISTENT) | NECESSARY | 52.00 | 46.80 |
| 1 | REAR BOOT EMBLEM 'MITSUBISHI'(CONSISTENT) | NECESSARY | 60.00 | 42.00 |
| 1 | REAR BOOT LAMP LEFT (CONSISTENT) | NOT DAMAGED | 274.00 | - |
| 1 | REAR BOOT LAMP RIGHT (CONSISTENT) | NOT DAMAGED | 274.00 | - |
| 1 | REAR FENDER LAMP LEFT (CONSISTENT) | NOT DAMAGED | 442.00 | - |
| 1 | REAR FENDER LAMP RIGHT (CONSISTENT) | NOT DAMAGED | 442.00 | - |
| 1 | REAR BOOT WEATHERSTRIP STRIP (CONSISTENT) | NOT DAMAGED | 95.00 | - |
| | LESS 20% DISCOUNT | | -2,802.40 | -718.34 |
| | | | 11,209.60 | 2,873.36 |
| | <u>LABOUR</u> | | | |
| | TO FIX & DISMANTLE AND REMOVE DAMAGED FRONTAL & REAR PORTIONS AFFECTED DAMAGED PORTION .INCLUSIVE OF THE REPAIR OF FRONT BONNET ,REAR INNER PANEL AND REAR BOOT. | | 1,200.00 | 800.00 |
| | TO APPLY ANTI RUST COAT AND AFFECTED AREAS. | | 120.00 | 60.00 |
| | TO CHECK WIRING . | | 120.00 | 30.00 |
| | WELDING AND CUTTING OF AFFECTED PANELS ,INCLUDING CHASSIS ALIGNMENT. | | 800.00 | 200.00 |
| | SPRAY PAINTING FOR FRONT AND REAR PORTIONS AFFECTED PARTS. | | 1,600.00 | 1,000.00 |
| | TO APPLY WATERPROOFING SEALER ON END PANELS. | | 120.00 | 60.00 |
| | DIAGNOSE ECU SYSTEM AND RESET ERROR CODE. | NOT NECESSARY | 120.00 | - |
| | REFOCUSING OF HEADLAMPS . | NOT NECESSARY | 180.00 | - |
| | 3D WHEEL ALIGNMENT. | NOT NECESSARY | 180.00 | - |
| | | | 4,440.00 | 2,150.00 |
| | GRAND TOTAL | | 15,649.60 | 5,023.36 |



Page No.:3 of 3

| RECOMMENDED COST OF LUMP SUM REPAIRS | 4,000.00 |
|--------------------------------------|----------|
| (TO ITS PRE-ACCIDENT CONDITION) | |

Report Ref No. CS3/ASM20014094/Bga3q2-1

LIM TEOW GUAN

Automotive Assessor

mont

HO LEONG CHUAN

Automotive Assessor