

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Acknowledged by Repairer:
Signature: _____
Date: _____

Vehicle No: SLD2782A
Chassis No: JMYSR0Y1AGU004436
Engine No: 4A92C04123

Report No : AMM2012-01

Date : 12.12.2020

Replacement of Damaged Parts

S/No.	Quantity	Description	Condition / Remarks	Repairer's Estimates	My Recommendation
1	1	Front Bumper	Damaged	\$ 1,158.00	2016 \$858.40 1,042.20 BR ✓
2	2	Front Bumper Bracket left & Right	Necessary	\$ 120.00	45.00 \$ 90.00 108.00 NECV ✓
3	1	Front. Bumper Top Chrome & Grille	Broken	\$ 454.00	\$ 374.00 408.60 BR ✓
4	1	Front Bumper Top Panel Garnish	Broken	\$ 163.00	\$ 146.70 NDX
5	1	Front Bumper Lower Chrome & Chille	Damaged	\$ 495.00	\$ 445.50 NDX
6	1	Front Bumper Foglamp cover Left	Damaged	\$ 60.00	\$ 54.00 NDX
7	1	Front Bumper Foglamp cover Right	Damaged	\$ 60.00	\$ 54.00 NDX
8	1	Front Bumper Foglamp left	Damaged	\$ 374.00	\$ 336.60 NDX
9	1	Front Bumper Foglamp Right	Damaged	\$ 374.00	\$ 336.60 NDX
10	2	Front Bumper Daylight Left and Right	Faulty	\$ 1,008.00	\$ 907.20 NDX
11	1	Front Bumper Towing Cover	Damaged	\$ 66.00	\$ 59.40 DL ✓
12	1	Front Bumper Lower Lip (carbon Fibre)	Damaged	\$ 350.00	\$ 315.00 DL ✓
13	1	Front Headlamp Left	Damaged	\$ 798.00	\$ 718.20 NDX
14	1	Front HeadLamp Right	Broken	\$ 798.00	\$ 718.20 NDX
15	1	Front Reinforcement	Impacted	\$ 490.00	\$ 441.00 NDX
16	1	Front Bonnet	Dented	\$ 809.00	\$ 728.10 DD X R
17	1	Front Bonnet Lock	Distorted	\$ 80.00	\$ 72.00 NDX
18	1	Front Bonnet Damper	Impacted	\$ 20.00	\$ 18.00 NDX
19	1	Front Fender left		\$ 688.00	\$ 619.20 DD ✓
20	1	Front Fender Right		\$ 688.00	\$ 619.20 NDX
21	1	Rear Bumper		\$ 1,015.00	\$ 855.00 913.50 BR ✓
22	2	Rear Bumper Bracket Left & Right		\$ 90.00	\$ 81.00 NECV ✓
23	1	Rear Bumper Reflector Left & Right		\$ 148.00	\$ 133.20 NDX
24	2	Rear Reverse sensor		\$ 280.00	\$ 252.00 SC ✓
25	1	Rear Bumper Towing Cover		\$ 50.00	\$ 45.00 NDX
26	1	Rear Inner Panel		\$ 590.00	\$ 531.00 DD X R
27	1	Rear Boot		\$ 993.00	\$ 893.70 DD X R
28	1	Rear Boot Lock		\$ 97.00	\$ 87.30 NDX
29	1	Rear Boot Emblems 'logo'		\$ 57.00	\$ 51.30 NECV ✓
30	1	Rear Boot Emblems 'LANCER EX'		\$ 52.00	\$ 46.80
31	1	Rear Boot Emblems 'Mitsubishi'		\$ 60.00	\$ 54.00
32	1	Rear Boot lamp Left		\$ 274.00	\$ 246.60
33	1	Rear Boot Lamp Right		\$ 274.00	\$ 246.60
34	1	Rear Fender Lamp Left		\$ 442.00	\$ 397.80 NDX
35	1	Rear Fender Lamp Right		\$ 442.00	\$ 397.80
36	1	Rear Boot Weather Strip		\$ 95.00	\$ 85.50 NDX
				\$ 14,012.00	\$ 11,209.60

Total (Parts): \$ 14,012.00 Less 20% \$ 11,209.60 3591.70
@ 20% 718.34

Labour Charges

26	To fix & dismantle and remove damaged Frontal & Rear Portions; affected damaged portion.	800.00	\$ 1,200.00 ✓
27	To apply anti rust coat and affected areas	60.00	\$ 120.00 ✓
28	To check wiring	30.00	\$ 120.00 ✓
29	Welding and cutting of affected panels, including chassis alignment.	280.00	\$ 800.00 ✓
30	Spray painting for Front and Rear Portions affected parts	1000.00	\$ 1,600.00 ✓
31	To apply waterproofing sealer on end panels	60.00	\$ 120.00 ✓
32	Diagnose ECU system and reset error code.		\$ 120.00 NNX
33	ReFocusing of Headlamps		\$ 180.00 NNX
34	3D Wheel Alignment		\$ 180.00 NNX

Total Labour: \$ 4,440.00

Total cost of repairs (Total cost of parts + Total Labour Cost) \$ 15,649.60

Less 20% \$ 3,129.92

2150.00

Repair days 5
L/S 4000.00

PARTS 3873.36
LABOUR 3150.00 2150.00
@ 20% 6073.36 5053.36
1010.67
4042.69