

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS21004256/BQF3E2

Date: 26/04/2021

REFERENCE

Handling Insurer: ECICS Limited Policy No: MPC21A00018600
Claimant Vehicle No : SLQ7175B **Insured Vehicle No :** SKU9836E
Date of Loss: 30/03/2021 Nature of Claim: TP Claim No: DMPC2100112H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLQ7175B**
Make & Model: KIA FORTE K3, 1.6 (A) Engine No: G4FGGH634431
Reg. Date: 20/07/2017 (Man. Year: 2017) Chassis No: KNAFJ411MH5717988
Colour: Black Odometer: 116785 km
Engine Capacity: 1591 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm
Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,457.45	4,765.77	9,691.68	67.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,760.00	2,160.00	2,600.00	54.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	19,217.45	6,925.77	12,291.68	63.96
Approved Total (Overridden) (\$\$)		5,550.00		
(\$\$)	19,217.45	5,550.00	13,667.45	71.12
+ GST 7.00/7.00% (\$\$)	1,345.22	388.50	956.72	71.12
Nett Amount (\$\$)	20,562.67	5,938.50	14,624.17	71.12

INSPECTION

Date of Assignment: 05/04/2021
Date Inspected: 05/04/2021 Inspected At: Team Autopro Pte Ltd (Sin Ming)
160 SIN MING DR
#01-14 SIN MING AUTO CITY
SINGAPORE 575722
Estimated Period of Repair: 8.0 days

Adjuster: Lim Teow Guan

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Apr 2021)
Parts:	143	KIA FORTE K3 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ7175B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Dented	1,460.00 FL	*1,277.00 FL
2	1		*FRONT DOOR BLACK TAPE	Necessary	85.00 FL	*48.00 FL
3	1		*FRONT DOOR OUTER HANDLE	Not Damaged	350.00 FL	*- FL
4	1		*FRONT DOOR WEATHERSTRIP	Torn	198.00 FL	*145.00 FL
5	1		*FRONT DOOR INNER LOCK	Not Damaged	415.00 FL	*- FL
6	1		*FRONT DOOR INNER LOCK STRIKER	Not Damaged	48.00 FL	*- FL
7	1		*FRONT DOOR INNER TRIMBOARD	Broken	884.00 FL	*522.30 FL
8	1		*FRONT DOOR GLASS REGULATOR	Broken	260.00 FL	*260.00 FL
9	1		*FRONT DOOR GLASS REGULATOR MOTOR	Not Damaged	750.00 FL	*- FL
10	1		*FRONT DOOR GLASS CHANNEL BRACKET	Not Damaged	185.00 FL	*- FL
11	1		*FRONT DOOR GLASS CHANNEL RUBBER	Not Damaged	195.00 FL	*- FL
12	1		*FRONT DOOR HINGE	Lower Bent	230.00 FL	*115.00 FL
13	1		*FRONT FENDER RH	Dented	948.30 FL	*426.00 FL
14	1		*FRONT FENDER INNER COWLING	Torn	326.70 FL	*126.00 FL
15	1		*SIDE MIRROR ASSY RH	Cut	875.20 FL	*105.00 FL
16	1		*DOOR CENTRE PILLAR RH	Not Damaged	580.00 FL	*- FL
17	1		*ROCKER PANEL RH	Dented	580.00 FL	*580.00 FL
18	1		*FRONT LOWER ARM RH	Dented	500.18 FL	*286.00 FL
19	1		*FRONT KNUCKLE ARM RH	Dented	999.20 FL	*385.00 FL
20	1		*FRONT KNUCKLE ARM BEARING RH	Jammed	688.20 FL	*170.00 FL
21	1		*FRONT SHOCK ABSORBER RH	Dented	600.50 FL	*290.00 FL
22	1		*STEERING RACK	Not Damaged	1,800.00 FL	*- FL
23	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
24	1		*FRONT DOOR SEALANT	Necessary	100.00 FS	*40.00 FS
25	1		*FRONT DOOR SPEAKER	Broken	210.00 FS	*80.00 FS
26	1		*FRONT DOOR INNER TRIMBOARD CLIPS	Necessary	50.00 FS	*30.00 FS
27	1		*FRONT DOOR OUTER MOULDING	Dented	485.00 FS	*74.00 FS
28	1		*FRONT FENDER SEALANT	Not Necessary	100.00 FS	*- FS
29	1		*FRONT FENDER INNER COWLING CLIPS	Necessary	50.00 FS	*30.00 FS
30	1		*SIDE MIRROR SEAL	Not Necessary	60.00 FS	*- FS
31	1		*DOOR CENTRE PILLAR SEALANT	Not Necessary	100.00 FS	*- FS
32	1		*ROCKER PANEL SEALANT	Necessary	100.00 FS	*50.00 FS
33	1		*FRONT ALLOY RIM RH (LOCAL REPAIR)	Cut	980.00 FS	*200.00 FS
34	1		*FRONT TYRE RH	Not Damaged	480.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,753.28	5,239.30
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,295.83	473.53
Total Parts (\$\$)	14,457.45	4,765.77

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R FRONT DOOR COMPONENT	New	150.00	80.00
2	R&R FRONT UNDER CARRIAGE	New	300.00	150.00
3	R&R FRONT TYRE AND BALANCING	New	100.00	0.00
4	R&R STEERING RACK	New	150.00	0.00
5	WHEEL ALIGNMENT	New	180.00	60.00
6	DIAGNOSTIC RESET FAULT CODE	New	300.00	0.00
7	CONDUCT WATER LEAK TEST	New	180.00	0.00
8	CHECK WIRING	New	100.00	30.00
9	UPHOLSTERY	New	300.00	0.00
10	PANEL BEATING	New	1,400.00	1,000.00
11	RUST PROOFING	New	200.00	40.00
12	SPRAY PAINTING	New	1,400.00	800.00
Gross Labour Cost (\$)			4,760.00	2,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >