LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21004259/R1TF3E2

Date: 28/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700027433

Claimant Vehicle VP70424

No: SLQ9203R

Date of Loss: 26/03/2021 Nature of Claim: TP Claim No: 1468293539SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: XD7043A

 Make & Model:
 UD TRUCKS CONDOR PK, 7.0 D (M)
 Engine No:
 GH11711620

 Reg. Date:
 13/05/2013 (Man. Year: 2013)
 Chassis No:
 GKB5E00115

 Colour:
 Multi-colour
 Odometer:
 506127 km

Engine Capacity: 10837 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5 Rear Tyre Size: 295/80 R22.5 (D)
Front Left Side: KPATOS 8 mm Rear Left Side: KPATOS 8/8 mm
Front Right Side: KPATOS 8 mm Rear Right Side: KPATOS 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 05/04/2021

Date Inspected: 20/04/2021 Inspected At: 7 Soon Lee Street #01-39 Repairer: Lys Engineering - Pioneer (HQ)

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*FRT BUMPER LH	Bent	0.00 F	*- F
2	1	*FRT SIGNAL LAMP LH	Cracked	0.00 F	*-F
3	1	*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*- F
4	1	*FRT LH SIDE LAMP	Cracked	0.00 F	*-F
5 F=Fra	2 anchise part.	*FRONT BUMPER COVER GARNISH	Cracked	0.00 F	*- F
			Total Parts (S\$)	0.00	0.00
		Report was unsubmitted du	ing this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >