

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG21004272/EVF3E2

**Date:** 06/05/2021

### REFERENCE

Insured/Claimant:	MOHAMED NIZAR BIN SALIM	Policy No:	1900083983	
Date of Loss:	02/04/2021	Nature of Claim:	OD	Claim No: 1111602317SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJM8990C</b>	Engine No:	3A92UHS1042
Make & Model:	MITSUBISHI ATTRAGE, 1.2 (A)	Chassis No:	MMBSTA13AKH001518
Reg. Date:	04/04/2019 (Man. Year: 2018)	Odometer:	19112 km
Colour:	Grey		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	S\$57,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

*The above values represent the remaining tyre tread depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,809.00	2,275.33	4,533.67	66.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,310.00	3,145.00	1,165.00	27.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,119.00</b>	<b>5,420.33</b>	<b>5,698.67</b>	<b>51.25</b>
<b>- Excess (S\$)</b>	300.00	300.00	0.00	0.00
<b>(S\$)</b>	10,819.00	5,120.33	5,698.67	52.67
<b>+ GST 7.00/7.00% (S\$)</b>	757.33	358.42	398.91	52.67
<b>Nett Amount (S\$)</b>	<b>11,576.33</b>	<b>5,478.75</b>	<b>6,097.58</b>	<b>52.67</b>

### INSPECTION

Date of Assignment:	06/04/2021	
Date Inspected:	05/04/2021 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	6.0 days	

**Adjuster:** CHEN TSUE YEE

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
2	1		*FACE, FR BUMPER	Broken	706.00 F	*706.00 FL
3	1		*MARK, THREE-DIA	Necessary	70.00 F	*70.00 FL
4	1		*GRILLE, RADIATOR	Not Necessary	557.00 F	*- FL
5	1		*COVER, HEADLAMP SUPT PANEL	Broken	62.00 F	*62.00 FL
6	1		*BRACKET, FR BUMPER, RH	Broken	13.00 F	*13.00 FL
7	1		*GRILLE, FR UNDER	Crushed	165.00 F	*165.00 FL
8	1		*AIR DAM, SIDE, FR RH	Not Necessary	18.00 F	*- FL
9	1		*GARNISH, FR BUMPER, RH	Not Necessary	127.00 F	*- FL
10	1		*HOOD	Dented	737.00 F	*737.00 FL
11	1		*INSULATOR, HOOD	Not Necessary	177.00 F	*- FL
12	1		*LATCH, HOOD	Not Necessary	69.00 F	*- FL
13	1		*FENDER, FR RH	Dented	500.00 F	*500.00 FL
14	1		*SHIELD, FR WHEELHOUSE, RH	Not Necessary	98.00 F	*- FL
15	1		*PANEL ASSY, FR END	Not Necessary	1,055.00 F	*- FL
16	1		*PANEL, AIR GUIDE, RH	Not Necessary	11.00 F	*- FL
17	1		*HEADLAMP ASSY, RH	Broken	663.00 F	*663.00 FL
18	1		*TANK, WINDSHIELD WASHER	Not Necessary	75.00 F	*- FL
19	1		*MOTOR, WINDSHIELD WASHER	Not Necessary	30.00 F	*- FL
20	1		*BODY KIT ATTRAGE, TITANLUM GREY, U17	Not Necessary	1,643.00 F	*- FL
21	1		*COVER,FR BUMPER (Supplementary)	Missing	13.00 F	*13.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,809.00	2,949.00
- List Item Discount on L Items 0.00/23.00% (\$)	0.00	673.67
Total Parts (\$)	6,809.00	2,275.33

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	RENEW FRT AIRDAM, FRT BUMPER, FRT FENDER RH, BONNET, FRT SUPPORT PANEL. REPAIR FRT DOOR RH	New	1,800.00	1,125.00
2	SPRAY PAINT FOR FRT AIRDAM, FRT BUMPER, FRT FENDER, RH, FRT DOOR RH, FRT SUPPORT PANEL, BONNET	New	2,100.00	1,750.00
3	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	0.00
4	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
6	APPLY SEALANT FOR ACCIDENT PORTION	New	40.00	40.00
7	REMOVE & INSTALL FRT AIRDAM	New	100.00	80.00
<b>Gross Labour Cost (S\$)</b>			<b>4,310.00</b>	<b>3,145.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >