



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/CHEE SHU HUI (ZHU SHUHUI)
	Reg No/Reg Date	SMD9367H*ECB / 12/09/201
	Date In/Mileage	03/04/2021/ 0
	Chassis No	KNAF3416MK5013618
	Engine No	G4FGJH703967
	Make/Model	KIA/CERATO 1.6 A SX G335
	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
LAX00000	Credit	05/04/2021/ 12:58	QUK	282 / Kevin Leong	31468				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
E PNT88000	REPLACE REAR BUMPER, REAR RH FENDER, BOOT, REAR RH TAIL LIGHT PANEL & AFFECTED AREA								4480.00
E PNT98000	REPAIR ON END PANEL								
E PNT88000	PAINT WORK ON REAR BUMPER, BOOT, REAR RH FENDER, END PANEL & REAR RH TAIL LAMP PANEL								1750.00
E PNT88000	REMOVE & INSTALL REAR PARKING ASSIST								120.00
E PNT88000	REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR								120.00
E PNT88000	REMOVE & INSTALL REAR SEAT FOR FACILITATE REPAIR								120.00
E PNT88000	REPLACE REAR WINDSCREEN GLASS								240.00
M SUNDRY	TO APPLY WINDSCREEN SEALANT								80.00
M SUNDRY	TO SUPPLY WINDSCREEN SOLAR FILM								220.00
E PNT88000	TO TRANSFER REAR BOOT ATTACHMENT TO NEW PANEL								120.00
M SUNDRY	PERFORM RUST PREVENTION								120.00
M SUNDRY	TO APPLY BODY SEALANT ON AFFECTED AREA								80.00
A 54900099	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								30.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								120.00
M SUNDRY	TO SUPPLY C & C EMBLEM								50.00
M SUNDRY									50.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/CHEE SHU HUI (ZHU SHUHUI)
	Reg No/Reg Date	SMD9367H*ECB / 12/09/201
	Date In/Mileage	03/04/2021/ 0
	Chassis No	KNAF3416MK5013618
	Engine No	G4FGJH703967
	Make/Model	KIA/CERATO 1.6 A SX G335
	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	05/04/2021/ 12:58	QUK	282 / Kevin Leong	31468

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
SUNDRIES				
M COVER-RR BUMPER	1.00	651.00	20.00	520.80
M COVER-RR BUMPER LWR	1.00	241.00	20.00	192.80
M COVER-RR BUMPER UNDER,LH	1.00	33.00	20.00	26.40
M COVER-RR BUMPER FOG LAMP,RH	1.00	19.00	20.00	15.20
M LAMP ASSY-SIDE T/SIGNAL,RH	1.00	181.00	20.00	144.80
M EXTN WIRING ASSY-BWS	1.00	207.00	20.00	165.60
M BRACKET-RR BEAM UPR MTG,RH	1.00	9.00	20.00	7.20
M BRACKET-RR BEAM UPR MTG,LH	1.00	9.00	20.00	7.20
M BRACKET-RR BEAM LWR,CTR	1.00	6.00	20.00	4.80
M BRACKET-RR BEAM LWR MTG	2.00	6.00	20.00	9.60
M BEAM-RR BUMPER	1.00	318.00	20.00	254.40
M ANTENNA ASSY-SMARTKEY	1.00	46.00	20.00	36.80
M STAY-RR BUMPER RH	1.00	65.00	20.00	52.00
M STAY-RR BUMPER LH	1.00	65.00	20.00	52.00
M BRACKET ASSY-RR BPR SIDE UPR,L	1.00	25.00	20.00	20.00
M BRACKET-ASSY RR BPR SIDE UPR,R	1.00	31.00	20.00	24.80
M ULTRASONIC SENSOR ASSY-BWS	1.00	163.00	20.00	130.40
M ULTRASONIC SENSOR ASSY-BWS	1.00	163.00	20.00	130.40
M EMBLEM-CERATO	1.00	28.00	20.00	22.40
M LOGO ASSY-KIA SUB	1.00	32.00	20.00	25.60
M GLASS ASSY-REAR WINDOW	1.00	447.00	20.00	357.60
M W/STRIP-TRUNK LID OPNG	1.00	100.00	20.00	80.00
M LATCH ASSY-TRUNK LID	1.00	112.00	20.00	89.60
M STRIKER ASSY-TRUNK LID	1.00	40.00	20.00	32.00
M TRIM ASSY-RR TRANSVERSE	1.00	41.00	20.00	32.80
M PANEL ASSY-QUARTER OUTER,RH	1.00	1349.00	20.00	1079.20
M PANEL ASSY-RR COMB LAMP HSG,RH	1.00	135.00	20.00	108.00
M PANEL ASSY-TRUNK LID	1.00	1297.00	20.00	1037.60
M PANEL ASSY-BACK	1.00	324.00	20.00	259.20
M HINGE ASSY-TRUNK LID,LH	1.00	97.00	20.00	77.60
M HINGE ASSY-TRUNK LID,RH	1.00	97.00	20.00	77.60
M PANEL & FRAME ASSY-PKG TRAY,RR	1.00	312.00	20.00	249.60

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/CHEE SHU HUI (ZHU SHUHUI)
	Reg No/Reg Date	SMD9367H*ECB / 12/09/201
	Date In/Mileage	03/04/2021/ 0
	Chassis No	KNAF3416MK5013618
	Engine No	G4FGJH703967
	Make/Model	KIA/CERATO 1.6 A SX G335
	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	05/04/2021/ 12:58	QUK	282 / Kevin Leong	31468

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M LAMP ASSY-CENTER GARNISH	1.00	690.00	20.00	552.00
M LAMP ASSY-REAR COMB INSIDE,RH	1.00	608.00	20.00	486.40
M LAMP ASSY-REAR COMB OUTSIDE,RH	1.00	675.00	20.00	540.00

Estimate

Confirm & accepted by

	Nett	14,602.40
7% GST on	14602.40	1022.17
Total Payable		15,624.57

 Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.