

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21004283/T1RA3Q2
Date: 29/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070138796
Claimant Vehicle No :	SHA7008H	Insured Vehicle No :	SMV3016R
Date of Loss:	02/04/2021	Nature of Claim:	TP
		Claim No:	8828418643SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA7008H		
Make & Model:	HYUNDAI AE IONIQ HEV DCT, 1.6 (A)	Engine No:	G4LEKU296070
Reg. Date:	26/06/2019 (Man. Year: 2019)	Chassis No:	KMHC851CVKU164385
Colour:	Blue	Odometer:	0 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,709.80	2,188.12	1,521.68	41.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,560.00	1,055.00	505.00	32.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,269.80	3,243.12	2,026.68	38.46
+ GST 7.00/7.00% (S\$)	368.89	227.02	141.87	38.46

Nett Amount (S\$)	5,638.69	3,470.14	2,168.55	38.46
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (4.0 x S\$125.19/day) (S\$)		500.76		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,172.90		

INSPECTION

Date of Assignment: 05/04/2021

Date Inspected: 05/04/2021

Estimated Period of Repair: 3.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Repair	430.90 FL	*- FL
2	1		*FRONT BUMPER BRACKET LH	Not Necessary	35.00 FL	*- FL
3	1		*FRONT FENDER LH	Repair	588.80 FL	*- FL
4	1		*FENDER EMBLEM -BLUE DRIVE	Necessary	26.60 FL	*26.60 FL
5	1		*FRONT BUMPER CENTRE MOULDING	Cut	368.50 FL	*368.50 FL
6	1		*FRONT WHEEL HUB COVER	Cracked	364.40 FL	*346.40 FL
7	1		*HEAD LAMP ASSY LH	Cut	1,993.65 FL	*1,993.65 FL
8	1		*FRONT DAY LIGHT LH	Not Necessary	642.50 FL	*- FL
9	1		*FRONT SIDE GRILLE LH	Not Necessary	186.90 FL	*- FL
					Sub Total (S\$)	4,637.25
					- List Item Discount on L Items 20.00/20.00% (S\$)	927.45
					Total Parts (S\$)	3,709.80
						2,188.12

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	750.00	525.00
2	SPRAY PAINT	New	750.00	500.00
3	CHECK LIGHTING	New	60.00	30.00
Gross Labour Cost (\$\$)			1,560.00	1,055.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >