

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/TMI21004286/T1QF3E2**Date:** 10/05/2021REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MM000075
<b>Claimant Vehicle No :</b>	SHA4397D	<b>Insured Vehicle No :</b>	SLG6253T
Date of Loss:	02/04/2021	Nature of Claim:	TP
		Claim No:	M2101591

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHA4397D</b>	Engine No:	G4LEJU192173
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Chassis No:	KMHC851CVKU141685
Reg. Date:	23/04/2019 (Man. Year: 2019)	Odometer:	0 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,633.04	3,558.28	74.76	2.06
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,400.00	880.00	520.00	37.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>5,044.04</b>	<b>4,449.28</b>	<b>594.76</b>	<b>11.79</b>
<b>+ GST 7.00/7.00% (S\$)</b>	353.08	311.45	41.63	11.79
<b>Nett Amount (S\$)</b>	<b>5,397.12</b>	<b>4,760.73</b>	<b>636.39</b>	<b>11.79</b>

INSPECTION

Date of Assignment:	05/04/2021	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	06/04/2021	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang)
			59 Loyang Drive
			Singapore 508969
Estimated Period of Repair:	2.0 days		

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 10 May 2021)
<b>Parts:</b>	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHA4397D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*FRT BUMPER ASSY	Cracked	430.90 FL	-	*430.90 FL
2	1		*HEADLAMP ASSY RH	Cracked	1,993.65 FL	-	*1,993.65 FL
3	1		*FRT BUMPER MOULDING	Cut	368.50 FL	-	*368.50 FL
4	1		*FRT DAY LIGHT ASSY RH	Cracked	642.50 FL	-	*642.50 FL
5	1		*FRT BUMPER SIDE GRILLE RH	Not Necessary	93.45 FL	-	*- FL
6	1		*FRT BUMPER SIDE BRACKET RH	Necessary	35.00 FL	-	*35.00 FL
<b>Supplementary #1</b>							
7	1		*HEADLAMP SUPPORT PANEL	Cracked	949.30 FL	-	*949.30 FL
8	1		*FRT BUMPER BRACKET RH	Cracked	28.00 FL	-	*28.00 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>4,541.30</b>	<b>4,447.85</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	908.26	889.57
<b>Total Parts (\$)</b>	<b>3,633.04</b>	<b>3,558.28</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	OD/TP Case (Insurer)	11.00	11.00
<b>Sub Total (\$\$)</b>			<b>11.00</b>	<b>11.00</b>

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	700.00	350.00
2	SPRAYPAINT	New	600.00	500.00
3	CHECK WIRING	New	50.00	30.00
4	TUFF KOTE	New	50.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,400.00</b>	<b>880.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >