

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21004290/DRS3Q2
Date: 25/05/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900103121
Claimant Vehicle No :	SLG7577C	Insured Vehicle No :	SML8504T
Date of Loss:	02/04/2021	Nature of Claim:	TP
		Claim No:	1302300409SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG7577C	Engine No:	M16A2081091
Make & Model:	SUZUKI VITARA, 1.6 GLX (A)	Chassis No:	TSMLYD21S00268893
Reg. Date:	13/10/2016 (Man. Year: 2016)	Odometer:	65591 km
Colour:	Beige		
Engine Capacity:	1586 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,675.50	8,244.30	5,431.20	39.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,800.00	1,670.00	1,130.00	40.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	16,475.50	9,914.30	6,561.20	39.82
	+ Loss of Use (9.0 x S\$80.00/day) (S\$)	720.00		
	+ Doc/Search Fee (S\$)	7.45		

Nett Liability (S\$)	10,641.75
Global Sum Settlement (S\$)	10,600.00

INSPECTION

Date of Assignment: 05/04/2021

Date Inspected: 06/04/2021 Inspected At: Alfred Auto Services & Supplies (HQ)
Blk 5035, Ang Mo Kio Ave 3, #01-351, Ang Mo Kio Industrial Park 2
Singapore 569538

Estimated Period of Repair: 7.0 days

Adjuster: BRYAN TANI**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Bent	1,020.00 F	*1,020.00 FL
2	1		*FRONT BONNET SPONGE	Bent	498.00 F	*498.00 FL
3	10		*FRONT BONNET SPONGE CLIPS	Necessary	65.00 FS	*15.00 FS
4	2		*FRONT BONNET HINGER	Repair	296.00 F	*- FL
5	1		*FRONT FOG LAMP (RH)	Mtg Cracked	499.80 F	*499.80 FL
6	1		*FRONT FOG LAMP HOLDER (RH)	Broken	186.50 F	*186.50 FL
7	1		*WIPER TANK ASSY	Deformed / Mtg Cracked	508.00 F	*125.30 FL
8	1		*HEAD LAMP (RH)	Broken	2,499.05 F	*2,499.05 FL
9	1		*HEAD LAMP MODULE	Not Necessary	989.00 F	*- FL
10	1		*HEAD LAMP BRACKET (RH)	Broken	56.00 F	*56.00 FL
11	1		*FRONT GRILLE ASSY	Serviceable	468.40 F	*- FL
12	1		*FRONT GRILLE LOGO	Serviceable	332.50 F	*- FL
13	10		*FRONT GRILLE CLIPS	Serviceable	60.00 F	*- FL
14	1		*FRONT BUMPER	Torn	998.80 F	*998.80 FL
15	1		*FRONT BUMPER GRILLE (CTR)	Not Necessary	189.20 F	*- FL
16	1		*FRONT BUMPER TOWING COVER	Dislodged	26.00 F	*26.00 FL
17	1		*FRONT BUMPER LAMP LED	Mtg Cracked	869.80 F	*869.80 FL
18	1		*FRONT BUMPER CORNER PAD	Distorted	320.00 F	*320.00 FL
19	1		*FRONT BUMPER CENTRE LOWER	Distorted	330.00 F	*330.00 FL
20	1		*FRONT BUMPER LOWER	Not Necessary	180.90 F	*- FL
21	12		*FRONT BUMPER CLIPS	Necessary	72.00 FS	*30.00 FS
22	1		*FRONT BUMPER SIDE CATCH	Not Necessary	28.80 F	*- FL
23	1		*FRONT BUMPER RETAINER	Broken	29.30 F	*29.30 FL
24	1		*FRONT BUMPER REINFORCEMENT	Dented	729.85 F	*729.85 FL
25	1		*FRONT RH FENDER	Dented	325.50 F	*325.50 FL
26	1		*FRONT RH FENDER GARNISH	Bent	110.60 F	*110.60 FL
27	10		*FRONT RH FENDER GARNISH CLIPS	Necessary	60.00 FS	*15.00 FS
28	1		*FRONT RH FENDER DUST COVER	Deformed	127.50 F	*127.50 FL
29	10		*FRONT RH DUST COVER CLIPS	Necessary	60.00 FS	*15.00 FS
30	1		*DISTANCE SENSOR	O/S Damaged	252.00 F	*126.00 FL
31	1		*DISTANCE HARNES WIRE	Not Necessary	288.00 F	*- FL
32	1		*SUPPORT PANEL	Repair	910.00 F	*- FL
33	1		*FENDER TOP GARNISH	Necessary	199.00 F	*199.00 FL
34	1		*COOLANT	Not Necessary	90.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Sub Total (\$)	13,675.50	9,152.00
					- List Item Discount on L Items 0.00/10.00% (\$)	0.00	907.70
					Total Parts (\$)	13,675.50	8,244.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT WIRING ,CHECKING & MEMORY TO STANDARD SETTING & REFOCUS HEAD LAMP	New	120.00	30.00
2	TO REPAIR ,KNOCKING ,STRAIGHTENING ALL ACCIDENT AFFECTED AREA	New	900.00	800.00
3	TO RESPRAY PAINTING ON ALL ACCIDENT DAMAGE AFFECTED AREA	New	1,200.00	800.00
4	TO RUST PROOF ALL ACCIDENT AFFECTED AREA	New	120.00	40.00
5	TO REMOVE & REFIT RADIATOR ,FAN MOTOR ASSY & ALL AFFECTED AREA	New	180.00	0.00
6	TO REMOVE & REFIT AIR-CON CONDENSER ,PIPE & TOP-UP GAS & OIL	New	280.00	0.00
Gross Labour Cost (\$\$)			2,800.00	1,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >