

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE	PTE LTD	Ref:	CS3/ASM21004293/R1vce2	
	8 SHENTON WAY TOWERSINGAPOR		Date	16/04/2021	
	ATTN: TAN JUN H	ONG	Code	: ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHD 6741P	Veh. Inspected	SLK 6391G	
	Policy No.	VFX/P2419138	Coverage (\$)	0.00	
	Claim No.	S1M0373L	Excess (\$)	0.00	
	Assign From	TAN JUN HONG	Assign Date	05/04/2021	
2.	Vehicle Particulars & Condition				
	Make & Model	HONDA VEZEL 1.5X CVT	c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	RU11203356	Colour	BLACK	
	Odometer	109838 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	215/60 R16	DUNLOP	6 mm	
	L/H Front Tyre	215/60 R16	DUNLOP	6 mm	
	R/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
	L/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
4.	Description of Damages				
	THE VEHICLE SUS	STAINED DAMAGES AT THE REA			
5.	General Information				
	Accident Date	31/03/2021	Inspect Date / Time	06/04/2021 (12:49 PM)	
	Survey held at	NO.5 DEFU LANE 10 #01-582	•		
	Repairer	HENG MOTOR SERVICES			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000				
5b.	D. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				

Report Ref No. CS3/ASM21004293/R1vce2

Inspected By

Automotive Assessor

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

DECD Asta Consultant OAE Utanasad Assault

REGD Auto Consultant-SAE, Licensed Appraiser

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$