

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21004295/ABS3Q2
Date: 19/10/2021REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MFL0006849
Claimant Vehicle No :	GBJ6296Y	Insured Vehicle No :	SLK3651B
Date of Loss:	04/04/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0001497

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ6296Y		
Make & Model:	TOYOTA DYNA, 3.0 D (M)	Engine No:	1KD2851488
Reg. Date:	26/06/2019 (Man. Year: 2019)	Chassis No:	KDY2318038173
Colour:	White	Odometer:	50918 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/70 R15C	Rear Tyre Size:	145 R13
Front Left Side:	Linglong 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Linglong 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,716.65	5,067.07	9,649.58	65.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,660.00	1,430.00	3,230.00	69.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,376.65	6,497.07	12,879.58	66.47
Approved Total (Overridden) (S\$)		5,200.00		

Nett Amount (S\$)	19,376.65	5,200.00	14,176.65	73.16
+ Car Rental (4.0 x S\$150.00/day + 7.00% GST) (S\$)		642.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		5,878.45		
Global Sum Settlement (S\$)		5,800.00		

INSPECTION

Date of Assignment: 05/04/2021

Date Inspected: 05/04/2021

Estimated Period of Repair: 6.0 days

Inspected At:

Smartone Auto Pte Ltd (HQ)
 8 Kaki Bukit Avenue 4, #08-09 Premier @ Kaki Bukit
 Singapore 415875

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:		(Last Synchronised: 06 Oct 2021)
Parts:	N/A	TOYOTA DYNA 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ6296Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,370.00 FL	*1,370.00 FL
2	4		*TAILGATE HINGE	Dented (2 PCS ONLY)	660.00 FL	*152.00 FL
3	1		*TAILGATE SIDE LOCK LH	Not Necessary	125.00 FL	*- FL
4	1		*TAILGATE STOPPER RUBBER LH	Not Necessary	35.00 FL	*- FL
5	1		*TAILGATE STOPPER BRACKET LH	Not Necessary	175.00 FL	*- FL
6	1		*SIDE GATE SAFETY LOCK LH	Not Necessary	132.10 FL	*- FL
7	1		*REAR NUMBER PLATE HOLDER	Bent	184.00 FL	*184.00 FL
8	2		*REAR NUMBER PLATE LAMP	Not Necessary	90.00 FL	*- FL
9	2		*TAIL LAMP	Cracked	490.00 FL	*490.00 FL
10	2		*TAIL LAMP LOWER REFLECTOR	Cracked	110.40 FL	*110.40 FL
11	2		*TAIL LAMP SUPPOER BRACKET	Bent	194.00 FL	*194.00 FL
12	1		*REAR STICKER DYNA	Necessary	45.00 FL	*45.00 FL
13	1		*REAR END PANEL	Dented	1,245.00 FL	*495.00 FL
14	2		*REAR END PANEL REFLECTOR	Cracked	139.60 FL	*139.60 FL
15	1		*REAR TOOLS BOX	Dented	467.40 FL	*467.40 FL
16	1		*REAR TOOLS BOX BRACKET	Bent	198.70 FL	*198.70 FL
17	1		*REAR END CROSS MEMBER	Dented	2,280.00 FL	*748.00 FL
18	1		*REAR 2ND END CROSS MEMBER	Repair	2,467.00 FL	*- FL
19	1		*SPARE TYRE CHAIN BOX	Damaged	398.00 FL	*398.00 FL
20	1		*REAR EXHAUST	Bent	790.00 FL	*489.00 FL
21	2		*REAR EXHAUST MOUNTING	Torn (1 PCS ONLY)	136.00 FL	*35.00 FL
22	1		*REAR EXHAUST HOLDER	Not Necessary	170.00 FL	*- FL
23	1		*REAR NUMBER PLATE	Bent	80.00 FS	*50.00 FS
24	1		*TAIL GATE COMPANY STICKER	Necessary	400.00 FS	*180.00 FS
25	1		*TAIL GATE AR STICKER	Not Necessary	80.00 FS	*- FS
26	1		*TAIL GATE 70KM/H STICKER	Necessary	40.00 FS	*15.00 FS
27	1		*TAIL GATE 13 PAX STICKER	Necessary	40.00 FS	*15.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*TAILGATE AUMINIUM COVER (SPECIAL TYPE)	Dented	680.00 FS	*400.00 FS
29	1		*TAILGATE STICKER (1550KG)	Necessary	350.00 FS	*40.00 FS
30	1		*REAR END PANEL SEALANT	Necessary	180.00 FS	*60.00 FS
31	1		*REAR END PANEL STICKER (BLACK)	Necessary	60.00 FS	*20.00 FS
32	1		*REAR FLOOR ALUMINIUM COVER (SPECIAL TYPE)	Not Necessary	2,800.00 FS	*- FS
33	1		*REAR STEP BAR (SPECIAL TYPE)	Bent	350.00 FS	*150.00 FS
34	1		*REAR SPARE TYRE (BIG)	Not Necessary	480.00 FS	*- FS
35	1		*REAR SPARE TYRE RIM (BIG)	Not Necessary	250.00 FS	*- FS
					Sub Total (S\$)	17,692.20
					- List Item Discount on L Items 25.00/25.00% (S\$)	2,975.55
					Total Parts (S\$)	14,716.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEAT ,WELD ,CUT ,ADJUST ,KNOCK	New	1,800.00	800.00
2	TO PUTTY ,SPRAY PAINT ,POLISH WAX	New	1,600.00	550.00
3	REMOVE AND REFIX REAR FLOOR AND TAILGATE COVER ALUMINIUM	New	650.00	0.00
4	REAR CHASSIS ALIGHMENT	New	250.00	0.00
5	REMOVE AND REFIX REAR EXHAUST PIPE	New	180.00	80.00
6	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			4,660.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >