

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21004300/KRA3Q2
Date: 07/01/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100405043
Claimant Vehicle No :	SFQ8101D	Insured Vehicle No :	SKR7929A
Date of Loss:	03/04/2021	Nature of Claim:	TP
		Claim No:	2396048168SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFQ8101D		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CVT (A)	Engine No:	1ZRX585917
Reg. Date:	20/01/2017 (Man. Year: 2016)	Chassis No:	MR053REH104554597
Colour:	Metallic Blue	Odometer:	78760 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,248.16	8,169.94	1,078.22	11.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,355.00	2,010.00	345.00	14.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,603.16	10,179.94	1,423.22	12.27
+ GST 7.00/7.00% (S\$)	812.22	712.60	99.62	12.27

Nett Amount (S\$)	12,415.38	10,892.54	1,522.84	12.27
+ Loss of Use (9.0 x S\$60.00/day) (S\$)		540.00		
Nett Liability (S\$)		11,432.54		

INSPECTION

Date of Assignment: 05/04/2021

Date Inspected: 06/04/2021

Estimated Period of Repair: 7.0 days

Inspected At:

S & H Motor Pte Ltd (Sin Ming)
 160 Sin Ming Drive #07-02, Sin Ming AutoCity
 Singapore 575722

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	867.60 FL	*867.60 FL
2	1		*RH BONNET HINGE	Bent	78.50 FL	*78.50 FL
3	1		*BONNET LOCK	Distorted	148.90 FL	*148.90 FL
4	1		*LH BONNET HINGE	Distorted	78.50 FL	*78.50 FL
5	1		*RH HEAD LAMP	Mtg Cracked	1,590.80 FL	*1,590.80 FL
6	1		*LH HEAD LAMP	Mtg Cracked	1,590.80 FL	*1,590.80 FL
7	1		*FRONT GRILLE	Cracked	276.85 FL	*276.85 FL
8	1		*SET FRONT GRILLE CLIPS	Necessary	35.00 FL	*35.00 FL
9	1		*RH FRONT FENDER	Bent	390.95 FL	*390.95 FL
10	1		*RH FRONT FENDER BADGE DUAL VVTI	Necessary	80.10 FL	*80.10 FL
11	1		*FRONT BUMPER	Bent	489.60 FL	*489.60 FL
12	1		*FRONT BUMPER CENTRE GRILLE	Cracked	120.20 FL	*120.20 FL
13	1		*FRONT BUMPER SPONGE	Cracked	110.40 FL	*110.40 FL
14	1		*FRONT BUMPER REINFORCEMENT	Bent	276.80 FL	*276.80 FL
15	1		*RH FRONT BUMPER RETAINER	Distorted	50.40 FL	*50.40 FL
16	1		*LH FRONT BUMPER RETAINER	Distorted	50.40 FL	*50.40 FL
17	1		*RH FRONT BUMPER BRACKET	Repair	127.60 FL	*- FL
18	1		*LH FRONT BUMPER BRACKET	Repair	127.60 FL	*- FL
19	1		*FRONT BUMPER LOWER DUST COVER	Serviceable	157.20 FL	*- FL
20	1		*SET FRONT BUMPER LOWER DUST COVER CLIPS	Not Necessary	55.20 FL	*- FL
21	1		*FRONT SUPPORT PANEL	Bent	570.40 FL	*570.40 FL
22	1		*FRONT SUPPORT PANEL TOP GARNISH	Distorted	130.80 FL	*130.80 FL
23	1		*SET FRONT SUPPORT PANEL TOP GARNISH CLIPS	Necessary	35.00 FL	*35.00 FL
24	1		*BONNET LOCK CENTRE BRACKET	Bent	80.90 FL	*80.90 FL
25	1		*AIR CON CONDENSOR	Bent	876.75 FL	*876.75 FL
26	1		*AIR CON CONDENSOR PIPE INLET	Dented	487.60 FL	*439.10 FL
27	1		*AIR CON CONDENSOR PIPE OUTLET	Dented	476.80 FL	*402.80 FL
28	1		*RADIATOR	Punctured	980.50 FL	*980.50 FL
29	1		*RADIATOR AUTO FAN COWLING	Cracked	170.80 FL	*170.80 FL
30	1		*RADIATOR AUTO FAN MOTOR	Dented	298.60 FL	*298.60 FL
31	1		*RADIATOR AUTO FAN BLADE	Cracked	150.70 FL	*150.70 FL
32	1		*FRONT NUMBER PLATE	Bent	45.00 FS	*45.00 FS
33	1		*ENGINE COOLANT	Necessary	30.00 FS	*30.00 FS
34	1		*RADIATOR TOP COVER BRACKET	Distorted	95.00 FL	*95.00 FL
35	1		*FRONT SPARE TAMK	Dented	190.10 FL	*155.70 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*FRONT WIPER TANK	Dented	219.10 FL	*170.40 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					11,541.45	10,868.25
- List Item Discount on L Items 20.00/25.00% (\$\$)					2,293.29	2,698.31
Total Parts (\$\$)					9,248.16	8,169.94

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND CHECK AIR CON CONDENSER ,DRYER ,ALUMINIUM PIPES ,VALVES AND REINSTALL COMPONENTS AND VACUUM AND CHARGE REFRIGERANT R134a CHECK FOR LEAKAGE AND FULL FUNCTIONALITY	New	120.00	100.00
2	TO REMOVE FRONT DAMAGED PARTS ,TO JACK OUT FRONT SUPPORT PANEL ,FRONT BODY ,AND CUT OUT DAMAGED PARTS ,TO STRAIGHTEN OUT FRONT CHASSIS TO REWELD RESHAPE AND REPAIR BONNET HINGE PANEL ,FRONT FENDER AND INNER PANEL, HEAD LAMP INNER PANEL ,FRONT SUPPORT PANEL ,FRONT CHASSIS MEMBER AND ADJUST BODY PANEL ALIGNMENT	New	750.00	700.00
3	TO SPRAY PAINT AFFECTED FRONT AND INNER DAMAGED PORTION INCLUSIVE OF PREPARATORY WORKS AND MATERIAL	New	900.00	800.00
4	TO APPLY ANTI-CORROSION TUFF-KOTE	New	100.00	90.00
5	TO DISCONNECT WIRE HARNESS TO FACILITATE REPAIRS AND CHECK FOR DAMAGE AND RECONNECT WIRING SYSTEM AND CHECK FOR FULL FUNCTIONALITY TO FOCUS HEADLAMP	New	25.00	20.00
6	TO PERFORM COMPUTER DIAGNOSTIC ON DRIVETRAIN ABS SYSTEMS PARKING SYSTEM AND CLEAR FAULT CODES	New	120.00	0.00
7	TOWING CHARGES	New	60.00	50.00
8	LABOUR CHARGE FOR STRAIGHTEN OUT FRONT RIGHT CHASSIS MEMBER	New	280.00	250.00
Gross Labour Cost (\$\$)			2,355.00	2,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >