

Not Authorized
Renuy Bepaint
7 days



Thirumaran S/O M Manickam
BLK 880 #07-265 Yishun Street 81
S760880

File No : SH/2021/028/04/001/TP
Date : 06-April-2021

810,179.94

Estimated cost of repair for vehicle no : SFQ8101D Toyota Corolla Altis
Accident involving vehicle no: SFQ8101D & SKR7929A on 03.04.2021

Description	Quantity	Cost Price
Bonnet	1	\$ B ₁ 867.60 ✓
Bonnet lock	1	\$ D ₁₁ 148.90 ✓
RH Bonnet hinge	1	\$ B ₁ 78.50 ✓
LH Bonnet hinge	1	\$ D ₁₁ 78.50 ✓
RH head lamp	1	\$ mjc _{cm} 1,590.80 ✓
LH head lamp	1	\$ mjc _{car} 1,590.80 ✓
Front grille	1	\$ CM 276.85 ✓
Front grille clips (1 set)	1	\$ m _u 35.00 ✓
RH front fender	1	\$ B ₁ 390.95 ✓
RH front fender badge "Dual Vvti"	1	\$ m _{cc} 80.10 ✓
Front bumper	1	\$ B ₁ 489.60 ✓
Front bumper centre grille	1	\$ CM 120.20 ✓
Front bumper sponge	1	\$ CM 110.40 ✓
Front bumper reinforcement	1	\$ B ₁ 276.80 ✓
RH Front bumper retainer	1	\$ D ₁₁ 50.40 ✓
LH Front bumper retainer	1	\$ D ₁₁ 50.40 ✓
RH Front bumper bracket	1	\$ R 127.60 X
LH Front bumper bracket	1	\$ R 127.60 X
Front bumper lower dust cover	1	\$ J _u 157.20 X
Front bumper lower dust cover clips (1 set)	1	\$ m _u 55.20 X
Front support panel	1	\$ B ₁ 570.40 ✓
Front support panel top garnish	1	\$ D ₁₁ 130.80 ✓
Front support panel top garnish clips (1 set)	1	\$ m _u 35.00 ✓
Bonnet lock centre bracket	1	\$ B ₁ 80.90 ✓
Air con condensor	1	\$ B ₁ 876.75 ✓
Air con condensor pipe inlet 439.10	1	\$ m _u 487.60 ✓
Air con condensor pipe outlet 402.80	1	\$ m _u 476.80 ✓
Radiator	1	\$ m _u 980.50 ✓
Radiator auto fan cowl	1	\$ CM (P _u) 170.80 ✓
Radiator auto fan motor	1	\$ m _u 298.60 ✓
Radiator auto fan blade	1	\$ CM 150.70 ✓
	25%	\$ 10,962.25
	Less 20%	\$ 2,192.45
		\$ 8,769.80
Front number plate	1	S. Nett \$ B ₁ 45.00 ✓
Engine coolant	1	S. Nett \$ m _{cc} 30.00 ✓

To remove and check air con condenser, dryer, aluminium pipes, valves and reinstall components and vacuum and charge refrigerant R134a and check for leakage and full functionality

\$ 120.00 100L
\$ 8,964.80

\$ 8,964.80

To remove front damaged parts, to jack out front support panel, front body, and cut out damaged parts, to straighten out front chassis, to reweld, reshape and repair bonnet hinge panel, front fender and inner panel, head lamp inner panel, front support panel, front chassis member and adjust body panel alignment

\$ 750.00 700/

To spray paint affected front and inner damaged portion inclusive of preparatory works and material

\$ 900.00 800/

To apply anti-corrosion Tuff-Kote

\$ 100.00 90/

To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus headlamp

\$ 25.00 20/

To perform computer diagnostic on drivetrain, ABS systems, parking system, and clear fault codes

\$ 120.00 X

Towing charges

\$ 60.00 50/

\$ 10,919.80

T/Party: AIG Asia Pacific Insurance Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Thirumaran S/O M Manickam
BLk 880 #07-265 Yishun Street 81
S760880

File No : SH/2021/028/04/001/TP
Date : 07-April-2021

Supplementary estimated cost of repair for vehicle no: SFQ8101D Toyota Corolla Altis
Accident involving vehicle no: SFQ8101D & SKR7929A on 03.04.2021

Description	Quantity	Cost Price
Radiator top cover bracket		\$ <i>DIY</i> 95.00 ✓
Front spare tank <i>155-70</i>		\$ <i>nd</i> 190.10 ✓
Front wiper tank <i>170.40</i>		\$ <i>nd</i> 219.10 ✓
	<i>25%</i>	\$ 504.20
	Less <i>20%</i>	\$ 100.84
		\$ 403.36
Labour charge for straighten out front right chassis member		\$ 280.00 <i>250/</i>
		\$ 683.36

T/Party: AIG Asia Pacific Insurance Pte Ltd