

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21004303/KPA3Q2**Date:** 05/07/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100509560
Claimant Vehicle No :	SKW6586K	Insured Vehicle No :	SLN8341Y
Date of Loss:	03/04/2021	Nature of Claim:	TP
		Claim No:	3631223259SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW6586K	Engine No:	G4NAFU075631
Make & Model:	HYUNDAI TUCSON, 2.0 GLS (A)	Chassis No:	KMHJ3813MGU071470
Reg. Date:	11/11/2015 (Man. Year: 2015)	Odometer:	51913 km
Colour:	Metallic Grey		
Engine Capacity:	1999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Pirelli 9 mm	Rear Left Side:	Pirelli 9 mm
Front Right Side:	Pirelli 9 mm	Rear Right Side:	Pirelli 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,113.56	13,012.45	2,101.11	13.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,470.00	3,070.00	400.00	11.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	18,583.56	16,082.45	2,501.11	13.46
Approved Total (Overridden) (\$\$)		12,850.00		
(\$\$)	18,583.56	12,850.00	5,733.56	30.85
+ GST 7.00/7.00% (\$\$)	1,300.85	899.50	401.35	30.85
Nett Amount (\$\$)	19,884.41	13,749.50	6,134.91	30.85
+ Car Rental (12.0 x S\$120.00/day) (\$\$)		1,440.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		15,191.50		
Global Sum Settlement (\$\$)		15,100.00		

INSPECTION

Date of Assignment:	05/04/2021	
Date Inspected:	05/04/2021	Inspected At: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	12.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER UPPER	Cracked	494.70 FL	*494.70 FL
2	1		*FRONT BUMPER LOWER	Serviceable	381.40 FL	*- FL
3	1		*FRONT BUMPER REINFORCEMENT	Repair	603.60 FL	*- FL
4	1		*FRONT BUMPER SPONGE	Cracked	94.00 FL	*94.00 FL
5	1		*FRONT BUMPER RH SIDE RETAINER	Distorted	9.90 FL	*9.90 FL
6	6		*FRONT BUMPER CLIPS	Necessary	21.00 FL	*21.00 FL
7	1		*FRONT GRILLE	Cracked	953.70 FL	*953.70 FL
8	6		*FRONT GRILLE CLIPS	Necessary	21.00 FL	*21.00 FL
9	2		*HORNS	Dented	191.80 FL	*191.80 FL
10	1		*BONNET	Bent	1,617.80 FL	*1,617.80 FL
11	1		*BONNET INNER LOCK	Repair	142.40 FL	*- FL
12	1		*BONNET INNER SPONGE	Deformed	220.50 FL	*220.50 FL
13	1		*BONNET INNER RUBBER	Cut	56.20 FL	*56.20 FL
14	2		*HEADLAMPS	O/S Mtg Cracked / N/S Cracked	5,355.80 FL	*5,355.80 FL
15	2		*HEADLAMP LOWER BRACKETS	Cracked	48.00 FL	*48.00 FL
16	1		*AIR-CON CONDENSER	Punctured	663.00 FL	*663.00 FL
17	1		*RADIATOR	Serviceable	799.00 FL	*- FL
18	1		*FRT SUPPORT PANEL	Buckled	882.20 FL	*882.20 FL
19	1		*FRONT SUPPORT PANEL TOP GARNISH	Cracked	52.80 FL	*52.80 FL
20	6		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Necessary	21.00 FL	*21.00 FL
21	1		*REAR BUMPER UPPER	Bent	446.50 FL	*446.50 FL
22	1		*REAR BUMPER LOWER	Bent	351.40 FL	*351.40 FL
23	1		*REAR BUMPER REINFORCEMENT	Bent	270.80 FL	*270.80 FL
24	1		*REAR BUMPER TOW COVER	Serviceable	5.70 FL	*- FL
25	2		*REAR BUMPER REFLECTORS	Serviceable	205.80 FL	*- FL
26	6		*REAR BUMPER CLIPS	Necessary	21.00 FL	*21.00 FL
27	2		*REAR REVERSE SENSORS (CENTRE)	Shorted	280.40 FL	*280.40 FL
28	1		*REAR TAILGATE	Bent	1,758.90 FL	*1,758.90 FL
29	1		*TAILGATE LOGO	Necessary	30.70 FL	*30.70 FL
30	1		*TAILGATE LOWER OUTER GARNISH	Cracked	202.00 FL	*202.00 FL
31	1		*TAILGATE EMBLEM (TUCSON)	Necessary	29.10 FL	*29.10 FL
32	1		*TAILGATE INNER LOCK	Dented	677.00 FL	*677.00 FL
33	1		*TAILGATE INNER RUBBER (50%)	Distorted / Dented	101.52 FS	*63.45 FS
34	1		*TAILGATE AUTO LOCK SENSOR	Dented	80.20 FL	*80.20 FL
35	1		*REAR END PANEL	Bent	739.10 FL	*739.10 FL
36	1		*REAR WINDSCREEN GLASS MOULDING	Not Necessary	440.90 FL	*- FL
37	1		*REAR WINDSCREEN GLASS GUM	Necessary	40.00 FS	*40.00 FS
38	1		*REAR NUMBER PLATE	Bent	35.00 FS	*35.00 FS
39	1		*FRONT SUPPORT PANEL INNER TOP GARNISH	Dented	30.00 FL	*30.00 FL
40	2		*FRONT FENDER INNER TOP GARNISHS	Distorted	85.00 FL	*85.00 FL
41	1		*RADIATOR LH SIDE GARNISH	Cracked	19.00 FL	*19.00 FL
42	1		*REVERSE SENSOR WIRE HARNESS	Cut	298.00 FL	*298.00 FL
43	1		*SMART KEY SENSOR	Dented	70.00 FL	*70.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	18,847.82	16,230.95
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,734.26	3,218.50
Total Parts (\$\$)	15,113.56	13,012.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	50.00	50.00
2	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	100.00	100.00
3	REMOVE & REFIX REAR BUMPER ASSY ,TAILLAMPS ,TAILGATE & ATTACHMENT ,REFLECTOR ,REAR WIPER ASSY ,SPOILER & THIRD BRAKE LIGHT ,TO CUT ,WELD & RENEW REAR PANEL ,KNOCK & REPAIR REAR FENDERS & COMPARTMENT AND REALIGN THE SAME	New	800.00	700.00
4	PUTTY & RESPRAY ON TAILGATE ,REAR PANEL,GARNISH ,REAR COMPARTMENT ,REAR FENDERS	New	900.00	800.00
5	REMOVE AND REFIX AIRCON ,CHECK ,VACUUM & REFILL GAS	New	100.00	100.00
6	REMOVE & REFIX FRT BUMPER ASSY ,GRILLE ,HEADLAMPS BONNET & ATTACHMENT,RADIATOR & MOTOR ,TO KNOCK & REPAIR FRT BOTH FENDERS & REALIGN THE SAME	New	700.00	600.00
7	PUTTY & RESPRAY ON FRT BUMPER ,BONNET ,FRT	New	700.00	600.00
8	REMOVE & REFIX REVERSE CAMERA ,REVERSE SENSOR ,AUTO LOCK SENSOR & RESET SYSTEM	New	60.00	60.00
9	RUSTPROOFING	New	60.00	60.00
Gross Labour Cost (\$)			3,470.00	3,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >